

V- 2009-00981-9

BOX # 1

Binder #22	Fraser River Structures Design Review Correspondence 1994
Binder #22	Fraser River Structures Design Review Correspondence 1995
Binder #22	Fraser River Structures Design Review Correspondence 1996
Binder #22	Fraser River Structures Design Review Drawings

BOX # 2

Fraser River Structures Design Review
GW Marine Corporation - Breakwater Extensions
Design Basis - Project Memorandum
January 1994 - Westmar Consultants Inc.

Fraser River Structures Design Review
Phase I Trifurcation Wall Repairs
Post Completion Report
PWGSC
May 1994

BOX # 2 Continued

Fraser River Structures Design Review
Phase II Trifurcation Wall Repairs
Post Completion Report
PWGSC
May 5, 1994

Fraser River Structures Design Review
Middle Eddy Bank Protection
Post Completion Report
PWGSC
May 1994

Fraser River Structures Design Review
North Arm Jetty Repairs
Post Completion Report
PWGSC
September 1994

Fraser River Structures Design Review
Fraser River Training Wall Structures
Site Notes
Westmar Consultants Inc.
September 19, 1994

Fraser River Structures Design Review
Annacis V-Dyke Repair
Project Brief
January 1995

Fraser River Structures Design Review
Harrison River
Miscellaneous Structures Maintenance
Post Completion Report
PWGSC
February 1995

Fraser River Structures Design Review
Phase III Trifurcation Wall Design Review
Interim Report No. 1
PWGSC
February 23, 1995

BOX # 2 Continued

Fraser River Structures Design Review
Deas & Kirkland Island Bank Protection
Class C Design Review
Interim Report No. 1
PWGSC
March 31, 1995

Fraser River Structures Design Review
Woodward Training Wall
Class B Design Review
Interim Report No. 1
PWGSC
March 31, 1995

Fraser River Structures Design Review
North Arm Jetty Design Review
Interim Report No. 1
PWGSC
March 31, 1995

Fraser River Structures Design Review
Rock Training Structures
Class "C" Design Review
Sapperton V-Dyke
Interim Report No. 1
PWGSC
April 1995

Fraser River Structures Design Review
Annacis V-Dyke Repairs
Post Completion Report
PWGSC
August 1995

Fraser River Structures Design Review
Steveston Bend Training Structures
Hydraulic Studies
Steady-State Steveston Flows
Northwest Hydraulic Consultants Ltd.
August 1995

BOX # 2 Continued

Fraser River Structures Design Review
Steveston North Jetty Design Review
PWGSC
October 1995

Fraser River Structures Design Review
Steveston South Jetty # 2
PWGSC
October 1995

Fraser River Structures Design Review
Timber Training Structures Sapperton Wingdams
PWGSC
March 7, 1996

Fraser River Structures Design Review
South Arm
Timber Training Structures Repairs
Post Completion Report
PWGSC
April 23, 1996

Fraser River Structures Design Review
Trifurcation Phase I & II Wall
Structure Inspection Report - Level II - Detailed Inspection
PWGSC
October 1996