

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	C 549-1	Admin-Trees-Shelterbelt; Admin-Towns and Cities - Morden; Community Water Development - St.Malo Dam; Water Supply - Dams	Shelterbelts five miles south of Morden.	Morden, MB	R.L. Paice	Colour - Photographic negatives	2.25 x 2.25	1971-09-07
RG17	R194	2019-00196-6	1	C 549-2	Admin-Trees-Shelterbelt; Admin-Towns and Cities - Morden; Community Water Development - St.Malo Dam; Water Supply - Dams	Shelterbelts five miles south of Morden.	Morden, MB	R.L. Paice	Colour - Photographic negatives	2.25 x 2.25	1971-09-07
RG17	R194	2019-00196-6	1	C 549-3	Admin-Trees-Shelterbelt; Admin-Towns and Cities - Morden; Community Water Development - St.Malo Dam; Water Supply - Dams	New federal building at Morden.	Morden, MB	R.L. Paice	Colour - Photographic negatives	2.25 x 2.25	1971-09-07
RG17	R194	2019-00196-6	1	C 549-4	Admin-Trees-Shelterbelt; Admin-Towns and Cities - Morden; Community Water Development - St.Malo Dam; Water Supply - Dams	New federal building at Morden.	Morden, MB	R.L. Paice	Colour - Photographic negatives	2.25 x 2.25	1971-09-07
RG17	R194	2019-00196-6	1	C 549-5	Admin-Trees-Shelterbelt; Admin-Towns and Cities - Morden; Community Water Development - St.Malo Dam; Water Supply - Dams	Boat launching.	Morden, MB	R.L. Paice	Colour - Photographic negatives	2.25 x 2.25	1971-09-08
RG17	R194	2019-00196-6	1	C 549-6	Admin-Trees-Shelterbelt; Admin-Towns and Cities - Morden; Community Water Development - St.Malo Dam; Water Supply - Dams	Beach area.	Morden, MB	R.L. Paice	Colour - Photographic negatives	2.25 x 2.25	1971-09-08
RG17	R194	2019-00196-6	1	C 549-7	Admin-Trees-Shelterbelt; Admin-Towns and Cities - Morden; Community Water Development - St.Malo Dam; Water Supply - Dams	Beach area.	Morden, MB	R.L. Paice	Colour - Photographic negatives	2.25 x 2.25	1971-09-08
RG17	R194	2019-00196-6	1	C 549-8	Admin-Trees-Shelterbelt; Admin-Towns and Cities - Morden; Community Water Development - St.Malo Dam; Water Supply - Dams	Individual farm dam five miles west of Alexander, Manitoba.	Morden, MB	R.L. Paice	Colour - Photographic negatives	2.25 x 2.25	1971-09-10
RG17	R194	2019-00196-6	1	623	Community Water Development (CWD)-Minnedosa Dam Project	Remains of the Minnedosa Power Dam. One mile from confluence with Assiniboine River, Manitoba	Minnedosa Dam, Assiniboine River, MB		Black-and-White - Photographic negatives	2.25 x 3.25	1949-05-12
RG17	R194	2019-00196-6	1	645 "F"	Admin-Soil Conservation-Erosion	Series of shots of sheet erosion on coral silt loam near Alexandra, Manitoba. These shots were taken after a cloudburst.	Alexander, MB		Black-and-White - Photographic negatives	2.25 x 3.25	1940-06-09
RG17	R194	2019-00196-6	1	654	Assiniboine River Project	Cross bracing in culvert prior to attempting installation at end of dam. Assiniboine River, Brandon, Manitoba	Brandon, MB		Black-and-White - Photographic negatives	2.25 x 3.25	1949-06-29
RG17	R194	2019-00196-6	1	2225	Soil Conservation-Erosion	Erosion of roadside ditch at Blackburns. Dauphin, Manitoba	Dauphin, MB		Black-and-White - Photographic negatives	2.25 x 3.25	1951-11-10
RG17	R194	2019-00196-6	1	2509	Crop Production-Grain-Wheat-Harvesting	Threshing operations near McCreary, Manitoba	McCreary, MB		Black-and-White - Photographic negatives	4 x 5	1952-08-01
RG17	R194	2019-00196-6	1	2700	Soil Conservation-Erosion	Gully problems near Bruxelles, Manitoba	Bruxelles, MB		Black-and-White - Photographic negatives	2.25 x 3.25	1952-08-21
RG17	R194	2019-00196-6	1	2702	Soil Conservation-Erosion	Gully problems near Bruxelles, Manitoba	Bruxelles, MB		Black-and-White - Photographic negatives		1952-08-21
RG17	R194	2019-00196-6	1	2807	Community Water Development (CWD)-Morden Dam	Spillway enlargement on Morden Dam	Morden Dam spillway		Black-and-White - Photographic negatives	2.25 x 2.25	Fall 1952

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	3257	Soil Conservation-Erosion-Water	Drop section from concrete culvert through highway north of Alexander. It was washed out due to heavy rains.	Alexander, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1953-06-16
RG17	R194	2019-00196-6	1	3259	Soil Conservation-Erosion-Water	Soil erosion in an area north of Alexander due to heavy rains.	Alexander, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1953-06-16
RG17	R194	2019-00196-6	1	3536	Public Relations Ceremonies-Morden Dam	Showing part of the crowd at the official opening of the Morden Dam.	Morden Dam, MB		Black-and-White - Photographic negatives	4 x 5	1954-08-02
RG17	R194	2019-00196-6	1	3540	Community Water Development-Morden Dam	Morden Dam showing the rip-rap on the upstream fare of the dam and part of the reservoir. Taken day of official opening.	Morden Dam, MB		Black-and-White - Photographic negatives	4 x 5	1954-08-02
RG17	R194	2019-00196-6	1	3544	Public Relations Ceremonies-Morden Dam	Head table at the luncheon held in conjunction with the opening to the Morden Dam.	Morden Dam, MB		Black-and-White - Photographic negatives	4 x 5	1954-08-02
RG17	R194	2019-00196-6	1	3546	Public Relations Ceremonies-Morden Dam	View of the crowd from the rear of the speakers platform at the official opening of the Morden Dam.	Morden Dam, MB		Black-and-White - Photographic negatives	4 x 5	1954-08-02
RG17	R194	2019-00196-6	1	3548	Public Relations-Ceremonies-Morden Dam	J.G. Gardiner delivering speech at theceremonies in conjunction with the opening of the Morden Dam.	Morden Dam, MB		Black-and-White - Photographic negatives	4 x 5	1954-08-02
RG17	R194	2019-00196-6	1	3552	Public Relations-Ceremonies-Morden Dam	Official party making a tour of the new canning plant at Morden.	Morden Dam, MB		Black-and-White - Photographic negatives	4 x 5	1954-08-02
RG17	R194	2019-00196-6	1	3555	Public Relations-Ceremonies-Morden Dam	The reservoir behind the Morden Dam ensures the people with adequate facilities for water sports. Shown here is a view of the beach.	Morden Dam, MB		Black-and-White - Photographic negatives	4 x 5	1954-08-02
RG17	R194	2019-00196-6	1	3643	Community Water Development-Minnedosa Dam Project	Spillway - Minnedosa Dam.	Minnedosa Dam, MB		Black-and-White - Photographic negatives	4 x 5	1954-11-10
RG17	R194	2019-00196-6	1	3657	Community Water Development-Boissevain Project	Pumphouse being constructed for town water supply for Boissevain West Dam can be seen in the background.	Boissevain, MB		Black-and-White - Photographic negatives	4 x 5	1954-11-12
RG17	R194	2019-00196-6	1	4405	Community Water Development-Melita Dam	On souris River near Melita, Manitoba	Melita, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1939-04-12
RG17	R194	2019-00196-6	1	6203	Community Water Development-Melita Dam	Construction of Melita Dam	Melita, MB		Black-and-White - Photographic negatives	2.5 x 4.5	1939-04-01
RG17	R194	2019-00196-6	1	6204	Community Water Development-Melita Dam	Construction of Melita Dam	Melita, MB		Black-and-White - Photographic negatives	2.5 x 4.5	1939-04-01
RG17	R194	2019-00196-6	1	6205	Community Water Development-Melita Dam	Construction of Melita Dam	Melita, MB		Black-and-White - Photographic negatives	2.5 x 4.5	1939-04-01

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	6206	Community Water Development-Melita Dam	Construction of Melita Dam	Melita, MB		Black-and-White - Photographic negatives	2.5 x 4.5	1939-04-01
RG17	R194	2019-00196-6	1	6214-1	Water Supply - Dams; Community Water Development-Melita Dam	Irrigation dam	Melita, MB		Black-and-White - Photographic negatives	2.5 X 4.25	1905-04-22
RG17	R194	2019-00196-6	1	6214-2	Water Supply - Dams; Community Water Development-Melita Dam	Stockwater dam	Melita, MB		Black-and-White - Photographic negatives	2.25 x 3.25	1905-04-22
RG17	R194	2019-00196-6	1	6214-3	Water Supply - Dams; Community Water Development-Melita Dam	Melita Dam construction.	Melita, MB		Black-and-White - Photographic negatives	2.5 x 4.25	1905-04-22
RG17	R194	2019-00196-6	1	6214-4	Water Supply - Dams; Community Water Development-Melita Dam	Melita Dam construction.	Melita, MB		Black-and-White - Photographic negatives	2.5 X 4.25	1905-04-22
RG17	R194	2019-00196-6	1	6215-1	Community Water Development-Melita Dam	Construction of Melita Dam.	Melita, MB		Black-and-White - Photographic negatives	2.5 x 4.25	1905-04-22
RG17	R194	2019-00196-6	1	6215-2	Community Water Development-Melita Dam	Construction of Melita Dam.	Melita, MB		Black-and-White - Photographic negatives	2.5 x 4.25	1905-04-22
RG17	R194	2019-00196-6	1	6215-3	Community Water Development-Melita Dam	Construction of Melita Dam.	Melita, MB		Black-and-White - Photographic negatives	2.5 x 4.25	1905-04-22
RG17	R194	2019-00196-6	1	6215-4	Community Water Development-Melita Dam	Construction of Melita Dam.	Melita, MB		Black-and-White - Photographic negatives	2.5 x 4.25	1905-04-22
RG17	R194	2019-00196-6	1	6216-1	Community Water Development-Melita Dam	Construction of Melita Dam	Melita, MB		Black-and-White - Photographic negatives	2.5 x 4.25	1905-04-22
RG17	R194	2019-00196-6	1	6216-2	Community Water Development-Melita Dam	Construction of Melita Dam	Melita, MB		Black-and-White - Photographic negatives	2.5 x 4.25	1905-04-22
RG17	R194	2019-00196-6	1	6216-3	Community Water Development-Melita Dam	Construction of Melita Dam	Melita, MB		Black-and-White - Photographic negatives	2.5 x 4.25	1905-04-22
RG17	R194	2019-00196-6	1	6216-4	Community Water Development-Melita Dam	Construction of Melita Dam	Melita, MB		Black-and-White - Photographic negatives	2.5 x 4.25	1905-04-22
RG17	R194	2019-00196-6	1	6218	Community Water Development-Melita Dam	Construction of Melita Dam	Melita, MB		Black-and-White - Photographic negatives	2.5 x 4.25	1905-04-22
RG17	R194	2019-00196-6	1	7324	Community Water Development-Morden Dam	Morden Dam - In the spring of 1945, the floor of the spillway heaved due to unstable foundation material. Heavy runoff during that year undermined the structure causing a portion of the spillway to be washed away.	Morden, MB		Black-and-White - Photographic negatives	4 x 5	1905-04-28

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	7326	Community Water Development-Morden Dam	Morden Dam-Construction work on the new spillway to the Morden Dam being carried out during the spring of 1953	Morden, MB		Black-and-White - Photographic negatives	4 x 5	1905-05-06
RG17	R194	2019-00196-6	1	10223	Assiniboine River Reclamation Project-Dyking	Hutterite girls carry sandbags to broken dyke near their farm.	Popular Point, MB		Black-and-White - Photographic negatives	4 x 5	1958-05-07
RG17	R194	2019-00196-6	1	10226	Assiniboine River Reclamation Project-Dyking	At the far end of dyke, the river is dangerously close to the top of sandbags near Hutterite farm.	Popular Point, MB		Black-and-White - Photographic negatives	4 x 5	1958-05-07
RG17	R194	2019-00196-6	1	10239	Community Water Development Project-Coulter Dam	Coulter Dam	Coulter Dam, MB		Black-and-White - Photographic negatives	4 x 5	1956-05-08
RG17	R194	2019-00196-6	1	12138	Community Water Development Project-Boissevain Dams	Filtration Plant near West Dam	Boissevain, MB	Bob Trawin	Black-and-White - Photographic negatives	4 x 5	1956-09-12
RG17	R194	2019-00196-6	1	12722	Community Water Development Project-Boissevain Dams	Aerial view of West and Boissevain Reservoir showing West Dam (LR). Roadway crossing reservoir and natural FSL control, summer 1956.	Boissevain, MB		Black-and-White - Photographic negatives	4 x 5	1956-08-16
RG17	R194	2019-00196-6	1	12723	Community Water Development Project-Boissevain Dam	Aerial view West Boissevain Dam and reservoir showing pumping and treatment plant.	Boissevain, MB		Black-and-White - Photographic negatives	4 x 5	1956-08-16
RG17	R194	2019-00196-6	1	12734	Community Water Development project-Morden Dam	Aerial view of Morden Dam showing part of reservoir and beach spillway entrance at upper left.	Morden Dam, MB		Black-and-White - Photographic negatives	4 x 5	1956-08-16
RG17	R194	2019-00196-6	1	13610	Westbourne Community Pasture	PFRA-Westbourne Community Pasture sign.	Westbourne Pasture, MB		Black-and-White - Photographic negatives	4 x 5	1957-07-04
RG17	R194	2019-00196-6	1	14522	Community Water Development Project-Boissevain Dam	Aerial view north-east of Boissevain, Manitoba. Town sewage lagoon in foreground.	Boissevain, MB	R.Y. Nakamura	Black-and-White - Photographic negatives	4 x 5	1957-10-01
RG17	R194	2019-00196-6	1	14776	Community Water Development project-Morden Dam	Morden Dam spillway. Upheaval of slab #4. Picture used in the Morden Dam Spillway Repairs Report.	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 3.25	1957-06-25
RG17	R194	2019-00196-6	1	14779	Community Water Development project-Morden Dam	Upstream edge of slab #4. Picture used in the Morden Dam Spillway Repairs Report.	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 3.25	1957-06-25
RG17	R194	2019-00196-6	1	14794	Community Water Development Project-Morden Dam	Morden Dam spillway. Chuting concrete from mixer to buggy. Picture used in the Morden Dam Spillway Repairs Report.	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 3.25	1958-10-18
RG17	R194	2019-00196-6	1	14870	Community Water Development project-Morden Dam	Upstream edge of slab #4. this aperture was filled with damp subbase gravel and shale particles and a hand could pass downward some six to eight inches.	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 3.25	1958-02-03
RG17	R194	2019-00196-6	1	14871	Community Water Development project-Morden Dam	Cracking at vertical construction joint between curved inlet wass and chute wall on right side of spillway.	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1958-02-03

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	15030	Community Water Development-Morden Dam	Repair of Morden Spillway.	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1957-06-01
RG17	R194	2019-00196-6	1	15398	Community Water Development Project-Carman Dam	Town of Carman, approximately one block west of concrete highway bridge.	Carman, MB		Black-and-White - Photographic negatives	2.25 x 3.25	1958-04-01
RG17	R194	2019-00196-6	1	15746	Admin-Soil Conservation-Erosion-Wind	Drifting soil filling in drainage ditch about twenty miles east of Portage La Prairie, MB, on the #1 Highway.	near Portage La Prairie, MB	R.L. Paice	Black-and-White - Photographic negatives	4 x 5	1958-05-09
RG17	R194	2019-00196-6	1	20246	Community Water Development Project-Boissevain Dam	PFRA sign at Boissevain Storage Project.	Boissevain, MB	R.L. Paice	Black-and-White - Photographic negatives	4 x 5	1960-07-01
RG17	R194	2019-00196-6	1	20349	Dauphin-Ethelbert Community Pasture	Post hole digging along S/W corner of Dauphin Ethelbert pasture.	Dauphin, MB	R.L. Paice	Black-and-White - Photographic negatives	4 x 5	1960-07-05
RG17	R194	2019-00196-6	1	20363	Dauphin-Ethelbert Community Pasture	Outside clay bake oven on Medwedchuck farm beside pasture.	Dauphin, MB	R.L. Paice	Black-and-White - Photographic negatives	4 x 5	1960-07-05
RG17	R194	2019-00196-6	1	21353	Community Water Development Project-Boissevain Dam	Aerial view of fresh topsoil spread on repaired emergency spillway at the Boissevain East Dam. The proposed drop inlet spillway would be located through this abutment of the dam.	Boissevain, MB	R.L. Paice	Black-and-White - Photographic negatives	4 x 5	1960-10-14
RG17	R194	2019-00196-6	1	21436	Towns and Cities - Plum Coulee	Aerial view of the village of Plum Coulee, MB, looking due west with Highway 14 crossing the centre of the photograph.	Plum Coulee, MB	R.L. Paice	Black-and-White - Photographic negatives	4 x 5	1960-10-14
RG17	R194	2019-00196-6	1	22271	Public Relations-Rivers Dam, Official Opening	Members of the Rivers arrangements committee checking sign erected near the newly completed Rivers Dam officially opened July 15, 1961. In the photo from left to right are: Mr. Charlie Stalker, Chairman of Wahtopanah Agricultural Association; Mr. H. Casselman, Committee Member; Mr. F.D. Taylor, Mayor of the Town of Rivers, MB.	Rivers Dam, MB		Black-and-White - Photographic negatives	4 x 5	1961-07-15
RG17	R194	2019-00196-6	1	22274	Public Relations-Rivers Dam, Official Opening	The Honourable Mr. Douglas Harkness in informal discussion with Captain Al Hill, Guard Commander, and Group Capt. RO Shaw, Commandant of the Canadian Joint Air Training Centre, Rivers Camp, Rivers, MB.	Rivers Dam, MB		Black-and-White - Photographic negatives	4 x 5	1961-07-15

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	22275	Public Relations-Rivers Dam, Official Opening	The Honourable Mr. Douglas Harkness, Minister of National Defence, met at the airport of the Canadian Joint Air Training Centre, Rivers Camp, Manitoba, by Mr. J.N. Mandziuk, MP for Marquette (on plane); acting Deputy Commandant Major DL Fromow; Group Captain RO Shaw, Commandant of the CJATC.	Rivers Dam, MB		Black-and-White - Photographic negatives	4 x 5	1961-07-15
RG17	R194	2019-00196-6	1	22280	Public Relations-Rivers Dam, Official Opening	The Honourable Mr. Douglas Harkness delivering his principal address during official opening of the Rivers Dam on the Minnedosa River near the town of Rivers in Manitoba, at which an estimated 3000 persons attended.	Rivers Dam, MB		Black-and-White - Photographic negatives	4 x 5	1961-07-15
RG17	R194	2019-00196-6	1	22285	Public Relations-Rivers Dam, Official Opening	Fly past of jet aircraft from the RCAF Station at Gimli, Manitoba during official opening ceremony at Rivers Dam, Rivers, Manitoba.	Rivers Dam, MB		Black-and-White - Photographic negatives	4 x 5	1961-07-15
RG17	R194	2019-00196-6	1	22286	Public Relations-Rivers Dam, Official Opening	Honourable Mr. Douglas Harkness delivering his principal address during official opening ceremony at the Rivers Dam, Rivers, MB.	Rivers Dam, MB		Black-and-White - Photographic negatives	4 x 5	1961-07-15
RG17	R194	2019-00196-6	1	22291	Public Relations-Rivers Dam, Official Opening	Aerial photograph of Rivers Dam and reservoir on the occasion of its official opening, July 15, 1961, with car park in foreground.	Rivers Dam, MB	R.Y. Nakamura	Black-and-White - Photographic negatives	4 x 5	1961-07-15
RG17	R194	2019-00196-6	1	24076	Dams	Foulliard Bros. irrigation and stock dam. NE 28-16-26 W1. Riparian outlet - showing riprap.	St. Lazarre, MB	R.L. Paice	Black-and-White - Photographic negatives	4 x 5	1963-09-04
RG17	R194	2019-00196-6	1	24077	Dams	O/S of Foulliard Farm and dam, from Fort Alice. Note: Hay field that can be irrigated.	St. Lazarre, MB	R.L. Paice	Black-and-White - Photographic negatives	4 x 5	1963-09-04
RG17	R194	2019-00196-6	1	24086	Crop Production-Special Crops	Elmer Del Monte canning factory.	Morden, MB	R.L. Paice	Black-and-White - Photographic negatives	4 x 5	1963-09-10
RG17	R194	2019-00196-6	1	24087	Crop Production-Special Crops	Unloading corn at Elmer Del Monte canning factory.	Morden, MB	R.L. Paice	Black-and-White - Photographic negatives	4 x 5	1963-09-10
RG17	R194	2019-00196-6	1	25658	Assiniboine River Project-Shellmouth Damsite	River crossing built between May 15 and May 22 was breached by the contractor on May 27 to save the four 48 inch centreline C.M.P. when the river rose rapidly following heavy rains May 23, 24 and 25.	Shellmouth Damsite, MB	R.Y. Nakamura	Black-and-White - Photographic negatives	4 x 5	1965-05-28
RG17	R194	2019-00196-6	1	25767	Assiniboine River Project - Shellmouth	Hauling from south east bank of Assiniboine River Valley at Shellmouth Dam.	Shellmouth Damsite, MB	R.L. Paice	Black-and-White - Photographic negatives	4 x 5	1965-06-01

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	25815	Public Relations - Irrigation pipes to Ottawa	Trucks and trailers ready to move irrigation pipes to Ottawa.	Brandon, MB	R.Y. Nakamura	Black-and-White - Photographic negatives	4 x 5	1965-07-06
RG17	R194	2019-00196-6	1	28123	Shellmouth Damsite	Sign at observation point - E. embankment.	Manitoba	R.L. Paice	Black-and-White - Photographic negatives	4 x 5	1967-11-08
RG17	R194	2019-00196-6	1	29191-1	Admin-Flooding-Manitoba	Killarney Dam	Manitoba	W. Lengerke	Black-and-White - Photographic negatives	4 x 5	1965-04-15
RG17	R194	2019-00196-6	1	29191-2	Admin-Flooding-Manitoba	Killarney Dam	Manitoba	W. Lengerke	Black-and-White - Photographic negatives	4 x 5	1965-04-15
RG17	R194	2019-00196-6	1	29191-3	Admin-Flooding-Manitoba	Oak River Indian Reserve farmland	Manitoba	W. Lengerke	Black-and-White - Photographic negatives	4 x 5	1965-04-15
RG17	R194	2019-00196-6	1	29191-4	Admin-Flooding-Manitoba	Oak River D.O and Dam	Manitoba	W. Lengerke	Black-and-White - Photographic negatives	4 x 5	1965-04-15
RG17	R194	2019-00196-6	1	29191-5	Admin-Flooding-Manitoba	Assiniboine Valley two miles north of Oak Lake, MB	Manitoba	W. Lengerke	Black-and-White - Photographic negatives	4 x 5	1965-04-15
RG17	R194	2019-00196-6	1	29191-6	Admin-Flooding-Manitoba	Farmstead north of Melita along Highway 83	Manitoba	W. Lengerke	Black-and-White - Photographic negatives	4 x 5	1965-04-15
RG17	R194	2019-00196-6	1	29191-7	Admin-Flooding-Manitoba	Municipal road six miles north of Melita	Manitoba	W. Lengerke	Black-and-White - Photographic negatives	4 x 5	1965-04-15
RG17	R194	2019-00196-6	1	29191-8	Admin-Flooding-Manitoba	Farmland six miles north of Melita	Manitoba	W. Lengerke	Black-and-White - Photographic negatives	4 x 5	1965-04-15
RG17	R194	2019-00196-6	1	29191-9	Admin-Flooding-Manitoba	Souris Valley Processors Ltd., Melita, MB	Manitoba	W. Lengerke	Black-and-White - Photographic negatives	4 x 5	1965-04-15
RG17	R194	2019-00196-6	1	29191-10	Admin-Flooding-Manitoba	Highway 3, east of Junction 83 and 3 at Melita, MB	Manitoba	W. Lengerke	Black-and-White - Photographic negatives	4 x 5	1965-04-15
RG17	R194	2019-00196-6	1	29191-11	Admin-Flooding-Manitoba	International Harvester	Manitoba	W. Lengerke	Black-and-White - Photographic negatives	4 x 5	1965-04-15
RG17	R194	2019-00196-6	1	29191-12	Admin-Flooding-Manitoba	Bottom land one mile south of Melita along Highway 83	Manitoba	W. Lengerke	Black-and-White - Photographic negatives	4 x 5	1965-04-15
RG17	R194	2019-00196-6	1	29906-1	Community Water Development (CWD) Project-Carman Dam	Stephenfield Dam	Carman, MB	L.G. Gemmel	Black-and-White - Photographic negatives	2.25 x 2.25	1970-04-11
RG17	R194	2019-00196-6	1	29906-2	Community Water Development (CWD) Project-Carman Dam	Stephenfield Dam	Carman, MB	L.G. Gemmel	Black-and-White - Photographic negatives	2.25 x 2.25	1970-04-11

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	29906-3	Community Water Development (CWD) Project-Carman Dam	Stephenfield Dam	Carman, MB	L.G. Gemmel	Black-and-White - Photographic negatives	2.25 x 2.25	1970-04-11
RG17	R194	2019-00196-6	1	29906-4	Community Water Development (CWD) Project-Carman Dam	Stephenfield Dam	Carman, MB	L.G. Gemmel	Black-and-White - Photographic negatives	2.25 x 2.25	1970-04-11
RG17	R194	2019-00196-6	1	29906-5	Community Water Development (CWD) Project-Carman Dam	Stephenfield Dam	Carman, MB	L.G. Gemmel	Black-and-White - Photographic negatives	2.25 x 2.25	1970-04-11
RG17	R194	2019-00196-6	1	29906-6	Community Water Development (CWD) Project-Carman Dam	Morden Dam	Carman, MB	L.G. Gemmel	Black-and-White - Photographic negatives	2.25 x 2.25	1970-04-25
RG17	R194	2019-00196-6	1	29906-7	Community Water Development (CWD) Project-Carman Dam	Morden Dam	Carman, MB	L.G. Gemmel	Black-and-White - Photographic negatives	2.25 x 2.25	1970-04-25
RG17	R194	2019-00196-6	1	29906-8	Community Water Development (CWD) Project-Carman Dam	Morden Dam	Carman, MB	L.G. Gemmel	Black-and-White - Photographic negatives	2.25 x 2.25	1970-04-25
RG17	R194	2019-00196-6	1	29906-9	Community Water Development (CWD) Project-Carman Dam	Carman flood	Carman, MB	L.G. Gemmel	Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-29
RG17	R194	2019-00196-6	1	29906-10	Community Water Development (CWD) Project-Carman Dam	Carman flood	Carman, MB	L.G. Gemmel	Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-29
RG17	R194	2019-00196-6	1	29906-11	Community Water Development (CWD) Project-Carman Dam	Carman flood	Carman, MB	L.G. Gemmel	Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-29
RG17	R194	2019-00196-6	1	30104	Admin-Special Area - The Pas	The Pas Special Area Agreement signed May 11, 1970, by Hon. Jean Marchand, Federal Minister of Regional Economic Expansion, and the Hon. Sidney Green, Manitoba Minister of Mines and Natural Resources.	The Pas, MB		Black-and-White - Photographic negatives	4.50 x 5.25	1970-05-11
RG17	R194	2019-00196-6	1	30214-1	Special Areas - The Pas	Anglican church on the Big Eddy Reserve, The Pas	The Pas, MB	R. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1970-10-23
RG17	R194	2019-00196-6	1	30214-2	Special Areas - The Pas	Anglican church on the Big Eddy Reserve, The Pas	The Pas, MB	R. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1970-10-23
RG17	R194	2019-00196-6	1	30214-3	Special Areas - The Pas	House on the Big Eddy Reserve	The Pas, MB	R. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1970-10-23
RG17	R194	2019-00196-6	1	30214-4	Special Areas - The Pas	House on the Big Eddy Reserve	The Pas, MB	R. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1970-10-23
RG17	R194	2019-00196-6	1	30214-5	Special Areas - The Pas	Newly constructed outdoor skating rink on Big Eddy Reserve	The Pas, MB	R. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1970-10-23

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	30214-6	Special Areas - The Pas	Loading gravel at The Pas Indian Band gravel pit	The Pas, MB	R. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1970-10-23
RG17	R194	2019-00196-6	1	30214-7	Special Areas - The Pas	Loading gravel at The Pas Indian Band gravel pit	The Pas, MB	R. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1970-10-23
RG17	R194	2019-00196-6	1	30214-8	Special Areas - The Pas	Loading gravel at The Pas Indian Band gravel pit	The Pas, MB	R. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1970-10-23
RG17	R194	2019-00196-6	1	30214-9	Special Areas - The Pas	Checker at The Pas Indian Band gravel pit	The Pas, MB	R. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1970-10-23
RG17	R194	2019-00196-6	1	30214-10	Special Areas - The Pas	The Pas Indian Band ready mix batch plant.	The Pas, MB	R. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1970-10-23
RG17	R194	2019-00196-6	1	30214-11	Special Areas - The Pas	The Pas Indian Band ready mix batch plant.	The Pas, MB	R. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1970-10-23
RG17	R194	2019-00196-6	1	30214-12	Special Areas - The Pas	The Pas Indian Band ready mix batch plant.	The Pas, MB	R. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1970-10-23
RG17	R194	2019-00196-6	1	30247	Admin-Special Area - The Pas	Sanitary sewer line under construction along access road to new sewage lagoon in background. Contractor: Taillieu Construction, Headingly, MB.	The Pas, MB	R. Nakamura	Black-and-White - Photographic negatives	4 x 5	1970-10-22
RG17	R194	2019-00196-6	1	30781-1	Admin - Water Supply - Dugouts	Pembina Hutterite Coloney - Community Dugout, approximately 14 miles south west of Morden.; Neg 6-7: New Federal Building in Morden; Neg 8: Pembina Poultry Packers building; Neg 9-12: Rice fields of Mr. M. Sagon, Piney, MB	Morden, MB	R.L. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1971-09-07
RG17	R194	2019-00196-6	1	30781-2	Admin - Water Supply - Dugouts	Pembina Hutterite Coloney - Community Dugout, approximately 14 miles south west of Morden.	Morden, MB	R.L. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1971-09-07
RG17	R194	2019-00196-6	1	30781-3	Admin - Water Supply - Community Water Development	Hutterite Colony buildings; Neg 5: Entrance to beach and picnic area at Morden Dam;	Morden, MB	R.L. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1971-09-07
RG17	R194	2019-00196-6	1	30781-4	Admin - Water Supply - Community Water Development	Hutterite Colony buildings.	Morden, MB	R.L. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1971-09-07
RG17	R194	2019-00196-6	1	30781-5	Admin - Signs	Entrance to beach and picnic area at Morden Dam.	Morden, MB	R.L. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1971-09-07
RG17	R194	2019-00196-6	1	30781-6	Admin - Water Supply - Towns and Cities	New federal government building in Morden, MB.	Morden, MB	R.L. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1971-09-07

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	30781-7	Admin - Water Supply -Towns and Cities	New federal government building in Morden, MB	Morden, MB	R.L. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1971-09-07
RG17	R194	2019-00196-6	1	30781-8	Admin - Water Supply -Towns and Cities	Pembina Poultry Packers Building, Morden, MB.	Morden, MB	R.L. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1971-09-07
RG17	R194	2019-00196-6	1	30781-9	Admin - Crop Production - Special Crops - Wild Rice	Rice fields of Mr. M. Sagon, Piney, MB	Piney, MB	R.L. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1971-09-07
RG17	R194	2019-00196-6	1	30781-10	Admin - Crop Production - Special Crops - Wild Rice	Rice fields of Mr. M. Sagon, Piney, MB	Piney, MB	R.L. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1971-09-07
RG17	R194	2019-00196-6	1	30781-11	Admin - Crop Production - Special Crops - Wild Rice	Rice fields of Mr. M. Sagon, Piney, MB	Piney, MB	R.L. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1971-09-07
RG17	R194	2019-00196-6	1	30781-12	Admin - Crop Production - Special Crops - Wild Rice	Rice fields of Mr. M. Sagon, Piney, MB	Piney, MB	R.L. Paice	Black-and-White - Photographic negatives	2.25 x 2.25	1971-09-07
RG17	R194	2019-00196-6	1	50434	Community Water Development - Morden Dam	Cutting downstream face.	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1952-10-02
RG17	R194	2019-00196-6	1	50435	Community Water Development - Morden Dam	Outlet channel	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1952-10-09
RG17	R194	2019-00196-6	1	50442	Community Water Development - Morden Dam	Outlet channel excavation	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1952-10-18
RG17	R194	2019-00196-6	1	50449	Community Water Development-Morden Dam	Dumping and backdragging gravel blanket	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 3.25	1953-06-22
RG17	R194	2019-00196-6	1	50457	Community Water Development-Morden Dam	Laying two rows of straight steel	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1953-07-08
RG17	R194	2019-00196-6	1	50459	Community Water Development-Morden Dam	Pouring footing for the west wall	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1953-07-10
RG17	R194	2019-00196-6	1	50460	Community Water Development-Morden Dam	Pouring footing for west wall	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1953-07-10
RG17	R194	2019-00196-6	1	50472	Community Water Development-Morden Dam	Timber beams for steel	Morden Dam, MB		Black-and-White - Photographic negatives	4 x 5	1953-07-28
RG17	R194	2019-00196-6	1	50473	Community Water Development-Morden Dam	Forms to hold steel	Morden Dam, MB		Black-and-White - Photographic negatives	4 x 5	1953-07-28
RG17	R194	2019-00196-6	1	50486	Community Water Development-Morden Dam	Drilling pile holes	Morden Dam, MB		Black-and-White - Photographic negatives	4 x 5	1953-08-27

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	50487	Community Water Development-Morden Dam	PFRA Power drill truck from Saskatoon	Morden Dam, MB		Black-and-White - Photographic negatives	4 x 5	1953-08-27
RG17	R194	2019-00196-6	1	50488	Community Water Development-Morden Dam	Power truck from Saskatoon	Morden Dam, MB		Black-and-White - Photographic negatives	4 x 5	1953-08-27
RG17	R194	2019-00196-6	1	50497	Morden Dam	Concrete Mat and Poured Piles in Place	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1953-09-16
RG17	R194	2019-00196-6	1	50498	Community Water Development-Morden Dam	Digging upstream cutoff wall	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1953-09-16
RG17	R194	2019-00196-6	1	50499	Morden Dam	Spraying a freshly poured slab	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1953-09-16
RG17	R194	2019-00196-6	1	50500	Community Water Development-Morden Dam	Weight scales for gravel trucks	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1953-09-16
RG17	R194	2019-00196-6	1	50520	Community Water Development-Morden Dam	Pumpcrete machine	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1953-10-19
RG17	R194	2019-00196-6	1	50529	Community Water Development-Morden Dam	Machinery hauling clay-gravel trucks	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1953-10-26
RG17	R194	2019-00196-6	1	50535	Community Water Development-Morden Dam	Finishing clay over old spillway	Morden Dam, MB		Black-and-White - Photographic negatives	5.5 x 3.25	1953-10-29
RG17	R194	2019-00196-6	1	50537	Community Water Development-Morden Dam	Placing and compacting clay	Morden Dam, MB		Black-and-White - Photographic negatives	5.5 x 3.25	1953-11-05
RG17	R194	2019-00196-6	1	50538	Community Water Development - Morden Dam	This channel had to be done by dragline	Morden Dam, MB		Black-and-White - Photographic negatives	5.5 x 3.25	1953-11-13
RG17	R194	2019-00196-6	1	50563	Community Water Development-Morden Dam	Preparing drill hole	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1953-09-03
RG17	R194	2019-00196-6	1	50564	Community Water Development-Morden Dam	Preparing mortar	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1957-09-03
RG17	R194	2019-00196-6	1	50565	Community Water Development-Morden Dam	Filling drill hole with mortar	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1957-09-03
RG17	R194	2019-00196-6	1	50570	Community Water Development-Morden Dam	Drilling and filling test holes	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1957-09-05
RG17	R194	2019-00196-6	1	50576	Community Water Development-Morden Dam	Method of weighing batches	Morden Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1957-10-25

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	51471	Assiniboine River Flooding	Completely flooded farm near Elie, MB	Elie, MB		Black-and-White - Photographic negatives	35 mm	1955-06-12
RG17	R194	2019-00196-6	1	51657	Community Water Development-La Salle River	Driving sheet pile in Lewko Dam	Lewko Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1955-02-07
RG17	R194	2019-00196-6	1	51658	Community Water Development-La Salle River	View showing placing of articulated slab-west side	Lewko Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1955-02-02
RG17	R194	2019-00196-6	1	51661	Community Water Development-La Salle River	View showing dumping of rock fill.	Lewko Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1955-02-17
RG17	R194	2019-00196-6	1	51662	Community Water Development-La Salle River	Looking downstream, showing river in flood.	Lewko Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1955-04-05
RG17	R194	2019-00196-6	1	51663	Community Water Development-La Salle River	View from east bank showing water flowing over weir section.	Lewko Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1955-04-28
RG17	R194	2019-00196-6	1	52079-1	Community Water Development - Boissevain Dam	Start of excavation in area of exit channel.	Boissevain Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1961-07-26
RG17	R194	2019-00196-6	1	52079-2	Community Water Development - Boissevain Dam	Cofferdam area at 80 percent completion stage. Note coarse nature of fill material.	Boissevain Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1961-07-31
RG17	R194	2019-00196-6	1	52079-3	Community Water Development - Boissevain Dam	Hand and dragline excavation for grouted rock trench.	Boissevain Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1961-08-03
RG17	R194	2019-00196-6	1	52079-4	Community Water Development - Boissevain Dam	Grouted rock trench complete; camp no 1 in background	Boissevain Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1961-08-07
RG17	R194	2019-00196-6	1	52079-5	Community Water Development - Boissevain Dam	Batching and placing setup for grouting rock trench, reservoir at right centre.	Boissevain Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1961-08-07
RG17	R194	2019-00196-6	1	52079-6	Community Water Development - Boissevain Dam	Leveling and aligning footing form for drop inlet structure.	Boissevain Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1961-08-10
RG17	R194	2019-00196-6	1	52079-7	Community Water Development - Boissevain Dam	Batching and placing method for drop inlet structure concrete footing pour.	Boissevain Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1961-08-11
RG17	R194	2019-00196-6	1	52079-8	Community Water Development - Boissevain Dam	Crushed rock base, footing forms and steel in place prior to pour.	Boissevain Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1961-08-11

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	52104-1	Dugouts-Emergency Pumping Operations	Pumping equipment in transit on completion of filling dugout at Kris Jorgenson's farm located on SW 1/4 section 14-9-29 W1, R.M of Pipestone. The load of four inch aluminium pipe being hauled by PFRA vehicle, followed by Manitoba Dept of Agriculture extension Service vehicle hauling Myers Irrigation Pump.	RM of Pipestone, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 3.25	1961-08-11
RG17	R194	2019-00196-6	1	52104-2	Dugouts-Emergency Pumping Operations	Four inch aluminium pipeline being laid for pumping operations to fill dugout on douglas Williamson's farm located on SW 1/4 section 23-9-29 W1, RM of Pipestone. The pipeline runs from Pipestone Creek to the dugout for a distance of two miles.	RM of Pipestone, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 3.25	1961-08-08
RG17	R194	2019-00196-6	1	52104-3	Dugouts-Emergency Pumping Operations	Four inch aluminium pipeline running along road immediately northeast of Cromer from Pipestone Creek to fill farm dugout on Morris Senki's farm located on NW 1/4 section 14-9-28 W1, RM of Pipestone. Trench dug by hand for section of pipe crossing road.	RM of Pipestone, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 3.25	1961-08-15
RG17	R194	2019-00196-6	1	52104-4	Dugouts-Emergency Pumping Operations	T.E. Oatway, Manitoba Dept of Agriculture Extension Service. Engineer inspecting four inch Myers Power Take-Off Irrigation pump during pumping operations from dugout located on SE 1.4 section, 2-7-28 W1, to fill dugout on Dennis Smith's farm one mile southwest located on NW 1/4 section, 34-6-28, W1, RM of Albert.	RM of Albert, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 3.25	1961-08-22
RG17	R194	2019-00196-6	1	52104-5	Dugouts-Emergency Pumping Operations	T.E. Oatway, Manitoba Dept of Agriculture Extension Service. Engineer inspecting four inch Myers Power Take-Off Irrigation pump during pumping operations from dugout located on SE 1.4 section, 2-7-28 W1, to fill dugout on Dennis Smith's farm one mile southwest located on NW 1/4 section, 34-6-28, W1, RM of Albert.	RM of Albert, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 3.25	1961-08-22

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	52172-1	Community Water Development - Morden Dam	The complete visible portion of the Morden reservoir temperature sensing and recording installation, showing the anchored support buoy, the shore line marker float, the anchor post, and the shelter.	Morden Dam, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1963-06-12
RG17	R194	2019-00196-6	1	52172-2	Community Water Development - Morden Dam	The plywood shelter which houses the Thermograph at Morden. The plastic hoses, through which the sensor cables pass, have since been clamped to the horizontal crossbar.	Morden Dam, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1963-06-12
RG17	R194	2019-00196-6	1	52172-3	Community Water Development - Morden Dam	The shelter, the Thermograph, and the buoys at the Morden reservoir. The temperature sensors are suspended from the larger buoy in the background.	Morden Dam, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1963-06-12
RG17	R194	2019-00196-6	1	52172-4	Community Water Development - Morden Dam	The rear, or lake-facing side of the Thermograph shelter at Morden. Since this photo was taken, wooden clamps have been installed which attach the sensor cable carrying plastic hoses securely to the horizontal 2 inch by four inch. This prevents any strain on the cables.	Morden Dam, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1963-06-12
RG17	R194	2019-00196-6	1	52172-5	Community Water Development - Morden Dam	The shore anchor cable marker floats and the buoy which supports the temperature sensors at the Morden reservoir.	Morden Dam, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1963-06-12
RG17	R194	2019-00196-6	1	52172-6	Community Water Development - Morden Dam	The lower sensor, at Morden, is attached to the supporting rod 12 feet below the upper unit. The hose clamp prevents the plastic pipe from slipping out of the U-clamp.	Morden Dam, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1963-06-15
RG17	R194	2019-00196-6	1	52172-7	Community Water Development - Morden Dam	The upper temperature sensor and sunshade at the Morden reservoir. The flexible cable, enclosing the sending capillary, is clamped inside a 4 inch length of split wooden dowelling, inside a 1 inch Carlon hose. The hose is then clamped to a lug on a 14-foot length of galvanized steel rod.	Morden Dam, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1963-06-15
RG17	R194	2019-00196-6	1	52172-8	Community Water Development - Morden Dam	The Bristol's Dual Thermograph is housed in this plywood shelter at Morden.	Morden Dam, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1963-06-15
RG17	R194	2019-00196-6	1	52172-9	Community Water Development - Morden Dam	The anchor post, shore line and floats, and the supporting buoy for the Morden reservoir temperature recorder.	Morden Dam, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1963-06-15

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	52172-10	Community Water Development - Morden Dam	The sensor-supporting buoy anchor line floats, anchor post and recording shelter. This installation was made on June 12, 1963.	Morden Dam, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1963-06-15
RG17	R194	2019-00196-6	1	52172-11	Community Water Development - Morden Dam	A view, from the reservoir, of the sensor-supporting buoy anchor line floats, anchor post and recording shelter. This installation was made on June 12, 1963.	Morden Dam, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1963-06-15
RG17	R194	2019-00196-6	1	52778-1	Community Water Development-McEachern Dam	Installing 48 inch culvert in crossing over diversion ditch.	McEachern Dam, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-25
RG17	R194	2019-00196-6	1	52778-2	Community Water Development-McEachern Dam	Installing 48 inch culvert in crossing over diversion ditch.	McEachern Dam, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-25
RG17	R194	2019-00196-6	1	52778-3	Community Water Development-McEachern Dam	Hand placing asphalt resurfacing over 10 inch watermain on 2nd street.	McEachern Dam, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-25
RG17	R194	2019-00196-6	1	52778-4	Community Water Development-McEachern Dam	Hand placing asphalt resurfacing over 10 inch watermain on 2nd street.	McEachern Dam, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-25
RG17	R194	2019-00196-6	1	52778-5	Community Water Development-McEachern Dam	Roller compacting asphalt resurfacing on 2nd street.	Town of Carman, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-25
RG17	R194	2019-00196-6	1	52778-6	Community Water Development-McEachern Dam	Roller compacting asphalt resurfacing on 2nd street.	Town of Carman, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-25
RG17	R194	2019-00196-6	1	52778-7	Community Water Development-McEachern Dam	Machine placing asphalt resurfacing on 2nd street.	Town of Carman, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-25
RG17	R194	2019-00196-6	1	52778-8	Community Water Development-McEachern Dam	Machine placing asphalt resurfacing on 2nd street.	Town of Carman, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-25
RG17	R194	2019-00196-6	1	52778-9	Community Water Development-McEachern Dam	Damsite after bush clearing.	McEachern Dam, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-25
RG17	R194	2019-00196-6	1	52778-10	Community Water Development-McEachern Dam	Damsite after bush clearing.	McEachern Dam, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-25
RG17	R194	2019-00196-6	1	52778-11	Community Water Development-McEachern Dam	Damsite after bush clearing.	McEachern Dam, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-25
RG17	R194	2019-00196-6	1	52778-12	Community Water Development-McEachern Dam	Pile of brush from clearing damsite.	McEachern Dam, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-25
RG17	R194	2019-00196-6	1	52782-2	MP-ASCA-Town or Gilbert Plains-Town of Beausejour- Contract #5	Part of PFRA survey crew-Miles Watsko-running control levels in the rain. Tom sitting where it is dry keeping notes.	Beausejour, MB	R.Down	Black-and-White - Photographic negatives	35 mm	1977-09-15

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	52782-5	MP-ASCA-Town or Gilbert Plains-Town of Gilbert Plains	View of river looking downstream from golf course bridge.	Gilbert Plains, MB	R. Down	Black-and-White - Photographic negatives	35 mm	1977-09-15
RG17	R194	2019-00196-6	1	52782-6	MP-ASCA-Town or Gilbert Plains-Town of Gilbert Plains	Existing rock weir viewed from east bank.	Gilbert Plains, MB	R. Down	Black-and-White - Photographic negatives	35 mm	1977-09-15
RG17	R194	2019-00196-6	1	52782-7	MP-ASCA-Town or Gilbert Plains-Town of Gilbert Plains	View upstream from existing rock weir.	Gilbert Plains, MB	R. Down	Black-and-White - Photographic negatives	35 mm	1977-09-15
RG17	R194	2019-00196-6	1	52782-8	MP-ASCA-Town or Gilbert Plains-Town of Gilbert Plains	View downstream from existing weir.	Gilbert Plains, MB	R. Down	Black-and-White - Photographic negatives	35 mm	1977-09-15
RG17	R194	2019-00196-6	1	52782-9	MP-ASCA-Town or Gilbert Plains-Town of Gilbert Plains	View upstream of farm looking downstream towards eroded bank near buildings.	Gilbert Plains, MB	R. Down	Black-and-White - Photographic negatives	35 mm	1977-09-15
RG17	R194	2019-00196-6	1	52782-10	MP-ASCA-Town or Gilbert Plains-Town of Gilbert Plains	Upstream of farm looking downstream towards eroded bank near buildings.	Gilbert Plains, MB	R. Down	Black-and-White - Photographic negatives	35 mm	1977-09-15
RG17	R194	2019-00196-6	1	52782-11	MP-ASCA-Town or Gilbert Plains-Town of Gilbert Plains	Eroded bank near buildings from junction of cutoff and natural stream.	Gilbert Plains, MB	R. Down	Black-and-White - Photographic negatives	35 mm	1977-09-15
RG17	R194	2019-00196-6	1	52782-12	MP-ASCA-Town or Gilbert Plains-Town of Gilbert Plains	Upstream from east bank of cutoff showing natural river channel.	Gilbert Plains, MB	R. Down	Black-and-White - Photographic negatives	35 mm	1977-09-15
RG17	R194	2019-00196-6	1	52782-13	MP-ASCA-Town or Gilbert Plains-Town of Gilbert Plains	Intersection of cutoff with natural channel.	Gilbert Plains, MB	R. Down	Black-and-White - Photographic negatives	35 mm	1977-09-15
RG17	R194	2019-00196-6	1	52782-14	MP-ASCA-Town or Gilbert Plains-Town of Gilbert Plains	PFRA survey crew, M. Watsko with 7 iron chipping to green from draw on #1 Fairway; D. Cook supervises.	Gilbert Plains, MB	R. Down	Black-and-White - Photographic negatives	35 mm	1977-09-15
RG17	R194	2019-00196-6	1	52784-2	Community Water Development-McEachern Dam-Contract 1-B	Upstream coffer dam.	McEachern Dam, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-30
RG17	R194	2019-00196-6	1	52784-3	Community Water Development-McEachern Dam-Contract 1-B	Dozing river banks down into river bottom and hauling out muck.	McEachern Dam, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-30
RG17	R194	2019-00196-6	1	52784-4	Community Water Development-McEachern Dam-Contract 1-B	Dozing river banks down into river bottom and hauling out muck.	McEachern Dam, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-30
RG17	R194	2019-00196-6	1	52784-5	Community Water Development-McEachern Dam-Contract 1-B	South slope of excavation partially completed.	McEachern Dam, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-30
RG17	R194	2019-00196-6	1	52784-6	Community Water Development-McEachern Dam-Contract 1-B	South slope of excavation partially completed.	McEachern Dam, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-30
RG17	R194	2019-00196-6	1	52784-7	Community Water Development-McEachern Dam-Contract 1-B	Rain water in ex avation seat.	McEachern Dam, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-30

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	52784-8	Community Water Development-McEachern Dam-Contract 1-B	Rain water in excavation seat.	McEachern Dam, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-30
RG17	R194	2019-00196-6	1	52784-9	Community Water Development-McEachern Dam-Contract 1-B	Excavating dam site.	McEachern Dam, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-30
RG17	R194	2019-00196-6	1	52784-10	Community Water Development-McEachern Dam-Contract 1-B	Excavating dam site.	McEachern Dam, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-30
RG17	R194	2019-00196-6	1	52784-11	Community Water Development-McEachern Dam-Contract 1-B	Cutting sheet piling to rod lengths.	McEachern Dam, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-30
RG17	R194	2019-00196-6	1	52784-12	Community Water Development-McEachern Dam-Contract 1-B	Cutting sheet piling to rod lengths.	McEachern Dam, MB	R. Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-08-30
RG17	R194	2019-00196-6	1	52789-1	MP-ASCA-McEachern Dam-Contract #1B	Sluicing gravel into dumped rock.	McEachern Dam, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-10-12
RG17	R194	2019-00196-6	1	52789-2	MP-ASCA-McEachern Dam-Contract #1B	Sluicing gravel into dumped rock.	McEachern Dam, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-10-12
RG17	R194	2019-00196-6	1	52789-3	MP-ASCA-McEachern Dam-Contract #1B	Placing rip-rap.	McEachern Dam, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-10-12
RG17	R194	2019-00196-6	1	52789-4	MP-ASCA-McEachern Dam-Contract #1B	Placing rip-rap.	McEachern Dam, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-10-12
RG17	R194	2019-00196-6	1	52789-5	MP-ASCA-McEachern Dam-Contract #1B	Excavating O/S of sheet piling.	McEachern Dam, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-10-12
RG17	R194	2019-00196-6	1	52789-6	MP-ASCA-McEachern Dam-Contract #1B	Placing dumped rock O/S of sheet piling.	McEachern Dam, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-10-12
RG17	R194	2019-00196-6	1	52789-7	MP-ASCA-McEachern Dam-Contract #1B	Excavation near completion O/S end.	McEachern Dam, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-10-12
RG17	R194	2019-00196-6	1	52789-8	MP-ASCA-McEachern Dam-Contract #1B	Excavation near completion O/S end.	McEachern Dam, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-10-12
RG17	R194	2019-00196-6	1	52789-9	MP-ASCA-McEachern Dam-Contract #1B	Placing bedding gravel O/S end.	McEachern Dam, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-10-12
RG17	R194	2019-00196-6	1	52789-10	MP-ASCA-McEachern Dam-Contract #1B	Placing bedding gravel O/S end.	McEachern Dam, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-10-12
RG17	R194	2019-00196-6	1	52789-12	MP-ASCA-McEachern Dam-Contract #1B	Placing dumped rock O/S end.	McEachern Dam, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-10-12

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	52858-1	Community Water Development-Gilbert Plains	River channel before rock was excavated for spillway.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-09-26
RG17	R194	2019-00196-6	1	52858-2	Community Water Development-Gilbert Plains	River channel before rock was excavated for spillway.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-09-26
RG17	R194	2019-00196-6	1	52858-3	Community Water Development-Gilbert Plains	Diversion channel around site.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-09-26
RG17	R194	2019-00196-6	1	52858-4	Community Water Development-Gilbert Plains	U/S plug and future site of dam.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-09-26
RG17	R194	2019-00196-6	1	52858-5	Community Water Development-Gilbert Plains	Diversion channel around site.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-09-26
RG17	R194	2019-00196-6	1	52858-6	Community Water Development-Gilbert Plains	River channel before rock was excavated for spillway.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-09-26
RG17	R194	2019-00196-6	1	52858-7	Community Water Development-Gilbert Plains	River U/S from site. Note posts in water surrounding town water intake.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-09-26
RG17	R194	2019-00196-6	1	52858-8	Community Water Development-Gilbert Plains	View from U/S showing U/S plug and walk bridge.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-09-26
RG17	R194	2019-00196-6	1	52858-9	Community Water Development-Gilbert Plains	Double exposure.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-09-26
RG17	R194	2019-00196-6	1	52858-10	Community Water Development-Gilbert Plains	Brush cleared below F.S.L.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-09-26
RG17	R194	2019-00196-6	1	52858-11	Community Water Development-Gilbert Plains	Reservoir area cleared below F.S.L.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-09-26
RG17	R194	2019-00196-6	1	52858-12	Community Water Development-Gilbert Plains	Old river crossing U/S from site.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1977-09-26
RG17	R194	2019-00196-6	1	52870-1	Community Water Development-Gilbert Plains Dam	Borrow pit for clay blanket.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1978-11-17
RG17	R194	2019-00196-6	1	52870-2	Community Water Development-Gilbert Plains Dam	Crew tying steel in U/S cutoff wall.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1978-11-17
RG17	R194	2019-00196-6	1	52870-3	Community Water Development-Gilbert Plains Dam	Same as -2	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1978-11-17
RG17	R194	2019-00196-6	1	52870-4	Community Water Development-Gilbert Plains Dam	U/S clay blanket with site in background.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1978-11-17

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	52870-5	Community Water Development-Gilbert Plains Dam	Diversion channel.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1978-11-17
RG17	R194	2019-00196-6	1	52870-6	Community Water Development-Gilbert Plains Dam	Contractor preparing U/S and D/D cutoff walls.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1978-11-17
RG17	R194	2019-00196-6	1	52870-7	Community Water Development-Gilbert Plains Dam	Same as -6.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1978-11-17
RG17	R194	2019-00196-6	1	52870-8	Community Water Development-Gilbert Plains Dam	Dragline trimming waste pile at lower end of diversion.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1978-11-17
RG17	R194	2019-00196-6	1	52870-9	Community Water Development-Gilbert Plains Dam	Same as -7.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1978-11-17
RG17	R194	2019-00196-6	1	52870-10	Community Water Development-Gilbert Plains Dam	U/S clay blanket.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1978-11-17
RG17	R194	2019-00196-6	1	52870-11	Community Water Development-Gilbert Plains Dam	Diversion channel.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1978-11-17
RG17	R194	2019-00196-6	1	52870-12	Community Water Development-Gilbert Plains Dam	Drainage ditch through waste area.	Gilbert Plains, MB	R.Down	Black-and-White - Photographic negatives	2.25 x 2.25	1978-11-17
RG17	R194	2019-00196-6	1	52900-1	Water Development Project-Gilbert Plains Dam	North wing wall, #6, #7 piers with stop logs in place.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-02-06
RG17	R194	2019-00196-6	1	52900-2	Water Development Project-Gilbert Plains Dam	Front of concrete structure before back fill placed.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-02-06
RG17	R194	2019-00196-6	1	52900-3	Water Development Project-Gilbert Plains Dam	Front of concrete structure before back fill was placed.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-02-06
RG17	R194	2019-00196-6	1	52900-4	Water Development Project-Gilbert Plains Dam	South wingwall and #1 and #2 piers with stop logs in place.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-02-06
RG17	R194	2019-00196-6	1	52900-5	Water Development Project-Gilbert Plains Dam	South sidewall and #1 and #2 piers with stop logs, walkway and handrails in place.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-02-06
RG17	R194	2019-00196-6	1	52900-6	Water Development Project-Gilbert Plains Dam	North sidewall and piers #4 - 7 with stop logs, walkway and handrails in place.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-02-06
RG17	R194	2019-00196-6	1	52900-7	Water Development Project-Gilbert Plains Dam	South wingwall and piers #1 - 5 with monorail posts installed.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-02-06
RG17	R194	2019-00196-6	1	52900-9	Water Development Project-Gilbert Plains Dam	Hoarding used by contractor to enclose concrete structure.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-02-06

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	52900-10	Water Development Project-Gilbert Plains Dam	D-8-H dozer and ripper removing frozen material from borrow area.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-02-08
RG17	R194	2019-00196-6	1	52900-11	Water Development Project-Gilbert Plains Dam	D-8-H Dozer and ripper removing frozen material from borrow area.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-02-08
RG17	R194	2019-00196-6	1	52900-12	Water Development Project-Gilbert Plains Dam	Contractor placing hand tamped backfill in front of concrete structure.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-02-08
RG17	R194	2019-00196-6	1	52917-1	Community Development Project-Gilbert Plains Dam-Vermilion Dam	View of Golf Club house taken from driveway.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-23
RG17	R194	2019-00196-6	1	52917-2	Community Development Project-Gilbert Plains Dam-Vermilion Dam	View of parking lot at Golf Course.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-23
RG17	R194	2019-00196-6	1	52917-3	Community Development Project-Gilbert Plains Dam-Vermilion Dam	View of Golf Club house taken from driveway.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-23
RG17	R194	2019-00196-6	1	52917-4	Community Development Project-Gilbert Plains Dam-Vermilion Dam	Note block of ice compared to flooding of south abutment. Welder leaning against hydro pole.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-23
RG17	R194	2019-00196-6	1	52917-5	Community Development Project-Gilbert Plains Dam-Vermilion Dam	Concrete structure. With ice jam in front note length of ice jam.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-23
RG17	R194	2019-00196-6	1	52917-6	Community Development Project-Gilbert Plains Dam-Vermilion Dam	Flood water coming over south abutment.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-23
RG17	R194	2019-00196-6	1	52917-7	Community Development Project-Gilbert Plains Dam-Vermilion Dam	Double exposure.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-23
RG17	R194	2019-00196-6	1	52917-8	Community Development Project-Gilbert Plains Dam-Vermilion Dam	Double exposure.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-23
RG17	R194	2019-00196-6	1	52917-9	Community Development Project-Gilbert Plains Dam-Vermilion Dam	Water flowing over spillway.	Vermilion Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-23
RG17	R194	2019-00196-6	1	52917-10	Community Development Project-Gilbert Plains Dam-Vermilion Dam	Water flowing over spillway.	Vermilion Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-23
RG17	R194	2019-00196-6	1	52917-11	Community Development Project-Gilbert Plains Dam-Vermilion Dam	Looking west along main embankment.	Vermilion Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-23
RG17	R194	2019-00196-6	1	52918-1	Community Water Development - Gilbert Plains Dam	View of concrete structure and south abutment after flood waters have gone down.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-24
RG17	R194	2019-00196-6	1	52918-2	Community Water Development - Gilbert Plains Dam	Farm buildings after flood waters have gone down.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-24

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	52918-3	Community Water Development - Gilbert Plains Dam	Tee jam against PFRA trailer which was shifted during flood.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-24
RG17	R194	2019-00196-6	1	52918-4	Community Water Development - Gilbert Plains Dam	Farm buildings and ice left on dike after flood waters have tone down.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-24
RG17	R194	2019-00196-6	1	52918-5	Community Water Development - Gilbert Plains Dam	Concrete structure after ice jam broke up (note) broken walkway.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-24
RG17	R194	2019-00196-6	1	52918-6	Community Water Development - Gilbert Plains Dam	Concrete structure after ice jam broke up (note) broken walkway.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-24
RG17	R194	2019-00196-6	1	52918-7	Community Water Development - Gilbert Plains Dam	Ice deposited by flood waters on south abutment.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-24
RG17	R194	2019-00196-6	1	52918-8	Community Water Development - Gilbert Plains Dam	Ice deposited by flood waters on south dike.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-24
RG17	R194	2019-00196-6	1	52918-9	Community Water Development - Gilbert Plains Dam	Ice deposited by flood waters on south dike.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-24
RG17	R194	2019-00196-6	1	52918-10	Community Water Development - Gilbert Plains Dam	Ice deposited by flood waters on south abutment (note) erosion along wingwall.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-24
RG17	R194	2019-00196-6	1	52918-11	Community Water Development - Gilbert Plains Dam	Ice deposited by flood waters on south abutment (note) erosion along wing-wall.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-24
RG17	R194	2019-00196-6	1	52918-12	Community Water Development - Gilbert Plains Dam	Ice deposited by flood waters on south abutment (note) erosion along wing-wall.	Gilbert Plains, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1979-04-24
RG17	R194	2019-00196-6	1	52409-1	Community Water Development-Kenton Damsite	Installation of perforated drain pipe under lower slab of stilling basin.	Kenton Damsite, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1968-08-13
RG17	R194	2019-00196-6	1	52409-2	Community Water Development-Kenton Damsite	Close up of perforated pipe and steel risers placed under lower slab of stilling basin	Kenton Damsite, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1968-08-13
RG17	R194	2019-00196-6	1	52409-3	Community Water Development-Kenton Damsite	View of embankment area and core trench showing water which ponded after 2.50 inches of rain.	Kenton Damsite, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1968-08-13
RG17	R194	2019-00196-6	1	52409-4	Community Water Development-Kenton Damsite	54 inches diameter pipe and downstream embankment area after heavy rain.	Kenton Damsite, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1968-08-16
RG17	R194	2019-00196-6	1	52409-5	Community Water Development-Kenton Damsite	General view of embankment area from southwest abutment showing water ponded on the area after a 2.50 inch rain.	Kenton Damsite, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1968-08-16
RG17	R194	2019-00196-6	1	52409-6	Community Water Development-Kenton Damsite	Close up of perforated drain pipe and Zone 3 material under upper slab of stilling basin.	Kenton Damsite, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1968-08-16

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	52409-7	Community Water Development-Kenton Damsite	Drain pipe under stilling basin, upper slab.	Kenton Damsite, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1968-08-27
RG17	R194	2019-00196-6	1	52409-8	Community Water Development-Kenton Damsite	Embankment area as seen from northeast abutment looking in an upstream direction. Note second wall lifts on drop inlet and gatewell structures completed.	Kenton Damsite, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1968-08-27
RG17	R194	2019-00196-6	1	52409-9	Community Water Development-Kenton Damsite	AC-HD-11 tractor pulling hyster 60 inch wedgefoot roller on left side of 30 inch diameter inlet pipe.	Kenton Damsite, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1968-08-27
RG17	R194	2019-00196-6	1	52409-10	Community Water Development-Kenton Damsite	Cat 619 motor scraper placing embankment material in Zone A area. Note core trench at upper left over-excavated by machine travel.	Kenton Damsite, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1968-08-29
RG17	R194	2019-00196-6	1	52409-11	Community Water Development-Kenton Damsite	Placing concrete for upper slab of stilling basin.	Kenton Damsite, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1968-08-29
RG17	R194	2019-00196-6	1	52409-12	Community Water Development-Kenton Damsite	Placing concrete for upper slab of stilling basin using crane with bucket direct from mixer situated at right side of photo.	Kenton Damsite, MB	H.G. Riesen	Black-and-White - Photographic negatives	2.25 x 2.25	1968-08-29
RG17	R194	2019-00196-6	1	52414-1	Communnity Water Development-Kenton Dam	Cat 619 motor scraper backfilling core trench through south west abutment.	Kenton Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-10-01
RG17	R194	2019-00196-6	1	52414-2	Communnity Water Development-Kenton Dam	Handtamping impervious material over 54 inch pipe between drop inlet and junction block.	Kenton Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-10-01
RG17	R194	2019-00196-6	1	52414-3	Communnity Water Development-Kenton Dam	View of 54 inch pipe and stilling basin from top of drop inlet. Note: Hough 50FEL placing Zone 2 embankment on left side of pipe, labourer placing Zone 2A around pipe.	Kenton Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-10-01
RG17	R194	2019-00196-6	1	52414-4	Communnity Water Development-Kenton Dam	IH-TD 24 dozer pulling Hyster wedgefoot pack through core trench on south west abutment.	Kenton Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-10-01
RG17	R194	2019-00196-6	1	52414-5	Communnity Water Development-Kenton Dam	Gatewell showing three lifts, top of first, second and third. Dark area is section cured with Sterneson Rite Cure.	Kenton Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-10-01
RG17	R194	2019-00196-6	1	52414-7	Communnity Water Development-Kenton Dam	View of drop inlet and gatewell as seen from downstream of the stilling basin	Kenton Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-10-01
RG17	R194	2019-00196-6	1	52414-8	Communnity Water Development-Kenton Dam	Work area as seen from south west abutment. Machines placing Zone A embankment	Kenton Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-10-01

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	52414-9	Communnity Water Development-Kenton Dam	Work area as seen from north east abutment. IH-TD 20 tractor pulling Hyster Wedgefoot roller. Drop inlet completed, final lift to be placed on gateway.	Kenton Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-10-01
RG17	R194	2019-00196-6	1	52414-10	Communnity Water Development-Kenton Dam	View of completed stilling basin. Dumped Zone 2 material in foreground.	Kenton Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-10-01
RG17	R194	2019-00196-6	1	52414-11	Communnity Water Development-Kenton Dam	Placing Zone B embankment from Sta. 13 and 75 to Sta. 15 and 75.	Kenton Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-10-01
RG17	R194	2019-00196-6	1	52414-12	Communnity Water Development-Kenton Dam	View of stilling basing as seen from Zone A embankment. Note: Zone 2A placed over pipe almost to grade.	Kenton Dam, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-10-01
RG17	R194	2019-00196-6	1	52417-1	Community Water Development-Kenton Dam	Dragline carrying gate to gateway.	Kenton Dam, Bars Creek, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-11-15
RG17	R194	2019-00196-6	1	52417-2	Community Water Development-Kenton Dam	Labourers hand placing riprap bedding along stilling basin sidewalls.	Kenton Dam, Bars Creek, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-11-15
RG17	R194	2019-00196-6	1	52417-3	Community Water Development-Kenton Dam	Armco 18H30 gate just prior to installation.	Kenton Dam, Bars Creek, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-11-15
RG17	R194	2019-00196-6	1	52417-4	Community Water Development-Kenton Dam	View of gate showing flange back.	Kenton Dam, Bars Creek, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-11-15
RG17	R194	2019-00196-6	1	52417-5	Community Water Development-Kenton Dam	Lowering gate into gateway.	Kenton Dam, Bars Creek, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-11-15
RG17	R194	2019-00196-6	1	52417-6	Community Water Development-Kenton Dam	Photo of overthrust showing lath at Sta. 14+00. The lath on the right was initially set in a vertical position on Nov 8, 1968.	Kenton Dam, Bars Creek, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-11-15
RG17	R194	2019-00196-6	1	52417-7	Community Water Development-Kenton Dam	View of stilling basin and dam looking upstream. Note erection of gatehouse just started.	Kenton Dam, Bars Creek, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-11-20
RG17	R194	2019-00196-6	1	52417-8	Community Water Development-Kenton Dam	Labourers erecting walls for gatehouse. Note gate stem is in the raised position.	Kenton Dam, Bars Creek, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-11-20
RG17	R194	2019-00196-6	1	52417-9	Community Water Development-Kenton Dam	General view of upstream side of dam as seen from north east abutment.	Kenton Dam, Bars Creek, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-11-29
RG17	R194	2019-00196-6	1	52417-10	Community Water Development-Kenton Dam	2010 John Deere front end loader and rock bucket used for processing riprap.	Kenton Dam, Bars Creek, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-11-22
RG17	R194	2019-00196-6	1	52417-11	Community Water Development-Kenton Dam	Source of riprap SW 1/4 33-10-22 WPM. Face is approximately five feet high.	Kenton Dam, Bars Creek, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-11-22

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	52417-12	Community Water Development-Kenton Dam	Municipal pit from which riprap bedding material was hauled. Face is approximately 12 feet high.	Kenton Dam, Bars Creek, MB		Black-and-White - Photographic negatives	2.25 x 2.25	1968-11-22
RG17	R194	2019-00196-6	1	52433-1	Community Water Development-Kenton Dam	Trimming backslope of embankment. D-8 tractor pulling harrows.	Kenton Dam, MB	R.L. Bigg	Black-and-White - Photographic negatives	2.25 x 2.25	1969-06-09
RG17	R194	2019-00196-6	1	52433-2	Community Water Development-Kenton Dam	Seeding grass in spillway area.	Kenton Dam, MB	R.L. Bigg	Black-and-White - Photographic negatives	2.25 x 2.25	1969-06-20
RG17	R194	2019-00196-6	1	52433-3	Community Water Development-Kenton Dam	Seeding grass on backslope of embankment. Two-horse team pulling diamond harrows.	Kenton Dam, MB	R.L. Bigg	Black-and-White - Photographic negatives	2.25 x 2.25	1969-06-23
RG17	R194	2019-00196-6	1	52433-4	Community Water Development-Kenton Dam	Screening rock riprap before placing on embankment.	Kenton Dam, MB	R.L. Bigg	Black-and-White - Photographic negatives	2.25 x 2.25	1969-07-03
RG17	R194	2019-00196-6	1	52433-5	Community Water Development-Kenton Dam	Placing rock riprap on embankment. Hough 60 front end loader.	Kenton Dam, MB	R.L. Bigg	Black-and-White - Photographic negatives	2.25 x 2.25	1969-07-15
RG17	R194	2019-00196-6	1	52433-6	Community Water Development-Kenton Dam	Embankment looking upstream from south end.	Kenton Dam, MB	R.L. Bigg	Black-and-White - Photographic negatives	2.25 x 2.25	1969-07-15
RG17	R194	2019-00196-6	1	52433-7	Community Water Development-Kenton Dam	Reservoir at full supply level (looking upstream from embankment).	Kenton Dam, MB	R.L. Bigg	Black-and-White - Photographic negatives	2.25 x 2.25	1969-07-16
RG17	R194	2019-00196-6	1	52433-8	Community Water Development-Kenton Dam	Gully caused by heavy rains. (North end, downstream side of embankment)	Kenton Dam, MB	R.L. Bigg	Black-and-White - Photographic negatives	2.25 x 2.25	1969-07-16
RG17	R194	2019-00196-6	1	52433-9	Community Water Development-Kenton Dam	Top of drop inlet spillway. Reservoir at full supply level. Temporary screen over inlet.	Kenton Dam, MB	R.L. Bigg	Black-and-White - Photographic negatives	2.25 x 2.25	1969-07-23
RG17	R194	2019-00196-6	1	52433-10	Community Water Development-Kenton Dam	Upstream face of embankment. Rock riprap in place.	Kenton Dam, MB	R.L. Bigg	Black-and-White - Photographic negatives	2.25 x 2.25	1969-07-23
RG17	R194	2019-00196-6	1	53071-1	Community Water Development-Gilbert Plains	Trees and scrub washed against structure from heavy rains in Duck Mountain.	Gilbert Plains, MB		Black-and-White - Photographic negatives	35 mm film	1981-07-06
RG17	R194	2019-00196-6	1	53071-2	Community Water Development-Gilbert Plains	Trees and scrub washed against structure from heavy rains in Duck Mountain.	Gilbert Plains, MB		Black-and-White - Photographic negatives	35 mm film	1981-07-06
RG17	R194	2019-00196-6	1	53071-3	Community Water Development-Gilbert Plains	Flood waters below structure from heavy rains in Duck Mountain	Gilbert Plains, MB		Black-and-White - Photographic negatives	35 mm film	1981-07-06
RG17	R194	2019-00196-6	1	53071-4	Community Water Development-Gilbert Plains	Water against emergency spillway plug. Note red ribbon at top of plug which was the elevation of water before stop logs removed.	Gilbert Plains, MB		Black-and-White - Photographic negatives	35 mm film	1981-07-06
RG17	R194	2019-00196-6	1	53071-5	Community Water Development-Gilbert Plains	Crew hoisting logs with hoists and sawing into pieces which will go through bays.	Gilbert Plains, MB		Black-and-White - Photographic negatives	35 mm film	1981-07-07

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	53071-6	Community Water Development-Gilbert Plains	Crew hoisting logs with hoists and sawing into pieces which will go through bays.	Gilbert Plains, MB		Black-and-White - Photographic negatives	35 mm film	1981-07-07
RG17	R194	2019-00196-6	1	53071-7	Community Water Development-Gilbert Plains	Trees and scrub against structure from heavy rains in Duck Mountain.	Gilbert Plains, MB		Black-and-White - Photographic negatives	35 mm film	1981-07-07
RG17	R194	2019-00196-6	1	53071-8	Community Water Development-Gilbert Plains	Trees and scrub against structure from heavy rains in Duck Mountain.	Gilbert Plains, MB		Black-and-White - Photographic negatives	35 mm film	1981-07-07
RG17	R194	2019-00196-6	1	53071-9	Community Water Development-Gilbert Plains	Trees and scrub against structure from heavy rains in Duck Mountain.	Gilbert Plains, MB		Black-and-White - Photographic negatives	35 mm film	1981-07-07
RG17	R194	2019-00196-6	1	53071-10	ASCA Town of Dauphin	Backfill around reservoir and pumphouse	Dauphin, MB		Black-and-White - Photographic negatives	35 mm film	1981-07-29
RG17	R194	2019-00196-6	1	53071-11	ASCA Town of Dauphin	Backfill around reservoir and pumphouse	Dauphin, MB		Black-and-White - Photographic negatives	35 mm film	1981-07-29
RG17	R194	2019-00196-6	1	53071-12	ASCA Town of Dauphin	Backfill around reservoir and pumphouse	Dauphin, MB		Black-and-White - Photographic negatives	35 mm film	1981-07-29
RG17	R194	2019-00196-6	1	53071-13	ASCA Town of Dauphin	Backfill around reservoir and pumphouse	Dauphin, MB		Black-and-White - Photographic negatives	35 mm film	1981-07-29
RG17	R194	2019-00196-6	1	53071-14	ASCA Town of Dauphin	Backfill around reservoir and pumphouse	Dauphin, MB		Black-and-White - Photographic negatives	35 mm film	1981-07-29
RG17	R194	2019-00196-6	1	53071-15	Community Water Development-Lower Edwards Creek Dam	Condition of wooden structure at upper end of Lower Edwards Creek Dam.	Lower Edwards Creek Dam, MB		Black-and-White - Photographic negatives	35 mm film	1981-09-15
RG17	R194	2019-00196-6	1	53071-16	Community Water Development-Lower Edwards Creek Dam	Condition of wooden structure at upper end of Lower Edwards Creek Dam.	Lower Edwards Creek Dam, MB		Black-and-White - Photographic negatives	35 mm film	1981-09-15
RG17	R194	2019-00196-6	1	53071-17	Community Water Development-Lower Edwards Creek Dam	Condition of wooden structure at upper end of Lower Edwards Creek Dam.	Lower Edwards Creek Dam, MB		Black-and-White - Photographic negatives	35 mm film	1981-09-15
RG17	R194	2019-00196-6	1	53071-18	Community Water Development-Lower Edwards Creek Dam	Condition of wooden structure at upper end of Lower Edwards Creek Dam.	Lower Edwards Creek Dam, MB		Black-and-White - Photographic negatives	35 mm film	1981-09-15
RG17	R194	2019-00196-6	1	53071-19	Community Water Development-Lower Edwards Creek Dam	Condition of wooden structure at upper end of Lower Edwards Creek Dam.	Lower Edwards Creek Dam, MB		Black-and-White - Photographic negatives	35 mm film	1981-09-15
RG17	R194	2019-00196-6	1	53071-20	Community Water Development-Lower Edwards Creek Dam	Condition of wooden structure at upper end of Lower Edwards Creek Dam.	Lower Edwards Creek Dam, MB		Black-and-White - Photographic negatives	35 mm film	1981-09-15
RG17	R194	2019-00196-6	1	53071-21	Community Water Development-Lower Edwards Creek Dam	Condition of wooden structure at upper end of Lower Edwards Creek Dam.	Lower Edwards Creek Dam, MB		Black-and-White - Photographic negatives	35 mm film	1981-09-15

RG	R	Accession no. / No. d'acquisition	Box / Boîte	Neg. No.	Title / Titre	Caption / Légende de la photo	Geographic Location/ Position géographique	Photographer / Photographe	Photograph Type/ Type de photographie	Dimensions	Date
RG17	R194	2019-00196-6	1	53071-22	Community Water Development-Lower Edwards Creek Dam	Condition of wooden structure at upper end of Lower Edwards Creek Dam.	Lower Edwards Creek Dam, MB		Black-and-White - Photographic negatives	35 mm film	1981-09-15
RG17	R194	2019-00196-6	1	53071-23	Community Water Development-Lower Edwards Creek Dam	Condition of wooden structure at upper end of Lower Edwards Creek Dam.	Lower Edwards Creek Dam, MB		Black-and-White - Photographic negatives	35 mm film	1981-09-15
RG17	R194	2019-00196-6	1	53121-1	Admin-Public Relations-Morden Dam Official Opening-	Opening ceremonies. Speaker is Herb Gray, Minister of Regional Economic Expansion	Morden Dam, MB		Colour - Photographic negatives	35 mm film	1982-10-01
RG17	R194	2019-00196-6	1	53121-1A	Admin-Public Relations-Morden Dam Official Opening-	Opening ceremonies, unveiling plaque.	Morden Dam, MB		Colour - Photographic negatives	35 mm film	1982-10-01
RG17	R194	2019-00196-6	1	53121-2A	Admin-Public Relations-Morden Dam Official Opening-	Opening ceremonies. Unveiling of plaque. Left to right: Frank Strauss, Mason Construction; Herb Gray, Minister of Regional Economic Expansion; Al Mackling, Minister of Natural Resources for Prov of Manitoba; Max Friesen, Mayor of Morden.	Morden Dam, MB		Colour - Photographic negatives	35 mm film	1982-10-01
RG17	R194	2019-00196-6	1	53121-3A	Admin-Public Relations-Morden Dam Official Opening-Pipestone Creek	CPR dam on Pipestone Creek W Boundary Sec. 21-7-27W1.	Pipestone Creek, MB		Colour - Photographic negatives	35 mm film	1982-10-01
RG17	R194	2019-00196-6	1	53121-4A	Admin-Public Relations-Morden Dam Official Opening-Pipestone Creek	Pipestone Creek at SW corner Sec. 17-8-27W1.	Pipestone Creek, MB		Colour - Photographic negatives	35 mm film	1982-10-01
RG17	R194	2019-00196-6	1	53121-5A	Admin-Public Relations-Morden Dam Official Opening-Pipestone Creek	Pipestone Creek looking downstream at S boundary Sec. 35-8-28W1.	Pipestone Creek, MB		Colour - Photographic negatives	35 mm film	1982-10-01
RG17	R194	2019-00196-6	1	53121-6A	Admin-Public Relations-Morden Dam Official Opening-Pipestone Creek	Looking west across valley of Pipestone Creek near Cromer Damsite in NE 1/4 Sec. 24-9-29W1.	Pipestone Creek, MB		Colour - Photographic negatives	35 mm film	1982-10-01
RG17	R194	2019-00196-6	1	53121-7A	Admin-Public Relations-Morden Dam Official Opening-Pipestone Creek	Looking west across valley upstream of previous picture.	Pipestone Creek, MB		Colour - Photographic negatives	35 mm film	1982-10-01
RG17	R194	2019-00196-6	1	53121-8A	Admin-Public Relations-Morden Dam Official Opening-Pipestone Creek	Looking upstream (north-west) in SE 1/4 Sec. 25-9-29W1.	Pipestone Creek, MB		Colour - Photographic negatives	35 mm film	1982-10-01
RG17	R194	2019-00196-6	1	53121-9A	Admin-Public Relations-Morden Dam Official Opening-Pipestone Creek	Looking downstream (south) in SE 1/4 Sec 25-9-29W1.	Pipestone Creek, MB		Colour - Photographic negatives	35 mm film	1982-10-01
RG17	R194	2019-00196-6	1	53121-10A	Admin-Public Relations-Morden Dam Official Opening-Pipestone Creek	Flashboards and ogee weir on Moosomin Dam spillway.	Pipestone Creek, MB		Colour - Photographic negatives	35 mm film	1982-10-01
RG17	R194	2019-00196-6	1	53121-11A	Admin-Public Relations-Morden Dam Official Opening-Pipestone Creek	Looking across spillway at Moosomin Dam.	Pipestone Creek, MB		Colour - Photographic negatives	35 mm film	1982-10-01
RG17	R194	2019-00196-6	1	53121-12A	Admin-Public Relations-Morden Dam Official Opening-Pipestone Creek	Looking down spillway at Moosomin Dam.	Pipestone Creek, MB		Colour - Photographic negatives	35 mm film	1982-10-01