

isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
1	RG52 / R1195	2018-00304-6	1	Project E1-074	SLSA : The Use of Locks as Cascades	1971-11-30	
2	RG52 / R1195	2018-00304-6	1	N-1992-39, 14-642	MIE Consulting Engineers Ltd. : Welland Canal Wharf 10 Underwater Inspection November 1992	1992-11-30	
3	RG52 / R1195	2018-00304-6	1	N-1992-39, 14-642	MIE Consulting Engineers Ltd. : Welland Canal Wharf 9 Underwater Inspection November 1992	1992-11-30	
4	RG52 / R1195	2018-00304-6	1		SLSA : The St. Lawrence Seaway Authority Preliminary Twinning Study Montreal to Lake Erie	1965-11-08	
5	RG52 / R1195	2018-00304-6	1		SLSA : Report on the Closing of Navigation 1988 Season Western Region Welland Canal	1988-12-31	
6	RG52 / R1195	2018-00304-6	1		SLSA : Report on Closing of Navigation 1983 Season Welland Canal Western Region	1983-12-31	
7	RG52 / R1195	2018-00304-6	1	M-1968-17, 14-206	H.G. Acres & Company Limited : Townline Road Pump Test Interim Presentation of Data	1968-03-30	
8	RG52 / R1195	2018-00304-6	1	9, 12 & 13-B-47, 96- K-56, I,4,5-C-49, 2- D-59, 2-D-92, 1&2-C- 48, 40-G-51	SLSA : 11 Bridge No. 4 - Homer, Track Girders, etc..	1930-05-21	1956-11-14
9	RG52 / R1195	2018-00304-6	1	Project No. 152076	Sandwell Inc. : Power System Study for Distribution System at the St. Lawrence Seaway Authority Western Region Glendale Avenue Administration & Maintenance Complex	1990-01-01	
10	RG52 / R1195	2018-00304-6	1	L04757-50317-C7- 430300, N-1191-20	Warnock Hersey Professional Services Ltd./R.C. Sansom : Report on the Surge Tank Inspection (1991) Contract No. 14-600	1991-01-31	
11	RG52 / R1195	2018-00304-6	1		Monenco Consultants Ltd. : St. Lawrence Seaway Authority Short Circuit & Protection Co-Ordination Study for CoGeneration Feasibility Interim Report	1987-10-31	
12	RG52 / R1195	2018-00304-6	1		Royal Commission: Quebec Bridge Inquiry List of Plans Accompanying the Report (Drawings 1 to 35 & Drawing 37)	1907-01-01	1908-12-31
13	RG52 / R1195	2018-00304-6	1	Sessional Paper No. 154 7-8 Edward VII	Printed by Order of Parliament, Printed by S.E. Dawson : Royal Commission: Quebec Bridge Inquiry Vol II, Minutes of Procedures & Printed Exhibits	1908-12-31	
14	RG52 / R1195	2018-00304-6	1	Ex. Doc 1, pt.2, vol II	Washington: Government Printing Office 1892 : Annual Report of the Chief of Engineers United States Army to the Secretary of War for the Year 1892 (Drawings)	1892-01-01	
15	RG52 / R1195	2018-00304-6	1		Printed & Published by Baptist Johnston, Printer to the Queen's Most Excellent Majesty : Report of the Select Committee of the Ontario Legislature on Lake Levels of the Great Lakes	1953-01-01	

isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
16	RG52 / R1195	2018-00304-6	2	B7877, 01B (0896), Contract #14-697 (AVMSL), 08200-96- LAB-005-00 (Hydro Québec)	Laboratoire de Béton Ltée/Pierre Lamothe : Essais en laboratoire détermination de la teneur en alcalis soluble du béton écluses de Saint-Lambert, Sainte-Catherine et de Beauharnois	1996-08-26	
17	RG52 / R1195	2018-00304-6	2	B7877, 02B (1096)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 01 (mai 1996) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint-Laurent, Contrat AVMSL No. 14-697 Contract HQ No. 08200-96-LAB-005-00	1996-10-31	
18	RG52 / R1195	2018-00304-6	2	B7877, 03B (1096)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 02 (juin 1996) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint-Laurent, Contrat AVMSL No. 14-697 Contract HQ No. 08200-96-LAB-005-00	1996-10-31	
19	RG52 / R1195	2018-00304-6	2	B7877, 04B (1096)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 03 (juillet 1996) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint-Laurent, Contrat AVMSL No. 14-697 Contract HQ No. 08200-96-LAB-005-00	1996-10-31	
20	RG52 / R1195	2018-00304-6	2	B7877, 05B (1196)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 04 (août et septembre 1996) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint-Laurent, Contrat AVMSL No. 14-697 Contract HQ No. 08200-96-LAB-005-00	1996-11-30	
21	RG52 / R1195	2018-00304-6	2	B7877, 06B (0197)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 05 (octobre et novembre 1996) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint-Laurent, Contrat AVMSL No. 14-697 Contract HQ No. 08200-96-LAB-005-00	1997-01-31	
22	RG52 / R1195	2018-00304-6	2	B7877, 07B (0197)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 06 (décembre 1996) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint-Laurent, Contrat AVMSL No. 14-697 Contract HQ No. 08200-96-LAB-005-00	1997-01-31	
23	RG52 / R1195	2018-00304-6	2	B7877, 08B (0397)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 07 (janvier 1997) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint-Laurent, Contrat AVMSL No. 14-697 Contract HQ No. 08200-96-LAB-005-00	1997-03-31	
24	RG52 / R1195	2018-00304-6	2	B7877, 09B (0397)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 08 (février 1997) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint-Laurent, Contrat AVMSL No. 14-697 Contract HQ No. 08200-96-LAB-005-00	1997-03-31	

isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
25	RG52 / R1195	2018-00304-6	2	B7877, 10B (0697)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 09 (mars 1997) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint-Laurent, Contrat AVMSL No. 14-697 Contract HQ No. 08200-96-LAB-005-00	1997-04-30	
26	RG52 / R1195	2018-00304-6	2	B7877, 11B (0697)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 10 (mars 1997) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint-Laurent, Contrat AVMSL No. 14-697 Contract HQ No. 08200-96-LAB-005-00	1997-06-30	
27	RG52 / R1195	2018-00304-6	2	B7877, 13B (0797)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 11 (mai 1997) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint-Laurent, Contrat AVMSL No. 14-697 Contract HQ No. 08200-96-LAB-005-00	1997-07-31	
28	RG52 / R1195	2018-00304-6	2	B7877, 14B (0797)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 12 (juin 1997) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint-Laurent, Contrat AVMSL No. 14-697 Contract HQ No. 08200-96-LAB-005-00	1997-07-31	
29	RG52 / R1195	2018-00304-6	2	B7877, 15B (0897)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 13 (juillet 1997) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint-Laurent, Contrat AVMSL No. 14-697 Contract HQ No. 08200-96-LAB-005-00	1997-08-31	
30	RG52 / R1195	2018-00304-6	2	B7877, 16B (0198)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 14 (août 1997) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint-Laurent, Contrat AVMSL No. 14-697 Contract HQ No. 08200-96-LAB-005-00	1998-01-30	
31	RG52 / R1195	2018-00304-6	2	B7877, 17B (0198)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 15 (septembre 1997) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint- Laurent, Contrat AVMSL No. 14-697 Contract HQ No. 08200-96-LAB-005-00	1998-01-30	
32	RG52 / R1195	2018-00304-6	2	B7877, 18B (0198)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 16 (octobre 1997) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint-Laurent, Contrat AVMSL No. 14-697 Contract HQ No. 08200-96-LAB-005-00	1998-01-30	
33	RG52 / R1195	2018-00304-6	2	B7877, 19B (0198)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 17 (novembre 1997) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint- Laurent, Contrat AVMSL No. 14-697 Contract HQ No. 08200-96-LAB-005-00	1998-01-30	

isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
34	RG52 / R1195	2018-00304-6	2	B7877, 20B (0198)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 18 (décembre 1997) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint-Laurent, Contrat AVMSL No. 14-697 Contract HQ No. 08200-96-LAB-005-00	1998-01-30	
35	RG52 / R1195	2018-00304-6	2	B7877, 21B (0298)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 19 (novembre 1997) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint-Laurent, Contrat AVMSL No. 14-697 Contract HQ No. 08200-96-LAB-005-00	1998-02-28	
36	RG52 / R1195	2018-00304-6	2	B7877, 23B (0398)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 20 (février 1998) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint-Laurent, Contrat AVMSL No. 14-697 Contract HQ No. 08200-96-LAB-005-00	1998-03-31	
37	RG52 / R1195	2018-00304-6	2	B7877, 24B (0498)	Groupe Qualitas/Laboratoire de Béton Ltée : Rapport mensuel 21 (mars 1998) Instrumentation à l'écluse de Saint-Lambert voie maritime du Saint-Laurent, Contrat AVMSL No. 14-697	1998-04-30	
38	RG52 / R1195	2018-00304-6	3	219/76	L.A. Perrigo, Marine Consultant Hull & Engine Surveyor : Survey Report M/T "Annette" Alleged Damage Sustained in St. Lawrence Seaway, October 23, 1976	1976-11-22	
39	RG52 / R1195	2018-00304-6	3		SLSA/O. Brunet, A. Gagnon, Florian Landry, R. St. Denis, Albert Roussel, J.A. Roger, J. Brossard, Robert Beauchemin, Mario Vachon, Jacques Lebrun : Board of Investigation Report Re: "Aegis Faith" Accident St. Lambert Lock, October 6, 1973	1973-10-26	
40	RG52 / R1195	2018-00304-6	3		SLSA/R. Corfe, D. Mullings & A. Proszanski : Investigation Into Sinking of "VM/S St. Lambert"	1987-04-18	
41	RG52 / R1195	2018-00304-6	3		SLSA/J.M. Kroon, E. Ahermae, H.L. Koski & B.N. Gravelle : Investigation Into the Accident Involving the Vessel "Steelton" & Bridge 12 on August 25, 1974	1974-09-04	
42	RG52 / R1195	2018-00304-6	3	CPO5	SLSA/P.T. Jenkins, C.G. Trepanier & A. Proszanski : Investigation Into the Accident of July 21, 1980 Involving St. Louis Bridge & LawrenceCliffe Hall	1980-07-21	
43	RG52 / R1195	2018-00304-6	3	W1-309, 28-19-1- 1/4	SLSA/Geo H. Hallett & A. Juster : 1993 Inspection Report Bridge No. 4 Bascule Lift Portions Queenston Road, St. Catharines Niagara Region	1993-02-28	
44	RG52 / R1195	2018-00304-6	3	W1-309, 28-19-1- 1/4	SLSA/M. Bowden & B. Azzeh : 1994 Inspection Report Bridge No. 4 Bascule Portions, Queenston Road, St. Catharines Niagara Region	1994-12-31	
45	RG52 / R1195	2018-00304-6	3	W1-309, 28-19-1- 1/4	SLSA/M. Bowden & B. Azzeh : 1994 Inspection Report Bridge No. 4 Fixed Approach Spans Niagara Region	1994-10-31	
46	RG52 / R1195	2018-00304-6	3		SLSA & GLPA/Camille Trépanier, Pat Vincelli, Harley Smith, Jean-Paul Bernier, Carol Fenton, Bob Killick & Anil Soni/Captains D. Trottier, G. Belley & Don Langlois : Transit Time Standards Reference Guide	1995-09-30	

isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
47	RG52 / R1195	2018-00304-6	3	202	SLSA/J.B. McLeod : A Brief on Imtic & Its Potential for the Marine Industry (for District #1 Pilots)	1972-09-12	
48	RG52 / R1195	2018-00304-6	3	DOT-TSC-SLS-72-1	U.S. Department of Transportation, Transportation Systems Center/Robert D. Reymond & Eugene V. Fesler : Fourth Coast - Seaway Systems Requirements Analysis, the Role of an Integrated Marine Traffic Information & Control System, Volume 1 Summary Report	1972-03-24	
49	RG52 / R1195	2018-00304-6	3		SLSA/J.B. McLeod : Un exposé sur le système Imtic et son potentiel pour la marine, pour délibération durant une assemblée des pilotes du district de Cornwall et du district No. 1	1972-09-12	
50	RG52 / R1195	2018-00304-6	3		SLSA : Operational Monitoring	1978-12-31	
51	RG52 / R1195	2018-00304-6	3		SLSA : The St. Lawrence Seaway Authority Lower Beauharnois Lock Lockage Procedure Centralized Control Operation	1966-02-17	
52	RG52 / R1195	2018-00304-6	3		SLSA : The St. Lawrence Seaway Authority Upper Beauharnois Lock Lockage Procedure Centralized Control Operation	1966-02-17	
53	RG52 / R1195	2018-00304-6	3	60-14-1-7, Project E1-210	SLSA/M. Liou : Emergency Mooring Iroquois Lock	1976-02-12	
54	RG52 / R1195	2018-00304-6	3		SLSA/N. Hill : Notes on the Design of Lock Control Rooms	1979-04-30	
55	RG52 / R1195	2018-00304-6	3	60-18-2-10/76	SLSA : Report on Closing of Navigation 1976 Season Welland Canal Western Region	1977-02-08	
56	RG52 / R1195	2018-00304-6	3		SLSA : Report on Closing of Navigation 1985 Season Welland Canal Western Region	1986-03-12	
57	RG52 / R1195	2018-00304-6	3		SLSA/J.P. Thomas, W.E. Webb, G. Hotte & E. Noble : Annual Data for Extension to Navigation Season Studies Closing of 1970	1970-11-30	
58	RG52 / R1195	2018-00304-6	3	60-3-4-1	SLSA/Jean F. Pilon, G. Hotte & G.J. McDonnell : Annual Data for Extension to Navigation Season Studies Opening of 1969	1969-03-13	
59	RG52 / R1195	2018-00304-6	3		SLSA/C.J. Mallette & G.J. McDonnell : Annual Data Eastern Region Closing of 1969 Navigation Season	1969-11-30	
60	RG52 / R1195	2018-00304-6	3	16	SLSA/W.E. Webb : Navigation Season Extension Opening Period 1973	1974-01-31	
61	RG52 / R1195	2018-00304-6	3		SLSA : Defining of & Recording Procedure for Single Lock Log Records	1977-05-31	
62	RG52 / R1195	2018-00304-6	3	Interim Report No. 2	Parker Consultants : Connecting Road Network for Third Bridge Crossing of Welland Canal in the City of Port Colborne Preliminary Design	1979-01-19	
63	RG52 / R1195	2018-00304-6	3		Lalonde, Girouard, Letendre & Associés Ltée : Ministère des Transports Évaluation des répercussions environnementales de l'installation d'ilots artificiels dans le Lac Saint-Louis	1980-02-05	

isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
64	RG52 / R1195	2018-00304-6	3		Groupe Conseil Polytec Inc./Robert Demers : Proposition d'étude évaluation des impacts suite à l'installation d'ilots artificiels sur le Lac Saint-Louis	1980-02-11	
65	RG52 / R1195	2018-00304-6	3	29-4-4-3, 29-3-4-3, Project E2-0010	SLSA/J.G. Vazalinskas : Eastern Region Compressed Air System St-Lambert & Cote Ste-Catherine Locks	1970-08-27	
66	RG52 / R1195	2018-00304-6	3		SLSA/Operational Services : Remote Operation of Bridge 5 Niagara Region Operational Feasibility	1997-05-02	
67	RG52 / R1195	2018-00304-6	3	Project E1-116	SLSA/B.K. Stinson : Desynchronized Operation of Beauharnois Locks Vessel Entry Into Upper Beauharnois Lock During Fills of Lower Beauharnois Lock	1972-07-31	
68	RG52 / R1195	2018-00304-6	3		SLSA/Wayne A. Dawson : Design Specification Operational Data Analysis (ODA) System, Operational Monitoring Subsystem	1980-12-11	
69	RG52 / R1195	2018-00304-6	3		SLSA : Besoin Opérationnel Écluse 3 Région Maisonneuve	1991-12-06	
70	RG52 / R1195	2018-00304-6	3		SLSA : Third Bridge Crossing Port Colborne	1981-04-30	
71	RG52 / R1195	2018-00304-6	3	W1-309, 28-19-1- 1/4	SLSA/Geo H. Hallett & B. Azzeh : (1993) Inspection Report Bridge No. 4 Fixed Approach Spans Only Niagara Region	1993-05-31	
72	RG52 / R1195	2018-00304-6	3		SLSA/Voir document pour multiple auteurs : Rapport Final Les normes relatives au temps de transit pour les sections Montréal - Lac Ontario Canal Welland	1995-12-29	
73	RG52 / R1195	2018-00304-6	3		SLSA : Bridge No. 4 Bascule Lift Portion Appendix III Photographs	1992-02-12	1992-10-28
74	RG52 / R1195	2018-00304-6	3		SLSA/Secretary & Director of Administration : Organization - Acts & Directives Seaway Act	1961-02-01	1962-06-30
75	RG52 / R1195	2018-00304-6	3		SLSA : Sinking of C.C.G.S. "Grenville" Photographs Only	1968-12-18	
76	RG52 / R1195	2018-00304-6	3		SLSA : Photos December 19, 1978 Ice Conditions-Beauharnois Canal Photos Taken Between 12:00-13:00 Hours, Baie St. Paul Incident	1978-12-20	
77	RG52 / R1195	2018-00304-6	3	60/5054	SLSA : Collision Between the "Calgadoc" & the "Ioannis S"	1974-10-28	
78	RG52 / R1195	2018-00304-6	3		SLSA : Bridge 6 Welland Canal Niagara Region (Photos Only)	1971-11-04	
79	RG52 / R1195	2018-00304-6	4	60-25-4-12	SLSA : Ice Conditions Beauharnois Canal	1981-01-01	1983-03-31
80	RG52 / R1195	2018-00304-6	4	60-25-4-12	SLSA : Ice Conditions Beauharnois Canal	1983-04-01	1985-03-31
81	RG52 / R1195	2018-00304-6	4	60-25-4-12	SLSA : Ice Conditions Beauharnois Canal	1985-04-01	1987-12-31

isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
82	RG52 / R1195	2018-00304-6	4	60-25-4-12	SLSA : Ice Conditions Beauharnois Canal	1987-04-01	1989-12-31
83	RG52 / R1195	2018-00304-6	4	15	SLSA/The St. Lawrence Seaway Authority Committee : Navigation Season Extension Appendix 7 to Report No. 15 Closing Period 1972	1972-12-31	
84	RG52 / R1195	2018-00304-6	4	14	SLSA/The St. Lawrence Seaway Authority Committee : Navigation Season Extension Appendix to Report No. 14 Opening Period 1972	1972-03-31	
85	RG52 / R1195	2018-00304-6	4	13	SLSA/The St. Lawrence Seaway Authority Committee : Navigation Season Extension Appendix to Report No. 13 Close-Up Period 1971	1971-12-31	
86	RG52 / R1195	2018-00304-6	4	12	SLSA/The St. Lawrence Seaway Authority Committee : Navigation Season Extension Appendix to Report No. 12 Opening Period 1971	1971-03-31	
87	RG52 / R1195	2018-00304-6	4		SLSA : Annual Date for Extension to Navigation Season Studies Opening of 1970	1970-03-31	
88	RG52 / R1195	2018-00304-6	4	W3-014, 28-19-1- 1/4	SLSA/B. Azzeh : Report on Load Evaluation of Bridge No. 4 (Bascule Section) (1995) Niagara Region, Part 1 of 2	1995-06-09	
89	RG52 / R1195	2018-00304-6	4	W3-014, 28-19-1- 1/4	SLSA/B. Azzeh : Report on Load Evaluation of Bridge No. 4 (Bascule Section) (1995) Niagara Region, Part 2 of 2	1995-06-09	
90	RG52 / R1195	2018-00304-6	4	54-50-5-3	SLSA/Transit Time Standards Task Force : Transit Time Standards for Montrel-Lake Ontario Welland Canal	1995-12-31	
91	RG52 / R1195	2018-00304-6	4		SLSA : Collision Between the "Helen Evans" & "Lake Winnipeg" South Shore Canal, July 5, 1977	1977-07-07	
92	RG52 / R1195	2018-00304-6	4	14-631-1	Colt Engineering (Ontario) Corporation : St. Lawrence Seaway Authority Lock 1 Installation Recommendations	1992-04-30	
93	RG52 / R1195	2018-00304-6	4	2754/JFW/92/jfw	Peat Marwick Stevenson & Kellogg : L'avenir du transport des marchandises non conteneurisées dans le système du Saint-Laurent	1993-04-21	
94	RG52 / R1195	2018-00304-6	4	R-86-01-1	Techno Scientific Inc./M. Macecek & D. Mowder : Ultrasonic Survey of Concrete in Monolith #9 West Lock 7 & Lock 5 for Cracks & Irregularities	1986-01-01	
95	RG52 / R1195	2018-00304-6	4	Contract #14-521	Vibron Limited/Bob Rimrott & Brian Howe : Establishing First Natural Frequencies of Welland Canal Bridges 1, 4 & 5 Western Region	1989-07-25	
96	RG52 / R1195	2018-00304-6	4	817011, Contract 14- 345	MHBH Timber Engineering & Wood Technology Division : Investigation of Timber Unwatering Gates Lock No. 8 - Welland Canal	1981-02-16	
97	RG52 / R1195	2018-00304-6	4		Brock University Centre for Social & Economic Research on Niagara : Economic Impact of the Marine Industry on the Niagara Region	1997-01-01	
98	RG52 / R1195	2018-00304-6	5	28-19-1-1	SLSA/H.L. Ferguson : Report on Removal of Bridge 12, Welland Canal with Particular Reference to the Removal Procedures & Timing of the Different Phases of the Work	1974-10-25	
99	RG52 / R1195	2018-00304-6	5	43-4-7-1	SLSA : Preliminary Review of Subsurface Conditions Lock 3 Area (Bridge 4 to Bridge 5) Welland Canal	N/A	

isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
100	RG52 / R1195	2018-00304-6	5	28-19-1-1-10	SLSA/E. Ahermae : Report on Non-destructive Testing of Counterweight Ropes on Vertical Life Bridge 10	1969-02-20	
101	RG52 / R1195	2018-00304-6	5	60-18-1-1	SLSA/M. Liou : Ships Transiting on Ice	1978-02-28	
102	RG52 / R1195	2018-00304-6	5	IR 67-9, Copy 12	Department of Energy, Mines & Resources/D.E. Parsons & D.A. Munro : Examination of Rimmed Steel Ship Plate Samples from Five Bulk Carriers Built 1905-1926	1967-05-05	
103	RG52 / R1195	2018-00304-6	5		SLSA/Operations Branch, Port Weller : A Review of Bridge 6 Rehabilitation & Remote Control	1971-12-31	
104	RG52 / R1195	2018-00304-6	5		SLSA/F.L. Reynolds : Report on Vessel Speed & Wave Study Thousand Islands Section - St. Lawrence River	1974-04-30	
105	RG52 / R1195	2018-00304-6	5		SLSA/Operations Branch : Report on Vessel Speed & Wave Study Beauharnois Canal Section of the St. Lawrence Seaway	1971-11-29	
106	RG52 / R1195	2018-00304-6	5		SLSA/Operations Branch : Report on Vessel Speed & Wave Study Welland By-Pass Channel Welland Canal	1974-02-28	
107	RG52 / R1195	2018-00304-6	5		SLSA/Operations Branch : Report on Vessel Speed & Wave Study Lake St. Francis Section of the St. Lawrence Seaway	1971-07-02	
108	RG52 / R1195	2018-00304-6	5		SLSA/Operations Branch : Report on Vessel Speed & Wave Study Lake St. Francis Entrance to Beauharnois Canal	1972-10-31	
109	RG52 / R1195	2018-00304-6	5		SLSA/Operations Branch : Report on Vessel Speed & Wave Study Carried Out Along the Southeast Section of Lake St. Louis Phase 1	1973-09-30	
110	RG52 / R1195	2018-00304-6	5	60-48-1-1	SLSA/M. Liou & W.E. Webb : The Selection of Criteria for Vessels Transiting in Ice, Appendix 1	1978-03-17	
111	RG52 / R1195	2018-00304-6	5		Transport Canada : Symposium "Managing Marine Pollution The Transportation Challenge"	1974-11-05	1974-11-06
112	RG52 / R1195	2018-00304-6	5	31/32/33 C-56 & 28-19-1-1-15	SLSA : Welland Canal Bridge No. 15 Various Photos Only	1956-03-19	1966-05-31
113	RG52 / R1195	2018-00304-6	5		SLSDC, New York : Final Environmental Statement Improved Navigation Saint Lawrence Seaway South Cornwall Channel (Polly's Gut)	1976-08-31	
114	RG52 / R1195	2018-00304-6	5		SLSA/M.S. Campbell & F.E. Jackson : Newspaper Clippings Port Robinson Bridge Accident & Other	1974-12-31	
115	RG52 / R1195	2018-00304-6	5		SLSA : Electrical Brief Bridge 3A Operation Lock 2 Welland Canal	1970-04-29	
116	RG52 / R1195	2018-00304-6	5		SLSA/Multiple : Commissions, Boards. Committees - Great Lakes Commission Reference Material	1993-05-01	1993-07-31
117	RG52 / R1195	2018-00304-6	5		SLSA/Multiple : Équipe Qualité du Service études et recommandations	1993-09-28	
118	RG52 / R1195	2018-00304-6	5		SLSA : Report on Expansion of St. Lawrence Seaway Facilities Volume 3 Montreal - Lake Ontario Section	1969-04-30	



isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
119	RG52 / R1195	2018-00304-6	5		SLSA/Multiple : Vision 2002 Report on How to Improve the Seaway's Market Share	1993-10-01	
120	RG52 / R1195	2018-00304-6	5	1-23-1-1	SLSA/A.A. Khan : Energy Consumption & Conversation in Eastern Region	1978-02-01	
121	RG52 / R1195	2018-00304-6	5		SLSA,Dept. of Transportation, Washington, External Affairs & Dept. of Justice Ottawa, Dept. of Fisheries, Canada Centre for Inland, Transport Canada, Corps of Eng. : Minutes of Meeting Extension to Navigation Season Great Lakes Ottawa	1971-01-21	
122	RG52 / R1195	2018-00304-6	5		Department of Highways, Planning Division : Recommendations on The Operation of a Full Traffic-Actuated Three Phase Control Systems on Hwy. #3 & Hwy. #58. Port Colborne	1958-07-31	
123	RG52 / R1195	2018-00304-6	5	IR 58-153, Copy 1	Department of Mines & Technical Surveys/D.R. Bell : Investigation of Fracture of 30 in. Wide Flange I-Beam from Welland Canal Bridge No. 18	1958-10-14	
124	RG52 / R1195	2018-00304-6	5	28-19-1-1/38, Doc. #5196	SLSA/Mike Whittington & Burhan Azzeq : Peter Street Bridge	1992-05-01	
125	RG52 / R1195	2018-00304-6	5		SLSA/D. Kwan : Study of Side Slope for Channel Widening North of Bridge 15 West Bsnk, W.S.C.	1966-12-01	
126	RG52 / R1195	2018-00304-6	5	28-19-1-1/38, W2-516	SLSA/B. Azzeq : Evaluation of Load Carrying Capacity of Peter Street Bridge	1992-12-11	
127	RG52 / R1195	2018-00304-6	6		SLSA : Great Lakes - St. Lawrence Seaway Navigation Season Extension Program	1978-08-07	
128	RG52 / R1195	2018-00304-6	6		SLSA : The St. Lawrence Seaway Authority Special Examination Bridge Inspection in Subsidiary Companies Inspection Improvement Program	1989-07-11	
129	RG52 / R1195	2018-00304-6	6	6645-02, 28-19-2-1/19A	M.M. Dillon Limited : Highway 3 Port Colborne Report on the Availability of Bicycle Access Across the Welland Canal	1975-01-31	
130	RG52 / R1195	2018-00304-6	6	28-1-21-1, Project E1-224	SLSA/E. Sutt : 1987 Inspection of Selected Eastern Region Bridges Nos 5, 9 & 10	1988-05-31	
131	RG52 / R1195	2018-00304-6	6		The Canadian Crocker-Wheeler Co., Limited : Electrical Equipment for Operating Bascule Bridges No 1, 3, 7 & 19 for Department of Railways & Canals	1925-08-20	
132	RG52 / R1195	2018-00304-6	6	W4-623	SLSA/C.T. Kwan : Study on the Stability of the Canal Road Bin Wall at Peter St. Bridge, Lock 7	1991-11-22	
133	RG52 / R1195	2018-00304-6	6	4050-115	Ralph B. Peck : Report on Stability Conditions West Abutment of Welland Drawbridge Canadian Main Line New York Central System	1957-02-07	
134	RG52 / R1195	2018-00304-6	6		SLSA/C.J. Christensen : Foundation Investigation for Proposed Bascule Bridge at Lock No. 8 Welland Canal Port Colborne, Ontario, Supplementary Report No. 1	1979-03-27	

isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
135	RG52 / R1195	2018-00304-6	6		Ecoplans : Tree Inventory & Evaluation for Port Colborne Approach Road Study	1978-12-31	
136	RG52 / R1195	2018-00304-6	6	H2671	The Trow Group Limited : Approach Roads to The New Welland Canal Lift Bridge Port Colborne Ontario	1979-01-17	
137	RG52 / R1195	2018-00304-6	6		Parker Consultants : Connecting Road Network for Third Bridge Crossing of Welland Canal in the City of Port Colborne Interim Report No. 3 Functional Requirements Signs and Signals	1979-03-23	
138	RG52 / R1195	2018-00304-6	6		Multiple Authors, Major P.J. Cowan in Collaboration with Dept. of Railways : The Opening of the Welland Ship Ship Canal, A Canadian Conception & Achievement & The Welland Ship Canal Between Lake Ontario and Lake Erie	1913-01-01	1932-08-06
139	RG52 / R1195	2018-00304-6	6	28-1-21-1	SLSA/E. Sutt : Inspection of Eastern Region Vertical Lift Bridges & Fixed Approach Spans Nos 2, 3, 7A, 7B, 9 & 10	1977-01-01	1978-12-31
140	RG52 / R1195	2018-00304-6	6	28-19-1-1-38	SLSA/H. Debicki : Review of Study Covering Rehabilitation of Concrete Spans West Approach Bridge 7, Welland Canal	1986-07-12	
141	RG52 / R1195	2018-00304-6	6	60-14-1-7	SLSA/P. Vincelli, J.M. Kroon, Jones, M. Liou & J.B. Lachapelle : Iroquois Lock, Walk-Through Procedure	1976-05-01	2000-05-31
142	RG52 / R1195	2018-00304-6	6	60-14-1-7	SLSA/P. Vincelli, J.M. Kroon, C.G. Trepanier, C.J. McDonnell, T.J. Quigg, E.J. Rossi, etc... : Documentation Walk-Through Procedure Iroquois Lock	1976-05-09	1976-11-09
143	RG52 / R1195	2018-00304-6	6	29-8-4-2	SLSA/W. Dawson, E.R. Smith, B.K. Stinson, S. Gerlovin, J.M. Kroon : Studies of Iroquois Walk-Through Procedure Earlier Opening of Sector Gates	1972-10-01	1972-11-30
144	RG52 / R1195	2018-00304-6	6		Larry Boland : Report on the Abolishment of Bridge Operators Working on Bridge #20 Welland Canal Section	1993-07-06	
145	RG52 / R1195	2018-00304-6	6		SLSA : The St. Lawrence Seaway Authority Vertical Lift Bridges Sequence of Operation	1962-09-30	
146	RG52 / R1195	2018-00304-6	6		G.W. English & Associates/G.W. English & C. Schwier : Additional Evaluation of Alternatives to the Railway Bridges 10 & 20 on the Welland Canal Final Report	1995-08-31	
147	RG52 / R1195	2018-00304-6	6		SLSA/Operations, Economics & Research Branch : Welland Canal Closing of Bridges 19 & 21 to Navigation for Three Fixed Periods on Working Days Report	1973-08-31	
148	RG52 / R1195	2018-00304-6	6		H. G. Acres Company Limited Consulting Engineers : Thorold Tunnel Feasibility Report Appendix B	1965-02-26	
149	RG52 / R1195	2018-00304-6	6	28-19-3-1, W1-277	SLSA/E. Sutt : 1986 Inspection of Western Region Bridges Nos. 20 & 21	1986-08-22	

isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
150	RG52 / R1195	2018-00304-6	6		SLSA, Ministry of Transport, SLSDC, Buffalo District Corps of Engineers, U.S. Coast Guard : Vessel Speed & Wave Study International Section of the St. Lawrence Seaway	1970-05-01	
151	RG52 / R1195	2018-00304-6	6	33-9-9-2, E5-204E	SLSA (Geotechnical Section)/K. Olpinski : Bank Rehabilitation & Erosion Repairs St. Lambert - S.E.R.	1972-11-30	
152	RG52 / R1195	2018-00304-6	6	33-9-9-1, E1-118	SLSA (Geotechnical Section)/K. Olpinski : Inspection of Canal Banks Upstream of St. Lambert Lock S.E.R.	1973-01-31	
153	RG52 / R1195	2018-00304-6	6	33-1-9-1, E1-070	SLSA (Soil & Foundations Section)/K. Olpinski : Protection Wall Repairs Downstream of La Tortue River Eastern Region	1970-10-31	
154	RG52 / R1195	2018-00304-6	6	33-9-9-2, E5-173	SLSA (Geotechnical Section)/K. Olpinski : Report on North Dyke Inspection (1974) Above Cote Ste Catherine Lock, S.E.R.	1974-08-31	
155	RG52 / R1195	2018-00304-6	6	33-9-9-2, E1-173	SLSA (Geotechnical Section)/K. Olpinski : Report on Surveys of Repairs to Dykes Below St. Lambert Lock, S.E.R.	1974-07-31	
156	RG52 / R1195	2018-00304-6	6	91-10915	The N.D.E. Service Group, Inc./B. Miller : Bridge #1, Lake Shore Road, Welland Ship Canal, Condition Survey Including Non-Destructive Testing for the Segmental & Track Girders	1991-12-21	
157	RG52 / R1195	2018-00304-6	6		Transport Canada Highway Branch/Y. Malépart : Federal Involvement in Highway Bridges/Tunnels Proposal for a Policy Review	1986-04-30	
158	RG52 / R1195	2018-00304-6	6	CG-129, Vol 18, No. 9	United States Coast Guard : Proceedings of the Merchant Marine Council	1961-09-30	
159	RG52 / R1195	2018-00304-6	6	14-225	De Leuw Cather & Co. of Canada Limited : Welland Channel Relocation Regional Road #8A Bridge	1969-06-01	1969-08-31
160	RG52 / R1195	2018-00304-6	6	33-9-9-2, E1-287	SLSA/G.H.K. Hallett : Banks & Dykes South Shore Canal 1983 Inspection Report	1983-12-31	
161	RG52 / R1195	2018-00304-6	6		Observers: SLSA, International Joint Commission US, US Dept of State, Technical Advisors: National Aeronautics & Space Administration, Energy Research & Development, Advisory Group Industry/Labor/Consumers/Concerned Citizens : Great Lakes - St. Lawrence Seaway Navigation Season Extension Program	1979-08-06	
162	RG52 / R1195	2018-00304-6	6	28-19-1-1/19, W3-005	SLSA/Geo H. Hallett & B. Azzeh : The St. Lawrence Seaway Authority Engineering Services Inspection Report Bridge No. 19 Port Colborne Niagara Region	1993-09-30	
163	RG52 / R1195	2018-00304-6	6	33-1-3-10, E1-283	SLSA/A. Proszanski : Setting of Machinery Brakes, S.E.R.	1981-12-08	
164	RG52 / R1195	2018-00304-6	6		Transport Québec : Toward a Transportation Plan for the Montréal Region Phase 1: Choices Existing Situation & Possible Orientations Consultation Document	1995-01-01	
165	RG52 / R1195	2018-00304-6	6		Transport Québec/Service des relations publiques : Bilan des activités salle de presse Transport Québec Région de Montréal Été 1989	1989-11-30	

isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
166	RG52 / R1195	2018-00304-6	6	56398	Ministère des Transports, Gouvernement du Québec : Refection Autoroute 20 plan préliminaire de transport/circulation, rév. 2	1989-01-18	
167	RG52 / R1195	2018-00304-6	6		Grande Région de Montréal, plan d'action 1988-98 : Comité de coordination régionale en transport (Comcret)	1989-02-24	
168	RG52 / R1195	2018-00304-6	6		Ministère des Transports, Gouvernement du Québec/Loris Piccin & Robert Dupont : Pont H. Mercier Analyse signalisation et circulation lord des travaux de 1989	1989-10-30	
169	RG52 / R1195	2018-00304-6	6	56398	Sous comité d'étude de circulation/Réjean L'Italien, Kinh S. Mach et Michel Parent : Project d'aménagement temporaire du boulevard Gauron en vue des travaux de réfection de l'Autoroute 20	1988-11-29	
170	RG52 / R1195	2018-00304-6	6		Gouvernement du Québec, Ministère des Transports : Le Transport dans la région de Montréal plan d'action 1988-98 Programmation des travaux sur le réseau routier (révisé)	1988-12-07	
171	RG52 / R1195	2018-00304-6	7	ISBN: 2-550-24343-9	Gouvernement du Québec, Ministère des Transports : Vers un plan de transport pour la région de Montréal Phase 1: Choisir Diagnostic et Orientations Document de Consultation	1995-12-29	
172	RG52 / R1195	2018-00304-6	7	ISBN: 2-550-24485-0	Gouvernement du Québec, Ministère des Transports : Vers un plan de transport pour la région de Montréal Cadre Institutionnel et Financier du Transport des Personnes Proposition Ministérielle	1995-12-29	
173	RG52 / R1195	2018-00304-6	7	ISBN: 2-550-24345-5	Gouvernement du Québec, Ministère des Transports : Vers un plan de transport pour la région de Montréal Programme d'intervention 1995 et 1996	1995-12-29	
174	RG52 / R1195	2018-00304-6	7	ISBN: 2-550-25109-1	Gouvernement du Québec, Ministère des Transports : Vers un plan de transport pour la région de Montréal Analyse Techniques du Systèmes de Transport en Commun Rapport Synthèse des Résultats fournis : fournis par les Mandataires	1995-12-29	
175	RG52 / R1195	2018-00304-6	7	ISBN: 2-550-24346-3	Gouvernement du Québec, Ministère des Transports : Vers un plan de transport pour la région de Montréal Phase 1: Choisir Diagnostic et Orientations Document de Référence	1995-12-29	
176	RG52 / R1195	2018-00304-6	7	28-18-21-1, E3-005	SLSA/Geo H. Hallett & A.P. Juster : Inspection Report Bridge No. 18 North Viaduct Victoria Approach St. Lambert Lock Maisonneuve Region	1993-05-31	
177	RG52 / R1195	2018-00304-6	7	28-19-21-1, E1-349	SLSA/Geo H. Hallett & A.P. Juster : Inspection Report Bridge #19 Weir Bridge Cote Ste-Catherine Maisonneuve Region	1992-09-30	
178	RG52 / R1195	2018-00304-6	7	28-20-21-1	SLSA/Geo H. Hallett & A.P. Juster : Inspection Report Spillway Chute Bridge No. 20 Regulating Works Lower Beauharnois Maisonneuve Region	1993-12-31	
179	RG52 / R1195	2018-00304-6	7	28-5318-21-1	SLSA/Sylvain Martin et Marie-Hélène Grenier : Rapport d'inspection Pont No 18 Viaduc Victoria Nord St-Lambert Région Maisonneuve	1995-08-31	

isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
180	RG52 / R1195	2018-00304-6	7	31-3-3-1	International St Lawrence River Board of Control : Lake Ontario - St Lawrence River Regulation Plan Evaluation: Summary of Board Rankings of Plans	1997-04-15	
181	RG52 / R1195	2018-00304-6	7	28-3-16-1, E4-103D	SLSA/J. Godin : St-Lambert Lock - Vehicular Traffic Report on Modification to Roadway Traffic Control Equipment Victoria Bridge	1971-03-17	
182	RG52 / R1195	2018-00304-6	7		SLSA : Welland Ship Canal Operating Instructions for Vertical Lift Bridges	1950-06-16	
183	RG52 / R1195	2018-00304-6	7	28-8-21-1	SLSA/Geo H. Hallett & E. Sutt : Inspection Report Bridge #9 Saint Louis-De-Gonzague Lift & Tower Spans Maisonneuve Region (Draft)	1992-06-30	
184	RG52 / R1195	2018-00304-6	7		CIMA et Hydro Québec/Francois Plourde : Appel d'offres Pont Laroque - Valleyfield, Québec Réfection des piliers Phase II Devis Technique	1992-03-31	
185	RG52 / R1195	2018-00304-6	7		SLSA/Fabien Laforest, Denis Vézina et Alain Chamberland : Pont Laroque à Valleyfield Suivi du comportement des tours (piliers 6, 7, 8 et 9)	1994-03-31	
186	RG52 / R1195	2018-00304-6	7		Lalonde Valois Lamarre Valois et Associés : Refection aux piliers #7 et #8 des Ponts Laroque et St-Louis à Valleyfield & St-Louis de Gonzague/Repair Work at Piers #7 & #8 of Laroque & St. Louis Bridges at Valleyfield & St. Louis de Gonzague	1974-06-30	
187	RG52 / R1195	2018-00304-6	7		Auteurs Multiple/Multiple Authors : Pont 10 Valleyfield, Bridge 10 Valleyfield	1989-04-26	
188	RG52 / R1195	2018-00304-6	7		Alta Limitée : Ponts construits par Alta Limitée jusqu'en 1990	1990-12-31	
189	RG52 / R1195	2018-00304-6	7		Valorex Inc. : Hydro-Québec Direction Réfections et Modifications de Centrales Analyse de la Valeur Pont Larocque	1991-09-30	
190	RG52 / R1195	2018-00304-6	7		SLSA/Alain Chamberland : Rapport Mensuel de Gestion de Projets, Réfection du Pont Larocque	1993-06-30	
191	RG52 / R1195	2018-00304-6	7		SLSA/Alain Chamberland : Rapport Mensuel de Gestion de Projets, Réfection du Pont Larocque	1993-07-31	
192	RG52 / R1195	2018-00304-6	7		SLSA/Alain Chamberland : Rapport Mensuel de Gestion de Projets, Réfection du Pont Larocque	1993-08-31	
193	RG52 / R1195	2018-00304-6	7		SLSA/Alain Chamberland : Rapport Mensuel de Gestion de Projets, Réfection du Pont Larocque	1993-09-30	
194	RG52 / R1195	2018-00304-6	7		SLSA/Alain Chamberland : Rapport Mensuel de Gestion de Projets, Réfection du Pont Larocque	1993-11-30	
195	RG52 / R1195	2018-00304-6	7		SLSA/Alain Chamberland : Rapport Mensuel de Gestion de Projets, Réfection du Pont Larocque	1993-12-31	
196	RG52 / R1195	2018-00304-6	7		SLSA/Alain Chamberland : Rapport Mensuel de Gestion de Projets, Réfection du Pont Larocque	1994-01-31	

isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
197	RG52 / R1195	2018-00304-6	7		SLSA/Alain Chamberland : Rapport Mensuel de Gestion de Projets, Réfection du Pont Larocque	1994-02-28	1991-03-31
198	RG52 / R1195	2018-00304-6	7	108-1634	SLSA/Jacquelin Marceau : Pont Larocque, Réfection (coûts résidentiels)	1994-05-17	
199	RG52 / R1195	2018-00304-6	7	28-9-7-12	SLSA/K. Olpinski : Valleyfield Bridge Beauharnois Canal S.E.R. Inspection of Cell Damaged by "John O. McKellar"	1972-07-20	
200	RG52 / R1195	2018-00304-6	7		SLSA : Photos Pond D Bridge, Niagara Region	1989-12-31	
201	RG52 / R1195	2018-00304-6	7		Operations Advisory Group : Minutes & River Board Correspondence	1993-01-01	1993-12-31
202	RG52 / R1195	2018-00304-6	7	Contract: PC-101	Penn Central Transportation Company, C.E. Defendorf, Chief Engineer : Specifications for Track Work & Grading R-S Line & John Deere Welland Works at Niagara Falls & Welland, Ontario	1971-01-15	
203	RG52 / R1195	2018-00304-6	7	Contract: THB-102	Toronto, Hamilton & Buffalo Railway Co./I.N. Wigle, Chief Engineer : Specifications for Construction of Railroad Subgrade, Bridge Structure & Drainage O-P Line at Pelham & Wainfleet, Ontario	1971-03-15	
204	RG52 / R1195	2018-00304-6	7	Contract: 3819	Canadian National Railway Company : Specification for the Construction of Grading & Drainage Northerly Section of Line FG Thorold Subdivision, Town of Thorold, Ontario	N/A	
205	RG52 / R1195	2018-00304-6	7		F. Wonders : Report on Control System Proposed for Seaway Bridges	1956-03-26	
206	RG52 / R1195	2018-00304-6	7	IR 58-153	Canada Department of Mines & Technical Surveys/D.R. Bell : Investigation of Fracture of 30 In. Wide Flange I-Beam from Welland Canal Bridge No. 18	1958-10-14	
207	RG52 / R1195	2018-00304-6	7	50-17-027	SLSA/W. Hay, Consultant : Assessment of Proposed Railroad Network Revision Schemes & Notes for Guidance in the Evaluation of the Railroads' Requirements	1969-12-31	
208	RG52 / R1195	2018-00304-6	7	14-209-1	H.G. Acres & Company Limited : The St. Lawrence Seaway Authority Railway Bridges Over Welland Tunnel Approaches, Design Transmittal No. 1	1968-08-31	
209	RG52 / R1195	2018-00304-6	7	28-5313-21-1	SLSA/Sylvain Martin : Photographies des dommages au Pont no. 13 suite à la collision du remorqueur SINMAC, St-Lambert	1996-05-10	
210	RG52 / R1195	2018-00304-6	7		SLSA : Besoins opérationnels deversoir de St-Lambert, Eastern Region Bridge 15	1993-01-06	
211	RG52 / R1195	2018-00304-6	7		Asselin, Benoit, Boucher, Ducharme, Lapointe Ingénieurs-Conseils/Gérard Lapointe : Projet de Tunnel sous la Voie Maritime du St-Laurent	1967-04-13	
212	RG52 / R1195	2018-00304-6	7		Per Hall Associates Consulting Engineers : The Louis-Hippolyte Lafontaine Bridge-Tunnel, Eastern Region	1967-03-11	

isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
213	RG52 / R1195	2018-00304-6	8		Hydro Québec, Legault Heurtel/Yves Rouleau & Michel Downing, Yann Heurtel : Pont St-Louis Projet de Réfection Estimation Sommaire des Coûts et Pont St-Louis de Gonzague Canal de Beauharnois Étude préliminaire "Réfection/Construction d'un Nouveau Pont/Désaffectation"	1992-05-08	1995-05-08
214	RG52 / R1195	2018-00304-6	8		Hydro Québec/Marcel Vermette : Appel d'offres PMS Région Maisonneuve Pont Ferroviaire St-Louis Remplacement des Appuis Fixes et Mobiles, Protection des Piliers Pont St-Louis et Pont du Chemin Larocque Devis Technique	1985-07-30	
215	RG52 / R1195	2018-00304-6	8		SLSA : Pont St-Louis (Photos Only)	1980-11-24	1992-06-26
216	RG52 / R1195	2018-00304-6	8		Association Internationale des Ponts et Charpentes (Zurich)/Chr. Ostenfeld & Others : Ship Collisions Against Bridge Piers	1965-12-31	
217	RG52 / R1195	2018-00304-6	8	28-3-3-1, E4-107A	SLSA/M. Kandyba : Report on the Rehabilitation of Concrete Bents & Slabs on Victoria Bridge No. 2 St-Lambert Seaway Eastern Region	1973-03-31	
218	RG52 / R1195	2018-00304-6	8	28-6-21-1, E1-349	SLSA/Geo H. Hallett & E. Sutt : Inspection Report Bridge #7B, C.P. Railway Lift Bridge Kahnawake Maisonneuve Region	1992-09-30	
219	RG52 / R1195	2018-00304-6	8	28-6-21-1, E1-349	SLSA/Geo H. Hallett & E. Sutt : Inspection Report Bridge #7A, C.P. Railway Lift Bridge Kahnawake Maisonneuve Region	1992-09-30	
220	RG52 / R1195	2018-00304-6	8	28-16-21-1, E1-349	SLSA/Geo H. Hallett & E. Sutt : Inspection Report Lower Weir Bridge (Victoria) St. Lambert Bridge #16 Maisonneuve Region	1992-01-31	
221	RG52 / R1195	2018-00304-6	8	28-15-21-1, E1-349	SLSA/Geo H. Hallett & E. Sutt : Inspection Report Bridge No. 15 Upper Weir Bridge St. Lambert Maisonneuve Region	1992-01-31	
222	RG52 / R1195	2018-00304-6	8	28-14-21-1, E3-005	SLSA/Geo H. Hallett & A.P. Juster : Inspection Report Bridge No. 14 South Viaduct Victoria Approach St. Lambert Lock Maisonneuve Region	1993-08-31	
223	RG52 / R1195	2018-00304-6	8	28-13-21-1, M1-349	SLSA/Geo H. Hallett & E. Sutt : Inspection Report Bridge No. 13 Ice Control Structure Upper St. Lambert Lock Maisonneuve Region	1992-01-31	
224	RG52 / R1195	2018-00304-6	8	Task 02-T8200-9- 9565 394230	Lalonde, Valois, Lamarra, Valois & Associés (1991) Inc. SNC-Lavalin : Rapport Final Capacité de pont Larocque	1993-02-28	
225	RG52 / R1195	2018-00304-6	8	28-9-12-1	Le Groupe S.M. Inc. : Estimation des couts d'infrastructure de la traversee du Canal Beauharnois	1989-04-05	
226	RG52 / R1195	2018-00304-6	8		SLSA/M. Cote & G. Shink, Service Technique Arpentage : Vérification des points de contrôle pont 10 Valleyfield Région Maisonneuve	1995-09-15	
227	RG52 / R1195	2018-00304-6	8		SLSA/M. Cote & G. Shink, Service Technique Arpentage : Vérification des points de contrôle pont 10 Valleyfield Région Maisonneuve	1996-10-03	
228	RG52 / R1195	2018-00304-6	8		SLSA/M. Cote & R. Bluteau : Vérification des points de contrôle pont 10 Valleyfield Région Maisonneuve	1994-12-12	
229	RG52 / R1195	2018-00304-6	8		SLSA : Pont Larocque à Valleyfield Suivi du comportement des tours (Piliers 6, 7, 8 et 9)	1993-06-30	

isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
230	RG52 / R1195	2018-00304-6	8		SLSA/J.P. des Chatelets : Report on the Vehicular Traffic on the Valleyfield & St. Louis Bridges	1966-12-20	
231	RG52 / R1195	2018-00304-6	8		Lalonde, Valois, Lamarra, Valois & Associés, Inc./Pierre Lamarre & Paul Roberge : Rapport sur la Dilatation des Piliers Nos 7 & 8 des ponts Larocque et St-Louis	1973-10-04	
232	RG52 / R1195	2018-00304-6	8		SLSA/Luc Lefebvre & P. Vincelli : Remote Operation of Bridges 7A/7B Feasibility Study	1993-02-01	
233	RG52 / R1195	2018-00304-6	8	Contract 12-970	SLSA/C.J. Christensen : Failure of West Side Slope Regional Road 84 South of Niedle's Overpass & Some Recommendations	1974-09-06	
234	RG52 / R1195	2018-00304-6	8		The Operations Advisory Group, Ontario Hydro, New York Power Authority, Hydro Quebec, Transport Canada, SLSDC/John Ho, Denise Bisnett, Sylvain Robert, N.E. Eryuzlu & John B. Adams : Report on Opening of 1992 Navigation Season Montreal - Lake Ontario Section, Saint Lawrence Seaway	1992-08-13	
235	RG52 / R1195	2018-00304-6	8		The Operations Advisory Group/T.E. Wiggle, D. Bisnett, F. Santerre, C.J.R. Lawrie & J.B. Adams : Report on Opening of 1983 Navigation Season Montreal - Lake Ontario Section, Saint Lawrence Seaway	1983-05-05	
236	RG52 / R1195	2018-00304-6	8		The Operations Advisory Group/John Ho, D. Bisnett, F. Santerre, C.J.R. Lawrie & J.B. Adams : Report on Opening of 1986 Navigation Season Montreal - Lake Ontario Section, Saint Lawrence Seaway	1986-08-07	
237	RG52 / R1195	2018-00304-6	8		The Operations Advisory Group/John Ho, D. Bisnett, Jean-Claude Rassam, G. Reginald Golding & J.B. Adams : Report on Opening of 1989 Navigation Season Montreal - Lake Ontario Section, Saint Lawrence Seaway	1989-08-31	
238	RG52 / R1195	2018-00304-6	8		The Operations Advisory Group : Report on Opening of 1979 Navigation Season Montreal - Lake Ontario Section, Saint Lawrence Seaway	1979-05-10	
239	RG52 / R1195	2018-00304-6	8		The Operations Advisory Group/T.E. Wiggle, J. Bartholomew, F. Santerre, C.J.R. Lawrie & J.B. Adams : Report on Ice Conditions & Operations - St. Lawrence River During December 1976	1977-03-15	
240	RG52 / R1195	2018-00304-6	8		Operations Advisory Group, Ontario Hydro, New York Power Authority, Hydro Quebec, Transport Canada, SLSDC/John Ching, Dan Herrmann, Sylvain Robert, N.E. Eryuzlu & Stephen C. Hung : Report on Opening of 1995 Navigation Season Montreal - Lake Ontario Section, Saint Lawrence Seaway	1995-07-31	
241	RG52 / R1195	2018-00304-6	8		Operations Advisory Group, Ontario Hydro, New York Power Authority, Hydro Quebec, Transport Canada, SLSDC/John Ho, Denise Bisnett, Sylvain Robert, N.E. Eryuzlu & John B. Adams : Report on Opening of 1993 Navigation Season Montreal - Lake Ontario Section, Saint Lawrence Seaway	1993-09-16	



isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
242	RG52 / R1195	2018-00304-6	8		Operations Advisory Group, Ontario Hydro, New York Power Authority, Hydro Quebec, Transport Canada, SLSDC/John Ho, Denise Bisnett, Sylvain Robert, N.E. Eryuzlu & John B. Adams : Report on Opening of 1994 Navigation Season Montreal - Lake Ontario Section, Saint Lawrence Seaway	1994-06-14	
243	RG52 / R1195	2018-00304-6	8		SLSDC & SLSA/Stephen C. Hung, OAG Member : Report on Opening of 1998 Navigation Season Montreal - Lake Ontario Section, Saint Lawrence Seaway	1998-06-01	
244	RG52 / R1195	2018-00304-6	8		SLSDC & SLSA/Stephen C. Hung, OAG Member : Report on Opening of 1997 Navigation Season Montreal - Lake Ontario Section, Saint Lawrence Seaway	1997-06-02	
245	RG52 / R1195	2018-00304-6	8		Operations Advisory Group, Ontario Hydro, New York Power Authority, Hydro Quebec, Transport Canada, SLSDC/John Ching, Dan Herrmann, Sylvain Robert, N.E. Eryuzlu & Stephen C. Hung : Report on Opening of 1996 Navigation Season Montreal - Lake Ontario Section, Saint Lawrence Seaway	1996-07-15	
246	RG52 / R1195	2018-00304-6	8		The Operations Advisory Group/John Ho, D. Bisnett, J.C. Rassam, G.R. Golding & John B. Adams : Report on Opening of 1987 Navigation Season Montreal - Lake Ontario Section, Saint Lawrence Seaway	1987-08-13	
247	RG52 / R1195	2018-00304-6	8		Operations Advisory Group, Ontario Hydro, New York Power Authority, Hydro Quebec, Transport Canada, SLSDC/John Ho, Denise Bisnett, Sylvain Robert, N.E. Eryuzlu & John B. Adams : Report on Opening of 1991 Navigation Season Montreal - Lake Ontario Section, Saint Lawrence Seaway	1991-10-10	
248	RG52 / R1195	2018-00304-6	8		Operations Advisory Group/John Ho, Denise Bisnett, Jean-Claude Rassam, G. Reginald Golding & John B. Adams : Report on Opening of 1990 Navigation Season Montreal - Lake Ontario Section, Saint Lawrence Seaway	1990-08-30	
249	RG52 / R1195	2018-00304-6	8		Operations Advisory Group/John Ho, Denise Bisnett, Jean-Claude Rassam, G.R. Golding & John B. Adams : Report on Opening of 1988 Navigation Season Montreal - Lake Ontario Section, Saint Lawrence Seaway	1988-08-18	
250	RG52 / R1195	2018-00304-6	8	33-2-32-4	SLSA/J.T. Carvell, F.E. Jackson, D.M. Miller, J.H. Graham, G. Smith, R.J. Cronmiller, R.J. Good : Report Future Disposition of the Section of the Fourth Welland Canal which will be Replaced by the By-Pass	1973-01-04	
251	RG52 / R1195	2018-00304-6	8		SLSA/W.F. Blair : Ice Reconnaissance Program Detroit River, Lake St. Clair & St. Clair River	1971-01-05	
252	RG52 / R1195	2018-00304-6	8	28-9-2-1, E1-104	SLSA/T.G. Tustin : Vertical Lift Bridge - Valleyfield (E1-104) Operation Difficulties & Pier Geometry & Construction	1972-04-04	

isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
253	RG52 / R1195	2018-00304-6	8		AML : Welland Ship Canal Operating Instruction for Railway Bridges Bascule	1952-11-19	
254	RG52 / R1195	2018-00304-6	8		AML : Welland Ship Canal Operating Instruction for Railway Bridges Vertical Lift	1952-11-19	
255	RG52 / R1195	2018-00304-6	8	60-3-4-3	SLSA, Transport Canada, Dept. of the Army, U.S. Enviromental Agency & Others/A.W. Bridgewater & W.E. Webb, D.R. Cuthbert, Brigadier General Robert L. Moore, George R. Alexander & Others : Great Lakes - St. Lawrence River System Extension of Navigation Season Short Term Forecasts of Ice Formation in St. Lawrence River Use	1971-05-01	1976-05-14
256	RG52 / R1195	2018-00304-6	8	28-7-23-10, E1-286	SLSA/J.G. Woodcock & G.H. Hallett : Upper Beauharnois Swing Bridge Reduction of Operation & Maintenance Costs with Re-Routing of Rail Traffic	1982-07-30	
257	RG52 / R1195	2018-00304-6	8		SLSA/Guy Ménard & Gilles Hotte : Preliminary Automatisation du pont 8 et son opération de la tour de contrôle aval à l'écuse no. 4 de Beauharnois	1977-06-23	
258	RG52 / R1195	2018-00304-6	8	28-7-1-1	SLSA/J. Godin : Rapport sur le coût d'entretien des signaux ferroviaires au pout #8 tel que facturé par "Consolidated Rail Corporation" (Conrail)	1980-05-20	
259	RG52 / R1195	2018-00304-6	8		SLSA : Seaway Lockage & Bridge Procedure Handbook Operations	N/A	
260	RG52 / R1195	2018-00304-6	8		National Snow & Ice Data Center, University of Colorado/Claire S. Hanson : Great Lakes Ice Data Set Numbers 1, 2, 3, 4, 5, 6, 7, 8-10	1955-01-01	1983-06-30
261	RG52 / R1195	2018-00304-6	8	60-29-1-1	NOAA National Oceanic & Atmosphere Administration, Environmental Research Laboratories/John V. Byrne & Vernon E. Derr : Lake Erie Regional Ice Cover Analysis: Preliminary Results	1983-07-29	
262	RG52 / R1195	2018-00304-6	8		SLSA/Guy Ménard & Gilles Hotte : Automatisation du pont 8 et son opération de la tour de contrôle aval à l'écuse no. 4 de Beauharnois	1977-06-23	
263	RG52 / R1195	2018-00304-6	8	Ref. Onan: VP- 27841 Rev. 2, 28- 5309-10-1	Cummins Division Énergie Onan : Dessins d'atelier Projet: L'Administration de la Voie Maritime du St-Laurent, Région Maisonneuve, Pont St-Louis 9 Groupe Electrogene d'urgence	1996-11-06	
264	RG52 / R1195	2018-00304-6	8	28-8-21-1, E1-349	SLSA/Geo H. Hallett & E. Sutt : Inspection Report Bridge #9 Saint-Louis-De-Gonzague Lift & Tower Spans Maisonneuve Region	1992-06-30	
265	RG52 / R1195	2018-00304-6	8		: Buoy Stations from Lake St-Francis to Lake St-Lawrence	1968-01-01	1994-12-30
266	RG52 / R1195	2018-00304-6	8		SLSA/M. Hanson : Beauharnois Canal Entrance Study Volume 1 of 2	1972-12-29	
267	RG52 / R1195	2018-00304-6	8	33-8-2-10	SLSA/W.R. MacKay : Desynchronization of the St. Lawrence Seaway's Beauharnois Locks	1971-06-25	
268	RG52 / R1195	2018-00304-6	8	33-8-2-10, E1-072	SLSA/B.K. Stinson : Desynchronization of the St. Lawrence Seaway's Beauharnois Locks	1971-05-31	

isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
269	RG52 / R1195	2018-00304-6	8		Canadian Shipowners Association/Capt Rejean Lanteigne, Marine Operations Manager : Transportation Reform, Restructing of Government Cost Recovery & Legislation	1996-01-09	
270	RG52 / R1195	2018-00304-6	8		SLSA : The Saint Lawrence Seaway Bridge Details, Complete Listing with Full Details		
271	RG52 / R1195	2018-00304-6	8	60-5-4-1	Canadian Shipowners Association/Capt Rejean Lanteigne, Marine Operations Manager : Navigational Aids in the Great Lakes	1997-03-23	
272	RG52 / R1195	2018-00304-6	8		Multiple Authors : Orders of Approval for Regulation of Lake Ontario	1956-01-01	2009-12-31
273	RG52 / R1195	2018-00304-6	9	Interim Report 1	Parker Associates : Connecting Road Network for Third Bridge Crossing of Welland Canal in the City of Port Colborne	1978-12-13	
274	RG52 / R1195	2018-00304-6	9		SLSA/M.A. Hanson : Study Cross Currents Below Lock 3 - Beauharnois Canal	1975-11-25	
275	RG52 / R1195	2018-00304-6	9		SLSA/J.G. Vazalinskas, Eng. : Report on Investigation Into Accident of November 24, 1986 at St-Lambert Lock Involving Truck Crane, S/VM Unit No. 341	1986-12-05	
276	RG52 / R1195	2018-00304-6	9		U.S. Army Engineer District, Detroit, Corp of Engineers : St. Lawrence River - Flow Distribution Around Cornwall Island, 1970	1970-11-30	
277	RG52 / R1195	2018-00304-6	9	RSH43-82-38	Hydro Québec/Claude Marche, Tung T. Quach et J.-G. Dussault : Modélisation numérique des conditions d'hydraulicité typiques dans l'archipel de Montréal entre le Lac Des Deux-Montagnes et les rapides de Lachine	1982-08-31	
278	RG52 / R1195	2018-00304-6	9		Canadian Shipowners Association : The Great Lakes/St. Lawrence Seaway System in Crisis and Its Impact on Canadian Shipowners	1992-12-08	
279	RG52 / R1195	2018-00304-6	9		M.M. Dillon Limited in Association with Stan H. Butcherd Per Hall Associates Ltd. & Alberty, Pullerits, Dickson & Associates Ltd. : Decision Highway 3, City of Port Colborne Township of Wainfleet, An Investigation Undertaken to Determine the Best Location for an Improved Highway Route & a New Crossing of the Welland Canal, that will Serve the Regional & Local Transportation Needs	1971-12-31	
280	RG52 / R1195	2018-00304-6	9		John J. McMullen Associates Inc./Carl H. Sjostrom : Effect of Shallow Water on Speed & Trim	1965-09-16	
281	RG52 / R1195	2018-00304-6	9		SLSA/Economics & Planning Branch : Winter Navigation in the Great Lakes St. Lawrence Seaway System Review of Activities & Survey of Potential Markets	1974-12-31	
282	RG52 / R1195	2018-00304-6	9		Ministry of Transportation & Communications & Fenco Consultants Ltd. : Recommendations for Illumination Improvement, Town Line Tunnel Welland, Ontario	1977-09-30	

isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
283	RG52 / R1195	2018-00304-6	9		SLSA : Traffic Management Improvement Project, Traffic Management System, User Requirements Document, Phase 1	1998-01-20	
284	RG52 / R1195	2018-00304-6	9		SLSA & SLSDC/Pat Vincelli, J.M. Kroon & Carol A. Fenton, Steven C. Hung : Seaway Radio Messages Closing Period 1990-1997	1990-11-26	1997-12-24
285	RG52 / R1195	2018-00304-6	9		SLSA/J.M. Kroon : Seaway Radio Messages Closing Period 1987-1989	1987-11-23	1989-12-22
286	RG52 / R1195	2018-00304-6	9		SLSA/J.M. Kroon : Seaway Radio Messages Closing Period 1985-1986	1985-11-05	1986-12-24
287	RG52 / R1195	2018-00304-6	9		SLSA/J.M. Kroon : Seaway Radio Messages Closing Period 1983-1984	1983-11-17	1984-12-31
288	RG52 / R1195	2018-00304-6	9		SLSA/J.M. Kroon : Seaway Radio Messages Closing Period 1977-1982	1977-11-21	1982-12-20
289	RG52 / R1195	2018-00304-6	9		SLSA/J.M. Kroon : Seaway Radio Messages & Ice Bulleting Opening Period 1978-1985	1978-03-27	1985-04-04
290	RG52 / R1195	2018-00304-6	9		SLSA & SLSDC/J.M. Kroon, Pat Vincelli & Carol Fenton : Seaway Radio Messages & Ice Bulleting Opening Period 1986-1988	1986-03-03	1998-03-31
291	RG52 / R1195	2018-00304-6	10		SLSA : Thorold Tunnels 1966 (Photos Only)	1966-01-17	
292	RG52 / R1195	2018-00304-6	10		Norland Science and Engineering Ltd./D. Lapp : Review of Freeze-up Forecasts for the Lower Great Lakes and St. Lawrence River Task 1: Documentation of Methods	1988-04-04	
293	RG52 / R1195	2018-00304-6	10		Norland Science and Engineering Ltd./D. Lapp : Review of Freeze-up Forecasts for the Lower Great Lakes and St. Lawrence River Task 2: Distribution and Use of Forecasts	1988-09-30	
294	RG52 / R1195	2018-00304-6	10		Norland Science and Engineering Ltd./D. Lapp : Review of Freeze-up Forecasts for the Lower Great Lakes and St. Lawrence River Task 3: Proposed Methodology for Comparing Forecasts	1988-09-30	
295	RG52 / R1195	2018-00304-6	10		SLSA/Economics & Planning Branch : Bibliography Ice Problems and Winter Navigation in the Great Lakes	1975-01-31	
296	RG52 / R1195	2018-00304-6	10		Ministry of Transport/The Canadian Marine Transportation Administration : Evolution of Canadian Developments in the Field of Winter Navigation on the St. Lawrence River and Great Lakes	1971-05-10	1971-05-11
297	RG52 / R1195	2018-00304-6	10		Environment Canada/Ice Climatology & Application Division : Ice Thickness Climatology of the Great Lakes (1963-1978)	1963-01-01	1978-12-31
298	RG52 / R1195	2018-00304-6	10	31-6-15-1	Ministry of Transport/Dr. Pierre Camu : Great Lakes Symposium	1971-07-21	1971-07-23
299	RG52 / R1195	2018-00304-6	10	ICEREC 1	Environment Canada/Atmospheric Department : Aerial Ice Reconnaissance & Ice Advisory Services/Services de reconnaissance aerienne des glaces et d'information	1988-12-31	

isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
300	RG52 / R1195	2018-00304-6	10	ICEREC 2	Environment Canada/Atmospheric Department : Aerial Ice Reconnaissance & Ice Advisory Services/Services de reconnaissance aeriennne des glaces et d'information	1988-12-31	
301	RG52 / R1195	2018-00304-6	10		SLSA/La Direction de la planification et du développement : La Prolongation de la saison de navigation Énoncé de position	1980-02-08	
302	RG52 / R1195	2018-00304-6	10	60-21-2-2	Department of Transportation Michigan State University/John L. Hazard : After the Demonstration A Year-Round Great Lakes St. Lawrence Seaway	1975-04-15	
303	RG52 / R1195	2018-00304-6	10	60-22-2-1	LBA Consulting Partners Limited : A Proposal for a Benefit-Cost Study of Possible Extensions to the Seaway Navigation Season	1978-01-09	
304	RG52 / R1195	2018-00304-6	10		SLSA/Planning & Development Division : The St. Lawrence Seaway Authority A Briefing Paper on Season Extension	1982-10-31	
305	RG52 / R1195	2018-00304-6	10	TR 0105-7	ARCTEC, Incorporated Columbia, Maryland : Saint Lawrence Seaway System Plan for All-Year Navigation Summary Report	1975-07-31	
306	RG52 / R1195	2018-00304-6	10	60-24-1-1	U.S. Army Corps of Engineers, Detroit District : Detroit River Ice Jam Alert Program, St. Clair River Ice Jam Alert Program Soo Harbour - Little Rapids Cut Monitoring & Emergency Operations Plan	1984-12-15	
307	RG52 / R1195	2018-00304-6	10	2-1331	Government of Canada/Bureau of Management Consulting : Commercial Evaluation Season Extension St. Lawrence Seaway Authority	1975-08-31	
308	RG52 / R1195	2018-00304-6	10		SLSA : Pont 7A - Caughnawaga (Photos seulement)	1971-09-17	
309	RG52 / R1195	2018-00304-6	10		SLSA/M. A. Hanson : Field Trials of the Air Cushion Vehicle (HL-301) Attached to Tug "Laprairie" January/February 1978	1978-06-30	
310	RG52 / R1195	2018-00304-6	10		SLSA/M. A. Hanson : Field Trials of the Air Cushion Vehicle (HL-301) Attached to Tug "Laprairie" 1978-1979	1979-11-30	
311	RG52 / R1195	2018-00304-6	10		SLSA : Protective Fendering Bluenose Walls	1970-06-01	
312	RG52 / R1195	2018-00304-6	10		SLSA/Traffic Control Process Improvement Team : Volume II - Process Flowcharts	1997-01-21	
313	RG52 / R1195	2018-00304-6	10	Contract No. 9483. Under Contract Order #40	Bridge & Tank Company of Canada Limited : Rolling Lift Bridges Installed at Cote Ste Catherine & Iroquois Locks of St. Lawrence Seaway Operating & Maintenance Recommendations	1957-12-31	
314	RG52 / R1195	2018-00304-6	10		SLSA, US Dept. of Army, Schlegel (UK Engineering)/G. H. Hallett, J.T. Stow, E. Sutt & E.G. Nisbet, Donald L. Billmaier & D. Boast : Documentation on Schlegel Fendering, Eastern Region	1975-01-01	1978-12-29
315	RG52 / R1195	2018-00304-6	10		Shell Tankers Ltd./Captain A.F. Dickson : Navigation of Tankers Through Channels	1959-01-01	

isn	RG / Rno	BAN	Box / Boîte	File number / No. de dossier	Title / titre	Date 1	Date 2
316	RG52 / R1195	2018-00304-6	10		SLSA/C.J. Christensen : Report on Investigation of Concrete Deterioration & Related Aspects Port Colborne West Breakwaters	1981-11-16	
317	RG52 / R1195	2018-00304-6	10		Canadian Vickers Limited : Lock Gate Operating Machinery for the St. Lawrence Seaway Authority	1958-01-01	
318	RG52 / R1195	2018-00304-6	10	28-19-1-1/44, W1-309	SLSA/Geo H. Hallett & Marie Gaudreault : Inspection Report Bridge at Former Lock No. 25 Weir 3rd Welland Canal Southwest of Guard Gate Western Region	1991-09-30	
319	RG52 / R1195	2018-00304-6	10	28-19-1-1/44, W3-005	SLSA/M. Bowden & B. Azzeq : Inspection Report Bridge at Former Lock No. 25 Weir 3rd Welland Canal Southwest of Guard Gate Western Region	1994-02-28	
320	RG52 / R1195	2018-00304-6	10		The Packard Electric Co. : The Electrification of the Welland Canal	N/A	
321	RG52 / R1195	2018-00304-6	10		United Steel Workers of America, Local 6200, Steelworkers of America : Decision Highway 3 Submission Port Colborne	1972-08-31	
322	RG52 / R1195	2018-00304-6	10		SLSA : Questions & Answers About "Decision Highway 3" in Port Colborne & Wainfleet	1972-05-18	
323	RG52 / R1195	2018-00304-6	10		Holy Cross School, Port Colborne/Len Bonnay : The People Speak Out: A Quantitative Analysis of the Transportation Crisis in Port Colborne	1972-06-21	
324	RG52 / R1195	2018-00304-6	10	60-22-25-3	Hickling-Partners Inc. : Great Lakes & St. Lawrence Seaway Season Extension Study	1981-06-30	