

Soulanges and Trent Canal R11329 2005-00302-6				
2001444336 - ALBUM 1; 2001444338 - Album 2; 2001444339 - Album 3; 2001444340 - Album 4; 2001444341 - Album 5; 2000952124 - The majority of the prints in Albums 4 and 5 have been removed and can be found in container 2000952124.				
Number	Measurement	Date	Inscription	Image Location
1	7.6x9.2	May 31, 1904	On album -- Streamer Tugela discharging timber, Three Rivers, Que.	removed (fr.album)
2	7.65x9.5	June 19, 1904	On album -- Shawinigan Falls, Que.	removed (fr.album)
3	9.8x7.5	June 19, 1904	On album -- Log Chute, Shawinigan Falls, Que.	removed (fr.album)
4	7.65x9.95	June 19, 1904	On album -- Upper end of the Gorge, Shawinigan Falls, Que.	removed (fr.album)
5	11.85x17.4	March 4, 1898	On album -- Stone Dressing Yard, Point Ann	removed (fr.album)
6	11.9x16.4	March 21, 1898	On album -- Soulanges Canal -- Section 11 -- Upper end of River Delisle (sp?) Culvert	removed (fr.album)
7	11.9x16.6	March 21, 1898	On album -- River Delisle Bridge, Coteau du Que. (flood waters)	removed (fr.album)
8	12x17.1	April 16, 1898	On album -- Soulanges Canal -- Section 9 -- Earth slides, stations 539-545, south bank	removed (fr.album)
9	11.5x17	April 16, 1898	On album -- East end of Section 9, showing slides in south bank. View taken from station 535. Station 9 -- Soulanges Canal	removed (fr.album)
10	11.6x16.8	May 22, 1898	On album -- West end of Section 8, showing slides in south bank -- view taken from station 535. Section 8 -- Soulanges Canal	removed (fr.album)
11	12.1x17	June 13, 1898	On album -- Soulanges Canal -- Section 13. Upper entrance of Lock and Raceway, from south end to dam.	removed (fr.album)
12	12.3x16.9	June 17, 1898	On album -- Soulanges Canal -- Section 13. Foundation course, at upper gates, Guard Lock	removed (fr.album)
13	11.95x16.5	June 17, 1898	On album -- Anchorage of Lower Centre Sills of Guard Lock. Section 13 -- Soulanges Canal	removed (fr.album)
14	11.6x17.1	June 17, 1898	On album -- Rock at Station 734 -- showing the projecting edges of the different layers of Rock. Section 13 -- Soulanges Canal	removed (fr.album)
15	11.85x16.45	August 1, 1898	On album -- Excavating for Culvert on Crib No 2, south. Section 13 -- Soulanges Canal	removed (fr.album)
16	11.9x16.2	August 1, 1898	On album -- Earth and Rock Excavation for Weir. Section 13 -- Soulanges Canal	removed (fr.album)
17	11.6x16.6	August 1, 1898	On album -- Soulanges Canal -- Section 13. Earth & Rock Excavation for Weir	removed (fr.album)
18	11.9x16.6	August 13, 1898	On album -- Raft caught on Piers of Canada Atlantic Railway Bridge, across River St Lawrence	removed (fr.album)
19	11.8x17.3	March 21, 1899	On album -- Regulating Weir. View taken from south bank looking towards the North West. Section 13 -- Soulanges Canal	removed (fr.album)
20	11.6x17	March 21, 1899	On album -- General view of Regulating Weir (illegible) taken from 150 ft south, station 750. Section 13 -- Soulanges Canal	removed (fr.album)
21	12.2x17.2	November 21, 1898	On album -- Regulating Weir and Raceway. View taken from Bridge at upper end of Raceway. Section 13 -- Soulanges Canal	removed (fr.album)
22	11.75x17.2	November 24, 1898	On album -- Regulating Weir and Raceway. View taken from Bridge at upper end of Raceway. Section 13 -- Soulanges Canal	removed (fr.album)
23	12.2x16.9	December 1, 1898	On album -- Guard Lock. View taken from upper end. Section 13 -- Soulanges Canal	removed (fr.album)
24	12x17.3	December 1, 1898	On album -- Regulating Weir. View taken from Raceway entrance. Section 13 -- Soulanges Canal	removed (fr.album)
25	12.8x17	December 1, 1898	On album -- Lower end of Raceway. View taken from north bank of Canal. Section 13 -- Soulanges Canal	removed (fr.album)
26	12.1x16.7	December 1, 1898	On album -- Guard Lock and Raceway showing 1st method of erecting Lock Gates -- view taken from C A Ry. bridge looking towards Canal Entrance. Section 13 -- Soulanges Canal	removed (fr.album)
27	12.3x16.6	April 15, 1899	On album -- Regulating Weir and Arches of Road Bridge. View taken from south bank 150 ft east of structures. Section 13 -- Soulanges Canal	removed (fr.album)
28	11.8x16.7	May 3, 1899	On album -- East end of Raceway, showing Stone Filling for South Pitching. Section 13 -- Soulanges Canal	removed (fr.album)
29	11.6x16.9	May 17, 1899	On album -- Earth Filling at slides, station 560. Section 9 -- Soulanges Canal	removed (fr.album)
30	11.5x16.5	May 17, 1899	On album -- Earth Excavation and Stone Filling at station 538. Section 9 -- Soulanges Canal	removed (fr.album)
31	11.8x16.5	May 22, 1899	On album -- General view from 120 ft north of station 756. Section 13 -- Soulanges Canal	removed (fr.album)
32	12.3x16.7	May 24, 1899	On album -- Slide North Bank -- station 559. Section 9 -- Soulanges Canal	removed (fr.album)
33	11.8x16.3	June 2, 1899	On album -- 1st Letting in of Water, above Guard Lock. Section 13 -- Soulanges Canal	removed (fr.album)
34	11.7x17.2	June 10, 1899	On album -- Coteau Rapids from Old Fort	removed (fr.album)
35	12.1x16.8	July 13, 1899	On album -- Upper end of Waste Channel. Section 13 -- Soulanges Canal	removed (fr.album)

36	12x17.1	March 3, 1898	On album -- Track opening in Stone piles -- Point Ann	removed (fr.album)
37	12.1x16.5	March 4, 1898	On album -- Dressed Stone at west derrick -- Point Ann	removed (fr.album)
38	11.8x16.8	March 3, 1898	On album -- Cut Stone Piles -- view taken from south of yard -- Point Ann	removed (fr.album)
39	11x16.8	March 3, 1898	On album -- Stone Piles and Dressing yard -- view taken from south east of piles -- Point Ann	removed (fr.album)
40	12x16.4	August 1, 1898	On album -- Earth and Rock Excavation for Weir. Section 13 -- Soulanges Canal	removed (fr.album)
41	11.8x17.2	August 8, 1898	On album -- Earth Excavation for Weir. Section 13 --Soulanges Canal	removed (fr.album)
42	11.8x16.5	August 27, 1898	On album -- Guard Lock and Raceway from C. A. Ry. Embankment near south east of Bridge. Section 13 -- Soulanges Canal	removed (fr.album)
43	11.8x17.3	August 27, 1898	On album -- Concrete Foundation for Weir. Section 13 -- Soulanges Canal	removed (fr.album)
44	12.2x17.2	September 15, 1898	On album -- East end of Guard Lock -- view taken from north of Lower Gates. Section 13 -- Soulanges Canal	removed (fr.album)
45	11.8x17	September 15, 1898	On album -- Excavating Clay left by Dredges. Section 13 -- Soulanges Canal	removed (fr.album)
46	12x17	April 15, 1899	On album -- Soulanges Canal -- Section 13. Regulating Weir (illegible) From south bank 150 ft east of Structure.	removed (fr.album)
47	11.9x16.6	May 8, 1899	On album -- Soulanges Canal -- Section 13. Launching Dredge No 4	removed (fr.album)
48	12.5x17	June 2, 1899	On album -- Raceway - from East-Bridge. Section 13 -- Soulanges Canal	removed (fr.album)
49	12.2x16.8	June 2, 1899	On album -- Raceway from south side under C. A. Ry. Bridge. Section 13 -- Soulanges Canal	removed (fr.album)
50	11.5x16.7	June 13, 1898	On album -- Upper Entrance of Guard Lock to Raceway, view taken from 100 ft north at station 752+50 (near dam). Section 13 -- Soulanges Canal	removed (fr.album)
51	12x16.6	May 28, 1898	On album -- Upper Raceway Bridge -- view taken from south bank, looking west. Section 13 -- Soulanges Canal	removed (fr.album)
52	11.8x16.7	March 4, 1898	On album -- Quarrying (at Point Ann) for Foundation course of Guard Lock. Section 13 -- Soulanges Canal	removed (fr.album)
53	12.2x16.7	March 4, 1898	On album -- General view of stone quarry at Point Ann for foundation course of Guard Lock. Section 13 -- Soulanges Canal	removed (fr.album)
54	11.8x16.8	March 21, 1898	On album -- Upper end of River Delisle culvert at flood waters -- Section 11 -- Soulanges Canal	removed (fr.album)
55	12x16.7	March 4, 1898	On album -- Quarrying (at Point Ann) for Foundation course of Guard Lock -- Section 13 -- Soulanges Canal	removed (fr.album)
56	11.8x16.4	March 21, 1898	On album -- River Delisle Bridge and dam at Coteau du Que. (sp?) -- flood waters	removed (fr.album)
57	12x16.9	March 21, 1898	On album -- West end of Section 9 -- Soulanges Canal	removed (fr.album)
58	11.8x17.1	April 16, 1898	On album -- Earth slides, station 539-545, south bank. Section 9 -- Soulanges Canal	removed (fr.album)
59	11.7x16.6	March 21, 1898	On album -- Lower end of River Delisle Culvert at flood waters -- Section 11 -- Soulanges Canal	removed (fr.album)
60	11.9x13	May 22, 1898	On album -- Upper Centre Sill anchorage, Guard Lock. View taken looking south. Section 13 -- Soulanges Canal	removed (fr.album)
61	12.2x16.7	May 22, 1898	On album -- Upper Mitre (sp?) Sill anchorage, Guard Lock. Section 13 -- Soulanges Canal	removed (fr.album)
62	11.2x16	July 20, 1898	On album -- Steam Shovel at station 737+00 -- In front of the steam shovel is the (illegible) of rock at 737+25, on which may be dimly seen the steam drill which had been at work. Rock can not be seen in view owing to light getting in on plate. Section 13 -- Soulanges Canal	removed (fr.album)
63	11.4x16.2	July 17, 1898	On album -- Stone yard at Point Ann, showing Culvert sheeting and other dressed stone for Guard Lock -- Section 13 -- Soulanges Canal	removed (fr.album)
64	11.5x16.9	July 20, 1898	On album -- Upper Entrance of Lock and Upper Raceway Bridge. Section 13 -- Soulanges Canal	removed (fr.album)
65	12.2x16.9	July 20, 1898	On album -- Guard Lock (illegible), showing state of work, and also men wheeling material across the Lock to make the puddle bank with 747+80 -- view taken from north flank (sp?) wall of Canal Entrance -- Section 13 -- Soulanges Canal	removed (fr.album)
66	11.9x16.5	August 13, 1898	On album -- Raft caught in piers of Canada Atlantic Railway Bridge, across River St Lawrence	removed (fr.album)
67	11.4x16.6	August 8, 1898	On album -- Blasting for Foundation of Weir. Section 13 -- Soulanges Canal	removed (fr.album)
68	11.9x17	August 27, 1898	On album -- Concrete Foundation for Weir. Section 13 -- Soulanges Canal	removed (fr.album)
69	12.1x16.4	August 15, 1898	On album -- Raceway -- view taken from Bridge at upper end of raceway. Section 13 -- Soulanges Canal	removed (fr.album)
70	12.1x16.75	September 24, 1898	On album -- East of Guard Lock (after heavy rain). View taken from north abutment of C. A. Ry. Bridge. Section 13 -- Soulanges Canal	removed (fr.album)
71	12x17	September 24, 1898	On album -- East end of Guard Lock. View taken from north bank about station 740. Section 13 -- Soulanges Canal	removed (fr.album)
72	11.2x16.2	June 3, 1899	On album -- General view, East of Lock. Section 13 -- Soulanges Canal	removed (fr.album)
73	12.8x16.8	June 2, 1899	On album -- Raceway from South side, under C. A. Ry bridge. Section 13 -- Soulanges Canal	removed (fr.album)

74	12.3x17	July 26, 1899	On album -- Lower end of Lock & Raceway. Section 13 -- Soulanges Canal	removed (fr.album)
75	11.9x17.2	July 14, 1899	On album -- Arches of Road Bridge. Section 13 -- Soulanges Canal	removed (fr.album)
76	11.9x16.6	May 22, 1899	On album -- Raceway -- showing Arch and Swing Bridges for Public Travel. Section 13 -- Soulanges Canal	removed (fr.album)
77	11.5x17	May 22, 1899	On album -- Bridge at Lower end of Raceway. Section 13 -- Soulanges Canal	removed (fr.album)
78	12.1x16.8	May 22, 1899	On album -- Soulanges Canal -- Section 13. South sluice gate of Regulating Weir	removed (fr.album)
79	12.2x16.7	May 22, 1899	On album -- Soulanges Canal -- Section 13. Bridge at lower end of Raceway	removed (fr.album)
80	11.8x16.5	December 1, 1898	On album -- Entrance of Culvert -- Guard Lock. Section 13 -- Soulanges Canal	removed (fr.album)
81	12x17.8	November 24, 1898	On album -- General view looking East from North abutment of C. A. Ry. Bridge. Section 13 -- Soulanges Canal	removed (fr.album)
82	11.8x16.9	August 29, 1899	On album -- View of Coteau Landing from 100 ft N. station 757. Section 13 -- Soulanges Canal	removed (fr.album)
83	12.2x16.8	August 29, 1899	On album -- General view, Section 13, from 100 ft N. at station 757. Soulanges Canal	removed (fr.album)
84	15.8x12.4	November 13, 1899	On album -- Steamer Porto Rico in Lock at Coteau Landing. Section 13 -- Soulanges Canal	removed (fr.album)
85	11.9x16.6	November 13, 1899	On album -- Steamer Porto Rico, in Lock at Coteau Landing. Section 13 -- Soulanges Canal. This is the first vessel to pass through the Soulanges Canal for ocean travel. The hull is of steel and is furnished with triple expansive engines. The vessel is registered of Toledo and is bound for the island of Porto Rico to engage in trade there. Length 240' ("240" written in pencil) width 36' ("36" written in pencil) draft 12' ("12" written in pencil)	removed (fr.album)
86	11.6x16.7	November 21, 1898	On album -- Upper entrance of Guard Lock showing also lower Gates of Lock, after having been passed over the dam. Section 13 -- Soulanges Canal	removed (fr.album)
87	11.9x17.2	October 28, 1898	On album -- Regulating Weir and Raceway . View taken from Bridge at upper end of Raceway. Section 13 -- Soulanges Canal	removed (fr.album)
88	12.3x16.6	May 22, 1899	On album -- South Sluice gate of Regulating Weir. Section 13 -- Soulanges Canal	removed (fr.album)
89	12.4x17	May 22, 1899	On album -- Regulating Weir. View taken from entrance of Raceway. Section 13 -- Soulanges Canal	removed (fr.album)
90	11.9x16.8	October 1, 1898	On album -- Guard Lock and Raceway -- view taken from Canada Atlantic Railway Bridge, looking towards Canal Entrance. Section 13 -- Soulanges Canal	removed (fr.album)
91	12.5x16.7	September 30, 1898	On album -- Anchorage of Lower Gate of Guard Lock. View taken from north bank looking south. Section 13 -- Soulanges Canal	removed (fr.album)
92	12.2x16.2	November 21, 1898	On album -- Soulanges Canal -- Section 13. Regulating Weir and Raceway, looking from upper end of Raceway	removed (fr.album)
93	11.8x17.2	November 21, 1898	On album -- Soulanges Canal -- Section 13. Guard Lock, upper entrance, showing lower gates after being passed over dam.	removed (fr.album)
94	12x16.7	October 12, 1898	On album -- Regulating Weir and Raceway. Section 13 -- Soulanges Canal	removed (fr.album)
95	12x17.2	October 12, 1898	On album -- Rock formation about station 733, showing stepped nature of surface. Section 13 -- Soulanges Canal	removed (fr.album)
96	12.2x16.9	October 1, 1898	On album -- Rock formation about station 733, showing stepped nature of surface. Section 13 -- Soulanges Canal	removed (fr.album)
97	11.8x17.2	October 1, 1898	On album -- East end of Raceway -- view taken from south bank near C. A. Ry. Bridge. Section 13 -- Soulanges Canal	removed (fr.album)
98	12.3x17.1	September 22, 1898	On album -- Excavating for Concrete toe (sp?) of south pitching at station 744 -- noon hour. Section 13 -- Soulanges Canal	removed (fr.album)
99	12.3x16.7	September 21, 1898	On album -- Excavating for Concrete toe of south Pitching about station 744. Section 13 -- Soulanges Canal	removed (fr.album)
100	11.8x17.2	September 9, 1898	On album -- Steam Shovel at East end of Raceway. Section 13 -- Soulanges Canal	removed (fr.album)
101	12.2x17.2	September 9, 1898	On album --Lower end of Guard Lock and Raceway. Section 13 -- Soulanges Canal	removed (fr.album)
102	12.2x17.2	September 6, 1898	On album -- Mr. R. Macdonald's house -- Coteau Landing	removed (fr.album)
103	12x17.2	September 3, 1898	On album -- Excavating for toe of Pitching south side of Raceway -- Section 13 -- Soulanges Canal	removed (fr.album)
104	10.6x17.2	August 28, 1898	On album -- Soulanges Canal Entrance and Canada Atlantic Railway Bridge, River St Lawrence from C. A. Ry. Elevator	removed (fr.album)
105	12.1x16.4	August 27, 1898	On album -- Soulanges Canal -- Section 13. Guard Lock & Raceway from south end of C. A. Ry. Bridge	removed (fr.album)
106	11.9x16.5	August 27, 1898	On album -- Soulanges Canal -- Section 13. Concrete Foundation for Weir	removed (fr.album)
107	11.9x17.2	August 15, 1898	On album -- Soulanges Canal -- Section 13. Raceway from Upper end	removed (fr.album)
108	11.8x16.6	August 15, 1898	On album -- Soulanges Canal -- Section 13. Guard Lock from Upper end	removed (fr.album)
109	11.2x16.7	August 15, 1898	On album -- Raft caught on Piers of Canada Atlantic Railway Bridge, across River St Lawrence	removed (fr.album)
110	11.7x16.9	November 24, 1898	On album -- Regulating Weir. View taken from south bank looking westward. Section 13 -- Soulanges Canal	removed (fr.album)
111	11.9x16.8	November 24, 1898	On album -- Regulating Weir. View taken from south bank looking northward. Section 13 -- Soulanges Canal	removed (fr.album)

112	11.6x16.7	November 24, 1898	On album -- East end of Raceway. View taken from south abutment of Bridge at East end of Raceway. Section 13 -- Soulanges Canal	removed (fr.album)
113	12.25x16.7	November 24, 1898	On album -- East end of Raceway. View taken from midway on South bank. Section 13 -- Soulanges Canal	removed (fr.album)
114	11.5x16.6	December 22, 1898	On album -- Excavating for Stone Foundation of North Bank -- view taken station 538. Section 9 -- Soulanges Canal	removed (fr.album)
115	12.1x16.9	December 16, 1898	On album -- Regulating Weir, showing walls occupied by Dominion Bridge Co. placing sluice gates. View taken from south bank of Raceway 100 ft from walls. Section 13 -- Soulanges Canal	removed (fr.album)
116	11.8x16.8	December 22, 1898	On album -- Soulanges Canal -- Section 9. Excavation for Stone Foundation of north bank 1000 ft from lower end of section	removed (fr.album)
117	12x17.9	December 16, 1898	On album -- Soulanges Canal -- Section 13. Regulating Weir, from south bank of Raceway 100 ft below the walls+D77	removed (fr.album)
118	11.9x17.2	December 22, 1898	On album -- Excavation for Stone Foundation of North bank. View taken from station 545. Section 9 -- Soulanges Canal	removed (fr.album)
119	12x16.8	December 22, 1898	On album -- Excavation for Stone Foundation of North bank. View taken from station 545. Section 9 -- Soulanges Canal	removed (fr.album)
120	12.3x16.6	February 21, 1899	On album -- Regulating Weir. View taken from south of structure. Section 13 -- Soulanges Canal	removed (fr.album)
121	11.6x17	December 22, 1898	On album -- General view taken from near the North Heading Pier. Section 13 -- Soulanges Canal	removed (fr.album)
122	9.2x11.8			removed (fr.album)
123	9.2x12.1	December 10, 1909	Stamped bottom left -- DEC 10 1909; stamped centre -- Hastings Work	removed (fr.album)
124	9.2x12	December 10, 1909	Stamped bottom left -- DEC 10 1909; stamped top centre -- Hastings Work	removed (fr.album)
125	11.9x9.2	December 10, 1909	Stamped bottom left -- DEC 10 1909; stamped top centre -- Hastings Work	removed (fr.album)
126	8.9x12	December 6, 1909	Stamped bottom right -- DEC 6 1909; stamped top centre -- Hastings Work	removed (fr.album)
127	11.9x9.3	December 6, 1909	Stamped bottom left -- DEC 6 1909; stamped top centre -- Hastings Work	removed (fr.album)
128	9.1x11.9	December 6, 1909	Stamped bottom left -- DEC 6 1909; stamped centre -- Hastings Work	removed (fr.album)
129	9.2x11.8	December 6, 1909	Stamped bottom right -- DEC 6 1909; stamped top centre -- Hastings Work	removed (fr.album)
130	8.7x11.7		Stamped top centre -- Hastings Work	removed (fr.album)
131	12.1x8.9	April 23, 1912	Stamped bottom left -- APR 23 1912; stamped top centre -- Hastings Work	removed (fr.album)
132	13.5x8.4	December 29, 1911	Stamped bottom right -- DEC 29 1911; stamped top centre -- Hastings Work	removed (fr.album)
133	13.8x8.4	December 29, 1911	Stamped bottom right -- DEC 29 1911; stamped top centre -- Hastings Work	removed (fr.album)
134	9.2x11.5	?	Stamped centre left -- DEC ... (faded); stamped centre left -- Hastings Work	removed (fr.album)
135	11.7x8.6		Stamped top centre -- Hastings Work	removed (fr.album)
136	8.6x11.6	April 23, 1912	Stamped bottom left -- APR 23 1912	removed (fr.album)
137	8.7x11.5		Stamped bottom centre -- Hastings Work	removed (fr.album)
138	9x11.8	June 1910	On album -- TRENT Bridge June 1910; stamped top centre -- JUN 1910	removed (fr.album)
139	8.9x11.6	June 1910	On album -- TRENT Bridge June 1910; stamped top centre -- JUN 1910	removed (fr.album)
140	11.7x8.8	June 1910	On album -- Lock Pit June 1910; stamped top right -- JUN 1910; stamped top right -- Hastings Work	removed (fr.album)
141	8.9x11.8	June 1910	On album -- Lock Pit June 1910; stamped top right -- JUN 1910; stamped top centre -- Hastings Work	removed (fr.album)
142	8.6x11.6	January 1912	On album -- Hastings Spillway -- Jan. 1912-	removed (fr.album)
143	8.6x11.7	January 1912	On album -- Hastings Spillway -- Jan. 1912-	removed (fr.album)
144	8.6x11.7		On album -- Dredge No. 8; stamped top left -- Hastings Work	removed (fr.album)
145	8.1x10.9		On album -- Tug Lake -- Dredge No 7; stamped top centre -- Hastings Work	removed (fr.album)
146	8.7x11.6		Stamped top centre -- Hastings Work	removed (fr.album)
147	9.2x11.5		Stamped top centre -- Hastings Work	removed (fr.album)
148	8.5x11.65		Stamped top centre -- Hastings Work	removed (fr.album)
149	8.5x11.65			removed (fr.album)
150	8.6x11.6			removed (fr.album)
151	8.7x11.7			removed (fr.album)
152	8.6x11.8		Stamped top centre -- Hastings Work	removed (fr.album)

153	8.6x11.7		Stamped top left -- Hastings Work	removed (fr.album)
154	9.2x12.05	April 13, 1909	Stamped top right -- APR 13 1909, stamped on album -- Hastings Work; top right -- Dredge No 8	removed (fr.album)
155	8.9x12		Top centre -- Heeley Falls.; stamped bottom right -- APR ?? (faded) 1910	removed (fr.album)
156	8.95x11.6	June 1910	On album -- Lock Pit Site June 1910	removed (fr.album)
157	9x11.8	June 1910	On album -- Lock Pit Site June 1910; stamped top left -- JUN 1910, stamped top centre -- Hastings Work	removed (fr.album)
158	9.1x11.8	April 13, 1909	On album -- APRIL 13/09 Dredge 38, HASTING, ONT	removed (fr.album)
159	9.1x11.75	April 13, 1909	On album -- APRIL 13/09 Dredge 38, HASTING, ONT	removed (fr.album)
160	9.2x11.9	April 13, 1909	On album -- APRIL 13/09 DRedge #8 HASTINGS ONT	removed (fr.album)
161	9.2x11.6	April 13, 1909	On album -- APRIL 13/09 DRedge #8 HASTINGS ONT.	removed (fr.album)
162	8.1x10.75			removed (fr.album)
163	8.4x13.6		Stamped top centre -- Rosedale Work	removed (fr.album)
164	8.1x13.6			removed (fr.album)
165	8.2x11		Top centre -- 38; on album -- DRILL BoaT #1 RosedALe WORK 1910	removed (fr.album)
166	8.15x13.65	November 20, 1908	On album -- N. entrance Walls Nov. 20/08; on album stamped -- Rosedale Work	removed (fr.album)
167	8.1x13.7		On album -- Jim Powell's Gang	removed (fr.album)
168	8.1x12.8	November 20, 1908	On album -- Lock, Nov 20/08; stamped on album -- Rosedale Work	removed (fr.album)
169	8.05x12.6	November 20, 1908	On album -- Looking west from S. Entrance Pier Nov 20/08	removed (fr.album)
170	8.1x13.5			removed (fr.album)
171	8.1x13.6			removed (fr.album)
172	8.05x13.5		On album -- Moonlight from office verandah	removed (fr.album)
173	8.2x13.4		On album -- View of Co Wharf; stamped on album -- Rosedale Work	removed (fr.album)
174	8.1x13.6		On album -- ?? Keep; stamped on album -- Rosedale Work	removed (fr.album)
175	8x13.55		On album -- Pete	removed (fr.album)
176	8.2x13.8		Stamped top centre -- Cobourg	removed (fr.album)
177	8.2x13.85			removed (fr.album)
178	8.5x14	May 11, 1909	Bottom left -- Dredge being built at Hastings, Ont. May 11 '09	removed (fr.album)
179	8.5x13.85	August 22, 1910	Top right -- 8/22/10; bottom left -- Work on Canal Hastings, Ont	removed (fr.album)
180	8.1x13.65			removed (fr.album)
181	8x13.7			removed (fr.album)
182	8.1x13.6		Stamped bottom centre -- Rosedale Work	removed (fr.album)
183	8.8x14		Stamped top right -- Cobourg Work; top right -- 1910; bottom left -- Krieghoff CoBourg; on album -- Derrick No 9 and Tug D and G	removed (fr.album)
184	9.1x11.8	April 26, 1909	Stamped top right -- APR 26 1909; top left -- Dredge No 8	removed (fr.album)
185	9.1x11.8	December 10, 1909	Stamped bottom right -- DEC 10 1909; stamped top centre -- Hastings Work	removed (fr.album)
186	9.25x11.9	December 10, 1909	Stamped bottom left -- DEC 10 1909; stamped top right -- Hastings Work	removed (fr.album)
187	9.1x11.9	December 10, 1909	Stamped bottom left -- DEC 10 1909; stamped top centre -- Hastings Work	removed (fr.album)
188	8.8x14.55	September 4, 1914	On album -- South End C. N. R. Diversion Sept. 4th, 1914; stamped on album -- Section No. 3, Severn Division, Trent Canal	removed (fr.album)
189	9.25x14.65	September 4, 1914	On album -- South End C. N. R. Diversion. Sept 4th, 1914; stamped on album -- Section No. 3, Severn Division, Trent Canal	removed (fr.album)
190	9x14.5	September 4, 1914	On album -- South End C. N. R. Diversion. Sept 4th, 1914; stamped on album -- Section No. 3, Severn Division, Trent Canal	removed (fr.album)
191	8.9x14.6	October 24, 1914	On album -- Stephen's House Oct. 24/14; stamped on album -- Section No. 3, Severn Division, Trent Canal	removed (fr.album)
192	8.45x13.8	May 20, 1909	Top right -- May 20, 1909; bottom -- CRIB #1. COBOURG BREAKWATER May 20-09	removed (fr.album)
193	8.5x14	May 11, 1909	Bottom -- Building the Dredge Hastings Ont May 11 "09. 52 men employed	removed (fr.album)

194	8.45x13.85		Centre right -- CANAL, HASTINGS, O	removed (fr.album)
195	13.9x8.1		Stamped top centre -- Farran's Point, Work	removed (fr.album)
196	8.2x13.25		Stamped top centre -- Farran's point, Work	removed (fr.album)
197	8x13.7		Stamped top centre -- Farran's Point, Work; top left -- Concrete Block's 1911	removed (fr.album)
198	7.9x13.5		Stamped top right -- Farran's Point, Work	removed (fr.album)
199	8.9x14.5	September 26, 1914	Stamped on album -- Hastings Work; on album -- Dredge # 8 on Ways, Hastings. Sept 26th 1914	removed (fr.album)
200	8.9x14.5	September 26, 1914	Stamped on album -- Hastings Work; on album -- Dredge No. 8 on Ways, Hastings. Sept 26th 1914	removed (fr.album)
201	8.9x14.45	September 4, 1914	Stamped on album -- Section No. 3, Severn Division, Trent Canal; on album -- Company's Office September 4th, 1914	removed (fr.album)
202	9x14.6	September 4, 1914	Stamped on album -- Section No. 3, Severn Division, Trent Canal; on album -- Clearing C. N. R. Diversion. Sept 4th 1914	removed (fr.album)
203	8.15x12.7	November 10, 1908	On album -- Looking west E. Entrance Pier Nov. 10-1908	removed (fr.album)
204	8x13.8	June 23, 1909	Stamped top left -- Rosedale Work; on album -- Lock -- June 23-1909; stamped on album -- Rosedale Work	removed (fr.album)
205	7.8x13.75	June 23, 1909	Stamped top centre -- Rosedale Work; on album -- Lock June 23-1909	removed (fr.album)
206	8.9x11.8	April 23, 1912	Stamped top centre -- Hastings Work; stamped bottom left -- APR 23 1912	removed (fr.album)
207	8.65x11.5	April 23, 1912	Stamped top centre -- Hastings Work; stamped bottom left -- APR 23 1912	removed (fr.album)
208	9.15x11.9	November 9, 1912	Stamped top right -- Hastings Work Nov 9; top right -- 1912	removed (fr.album)
209	8.7x13.7		Stamped bottom centre -- Hastings Work; bottom right -- G. T. R. BRIDGE TRENT RIVER HASTINGS, ONT.	removed (fr.album)
210	14x8.1		On album -- Piling Opposite Dean's Wharf	removed (fr.album)
211	13.9x8.2		On album -- View Showing Rods	removed (fr.album)
212	13.9x8.2	September 14, 1906	On album -- Last of the Diving Sept 14-06	removed (fr.album)
213	13.9x8.2	September 15, 1906	On album -- 5. Dredging to 30' Sept. 15-06	removed (fr.album)
214	8.1x13.1		Stamped top left -- Farran's Point, Work	removed (fr.album)
215	8.2x13.7	November 23, 1911	Bottom centre -- F. Point Nov 23/11; stamped top centre -- Farran's Point, Work	removed (fr.album)
216	8.9x14.8		Stamped top centre -- Farran's Point, Work; centre left -- Company's Office	removed (fr.album)
217	8.8x13.9		Stamped bottom centre -- Hastings Work; bottom right -- TRENT CANAL, HASTINGS, ONT	removed (fr.album)
218	13.7x8.3	December 29, 1911	Stamped bottom right -- DEC 29 1911; stamped bottom left -- Hastings Work	removed (fr.album)
219	11.7x9.5	December 18, 1913	Stamped top right -- Hastings Work DEC 18 1913	removed (fr.album)
220	11.7x9.4	December 1, 1911	Stamped top centre -- Hastings Work DEC; top centre -- 1 1911; stamped bottom centre -- Hastings Work	removed (fr.album)
221	8.7x11.8	April 23, 1912	Stamped top centre -- Hastings Work; stamped bottom left -- APR 23 1912	removed (fr.album)
222	12.6x17.65	June 1915	On album -- Stephen's House Washago, June 1915; stamped on album -- Section No. 3, Severn Division, Trent Canal	removed (fr.album)
223	6x8.75	September 1915	On album -- Crib for Coffor Dam Hamlet, Ont. Sept/15; stamped on album -- Section No. 3, Severn Division; Trent Canal	removed (fr.album)
224	6.15x8.5	September 1915	On album -- Crib for Coffor Dam Hamlet, Ont. Sept/15; stamped on album -- Section No. 3, Severn Division; Trent Canal	removed (fr.album)
225	8.6x14.3		Stamped on album -- Section No. 3, Severn Division, Trent Canal	removed (fr.album)
226	8.3x13.8		Stamped top centre -- Rosedale Work	removed (fr.album)
227	8.75x13.8		Bottom right -- TRENT CANAL, HASTING'S ONT	removed (fr.album)
228	8.7x13.8		Stamped top left -- Rosedale Work	removed (fr.album)
229	8.4x13.8		Stamped top centre -- Rosedale Work	removed (fr.album)
230	8.3x13.7		On album -- Teaming Boiler + Engine; stamped on album -- Rosedale Work	removed (fr.album)
231	8.1x13.5		On album -- Vulcan Shovel; stamped on album -- Rosedale Work	removed (fr.album)
232	8.3x13.8	March 1908	On album -- Cleansing R of way March -08	removed (fr.album)
233	8.3x13.8		On album -- Rosedale Section Trent Canal; stamped on album -- Rosedale Work	removed (fr.album)
234	8.15x10.6			removed (fr.album)
235	8.2x14	August 20, 1907	On album -- River Quelle (sp?) Wharf. Que., Aug 20-07	removed (fr.album)

236	8.2x14	August 20, 1907	On album -- River Quelle (sp?)Wharf, Que. Aug 20-07	removed (fr.album)
237	8.2x14	August 20, 1907	On album -- River Quelle (sp?) Wharf, Que. Aug 20-07	removed (fr.album)
238	13.9x8.15		On album -- Back View of Concrete Wall. Before & After Plasting; stamped on album -- Three Rivers, Que.	removed (fr.album)
239	13.9x8.15		On album -- Back View of Concrete Wall. Before & After Plasting; stamped on album -- Three Rivers, Que.	removed (fr.album)
240	8.2x14		On album -- Str. Virginian; stamped on album -- Three Rivers, Que.	removed (fr.album)
241	8.2x13.9		On album -- Allan Line Str Virginian	removed (fr.album)
242	13.2x77		On album -- Loading Barge at Quarry	removed (fr.album)
243	7.65x13.2		On album -- Grondines Quarry	removed (fr.album)
244	7.7x13.7		On album -- Grondines Quarry	removed (fr.album)
245	7.8x13.2	October 1906	On album -- Driving Clusters in Deans Wharf. Oct 06	removed (fr.album)
246	8.2x14		Stamped on album -- Three Rivers, Que.	removed (fr.album)
247	8.9x14	June 1908	On album -- Break Cornwall Canal June 1908	removed (fr.album)
248	14x8.2		Stamped on album -- Three Rivers, Que.	removed (fr.album)
249	14x8.2		Stamped on album -- Three Rivers, Que.	removed (fr.album)
250	8.2x13.8	September 1907	On album -- Towing No 5 Plant -- below Quebec, Sept 1907	removed (fr.album)
251	8.2x13.9			removed (fr.album)
252	8.3x14		On album -- Dredge No 5 - River Quelle Wharf	removed (fr.album)
253	8.25x13.95			removed (fr.album)
254	13.75x8.25	September 1907	On album -- Sept 1907, Quebec Bridge - South Shore	removed (fr.album)
255	13.8x8.25	September 1907	On album -- Sept 1907, Quebec Bridge - North Shore	removed (fr.album)
256	8.2x14		On album -- Guests from Lauintine House, River Quelle Wharf 1907	removed (fr.album)
257	8.2x14		On album -- Crew Dredge #5 River Quelle, Que.	removed (fr.album)
258	8.2x14		On album -- River Quelle Wharf, Que.	removed (fr.album)
259	8.2x14	August 20, 1907	On album -- River Quelle Wharf, Que. Aug 20-07	removed (fr.album)
260	8.2x13.95		On album -- St. Maurice River Bridge	removed (fr.album)
261	8.2x14			removed (fr.album)
262	8.1x14		On album -- Snow	removed (fr.album)
263	8.15x14		On album -- Moonlight on the Coteau	removed (fr.album)
264	8.3x14	September 20, 1906	On album -- Cluster #80 with Concrete Top. Sept 20-06	removed (fr.album)
265	8.3x14	September 15, 1906	On album -- Cluster #80, Bently Sand Filling, Sept 15-06	removed (fr.album)
266	7.9x13.5	September 15, 1906	On album -- Clam filling Behind Wall Sta. 1000' Sept 15-06	removed (fr.album)
267	8.25x14	September 1906	On album -- Concrete Wall front Deans Wharf, Three Rivers, Que. Sept 1906	removed (fr.album)
268	8.25x14.05		Stamped on album -- Three Rivers, Que.	removed (fr.album)
269	8.25x14.05		On album -- Tugs Horrden & Shamrock, Picking up Buoys	removed (fr.album)
270	8.25x14	October 19, 1906	On album -- View of Mixer Plant, Oct 19-06	removed (fr.album)
271	8.3x14.05		On album -- Stone Crusher Austin #3; stamped on album -- Three Rivers, Que.	removed (fr.album)
272	8.1x13.9	March 1907	On album -- # 6 + Tug Mar-07; stamped on album -- Three Rivers, Que.	removed (fr.album)
273	8.1x13.9	March 1907	On album -- Plant in Winter Quarters Mar-07	removed (fr.album)
274	8.1x13.9	March 1907	On album -- Fleet in Winter Quarters Mar-07	removed (fr.album)
275	8.2x14		On album -- Winter scene St Maurice River -07	removed (fr.album)
276	8.25x14.1		On album -- Tug Amy + Tow; stamped on album -- Three Rivers, Que.	removed (fr.album)
277	13.5x7.9		On album -- View of Clam from River; stamped on album -- Three Rivers, Que.	removed (fr.album)
278	8.2x14		On album -- Showing Binders between 1st + 2nd course of Concrete; stamped on album -- Three Rivers, Que.	removed (fr.album)
279	8.2x14		On album -- Last Section of Concrete Wall; stamped on album -- Three Rivers, Que.	removed (fr.album)

280	14x8.1		On album -- View of Clusters #92 East; stamped on album -- Three Rivers, Que.	removed (fr.album)
281	8.2x14		On album -- Preparing to Drive Clusters in Deans Wharf; stamped on album -- Three Rivers, Que.	removed (fr.album)
282	7.7x13.15	September 19, 1906	On album -- Rods in Deans Wharf Sept.19.06	removed (fr.album)
283	7.55x13.3	September 19, 1906	On album -- Rods in Deans Wharf Sept 19-06	removed (fr.album)
284	13.9x8.1		On album -- Loading Supply Scows for Mixer	removed (fr.album)
285	14x8.2		On album -- Loading Supply Scows for Mixer	removed (fr.album)
286	13.85x8.2	August 18, 1906	On album -- Showing Stone Filling objected to by Govt. Inspector Aug 18-06; stamped on album -- Three Rivers, Que.	removed (fr.album)
287	13.85x8.15		On album -- Showing Stone Filling objected to by Govt. Inspector Aug 18-06; stamped on album -- Three Rivers, Que.	removed (fr.album)
288	8.2x13.95	September 20, 1906	On album -- Sawing Last Pile Sept 20-06; stamped on album -- Three Rivers, Que.	removed (fr.album)
289	13.9x8.1		On album -- View of Back Moulds; stamped on album -- Three Rivers, Que.	removed (fr.album)
290	13.9x8.1	August 1906	On album -- Guide Piles S. E. End of Wharf Aug-06; stamped on album -- Three Rivers, Que.	removed (fr.album)
291	13.95x8.25		On album -- Plumbs. Culled by Inspector; stamped on album -- Three Rivers, Que.	removed (fr.album)
292	13.9x8.2		On album -- Driving Sheet Piles, In front of Dean's Wharf	removed (fr.album)
293	14x8.25		On album -- Three River "Nimrods"	removed (fr.album)
294	7.7x13.25		On album -- Loading Barge at Quarry	removed (fr.album)
295	8.1x13.65			removed (fr.album)
296	8.8x14.5			removed (fr.album)
297	8.7x14.6	1910	On album -- View Looking West From Office Rosedale Ont. 1910	removed (fr.album)
298	7.95x13.8	June 22, 1909	On album -- South Bank STA. 80 June 22/09; stamped top centre -- Rosedale Work	removed (fr.album)
299	9x14	June 1908	On album -- 2 Views. Break in Cornwall Canal June 1908; stamped bottom right -- R. Douglas MARLBOROUGH ST. CORNWALL.	removed (fr.album)
300	8.9x14			removed (fr.album)
301	14x8.2		Stamped on album -- Three Rivers, Que.	removed (fr.album)
302	13.9x8.15		Stamped on album -- Three Rivers, Que.	removed (fr.album)
303	13.95x8.15			removed (fr.album)
304	8.9x13.95	June 1908	On album -- Break in Cornwall Canal, June 1908; bottom left -- Douglas.	removed (fr.album)
305	9x14	June 1908	On album -- Break in Cornwall Canal June 1908	removed (fr.album)
306	8.7x14		Bottom -- HON. JAMES BUREAU. F.S. TOURIGNY. MAYOR. M. FARMER. THREE RIVERS CONFLAGRATION; on album -- Three Rivers Five June 1908	removed (fr.album)
307	11.8x16.65			removed (fr.album)
308	14.5x8.65		Top centre -- Mould Work for Dam; stamped, top centre -- Rosedale Work	removed (fr.album)
309	9.1x14.7		Stamped, bottom centre -- Rosedale Work	removed (fr.album)
310	8.25x13.55		Stamped, top centre -- Rosedale Work	removed (fr.album)
311	8.1x13.7		Stamped, top left -- Rosedale Work	removed (fr.album)
312	12.05x16.6	October 6, 1899	On album -- Canal Entrance, view from station 790. Section 13 -- Soulanges Canal	removed (fr.album)
313	11.3x17.35	August 29, 1899	On album -- Lock Gate Lifter in Canal Entrance. Section 13 -- Soulanges Canal	removed (fr.album)
314	12x16.75	October 25, 1899	On album -- Dyke at St Regis bar, view from East crib	removed (fr.album)
315	11.6x17.1	October 25, 1899	On album -- Dyke at St Regis bar, view from island north of channel	removed (fr.album)
316	8.8x14.35		Top left -- Mould work for Dam; stamped, bottom centre -- Rosedale Work	removed (fr.album)
317	8.05x13.65		Stamped, top centre -- Rosedale Work	removed (fr.album)
318	8.2x13.7		Top left -- Company's Boarding House; Stamped, top centre -- Rosedale Work	removed (fr.album)
319	8.9x14.8		Top left -- The Dam Completed; stamped, top centre -- Rosedale Work	removed (fr.album)
320	8x13.15		Stamped, top left -- Farran's Point, Work	removed (fr.album)
321	8x13.25	1911	Top right -- 1911; stamped, top right -- Farran's Point, Work	removed (fr.album)
322	8.9x14.8	1912	Top centre -- 1912; stamped, top centre -- Farran's Point, Work	removed (fr.album)



323	8.2x13.2	1912	Top right -- 1912; stamped, top left -- Farran's Point, Work	removed (fr.album)
324	16.6x24.2		Top right -- Form Work Dam; stamped, top right -- Rosedale Work	removed (fr.album)
325	9x14.5	October 1914	On album -- Belleville Wharf; stamped on album -- BELLEVILLE HARBOUR WORK	removed (fr.album)
326	8.8x14.35		Top centre -- Dump Seours on Dry Dock 1914; stamped, bottom centre -- BELLEVILLE HARBOUR WORK	removed (fr.album)
327	12.8x17.8		Poor; tear (3.6 cm long) starting at top edge 10.1 cm R; tear (1.5 cm long) at left edge 6.2 cm T; surface creased at several occasions, the longest starting at left edge 4.7 cm T; slightly soiled along edges; surface grime and abrasion	removed (fr.album)
328	8.7x14.3		Stamped on album -- Section No. 3, Severn Division, Trent Canal	removed (fr.album)
329	8.2x14		Bottom centre -- Belleville Wharf; stamped on album -- Section No. 3, Severn Division, Trent Canal	removed (fr.album)
330	8x13.8			removed (fr.album)
331	8.15x13.5	September 1908	On album -- Vulcan Shovel taking out foundation for N. Lock wall Sept -08; stamped on album -- Rosedale Work	removed (fr.album)
332	8.05x13.6	October 10, 1908	On album -- View through Lock pit from St 65	removed (fr.album)
333	8.1x13.6	October 10, 1908	On album -- View of Lock bottom; stamped on album -- Rosedale Work	removed (fr.album)
334	8.1x13.8	September 1915	On album -- Cofferdam Crib for Centre Pier Hamlet. Rd Bridge	removed (fr.album)
335	8.1x13.9	September 1914	On album -- Cofferdam Crib for Centre Pier Hamlet Rd Bridge	removed (fr.album)
336	8.1x13.8	September 1915	On album -- Cofferdam Crib for Centre Pier Hamlet Rd Bridge	removed (fr.album)
337	9.8x12.1	March 1916	On album -- Rock Excavation	removed (fr.album)
338	8.65x14.3	Winter 1914	On album -- Muskoka Rd Cut after heary storm	removed (fr.album)
339	8.9x14.3	Winter 1914	On album -- Muskoka Rd Cut after Heary Storm	removed (fr.album)
340	8.6x14.2	Winter 1914	On album -- Muskoka Road Cut after heary storm	removed (fr.album)
341	8.6x14.2		On album -- Heary Storm Winter 1914. Muskoka Road. C. M. R. Water Tank	removed (fr.album)
342	8.8x14.3	November 26, 1914	On album -- East Dumpou (sp?) Lake	removed (fr.album)
343	8.8x14.3	November 26, 1914	On album -- Muskoka Road Cut	removed (fr.album)
344	8.75x14.2	November 26, 1914	On album -- Muskoka Road Cut; stamped on album -- Section No. 3, Severn Division, Trent Canal	removed (fr.album)
345	9.1x14.55	October 29, 1914	On album -- Muskoka Road Cut; stamped on album -- Section No. 3, Severn Division, Trent Canal	removed (fr.album)
346	9x14.6	October 29, 1914	On album -- Muskoka Road Cut; stamped on album -- Section No. 3, Severn Division, Trent Canal	removed (fr.album)
347	8.9x14.5	October 29, 1914	On album -- Muskoka Road Cut; stamped on album -- Section No. 3, Severn Division, Trent Canal	removed (fr.album)
348	8.95x14.5	October 29, 1914	On album -- Erecting Drag Line, Washago; stamped on album -- Section No. 3, Severn Division, Trent Canal	removed (fr.album)
349	8.9x14.6	October 29, 1914	On album -- Camp Washago; stamped on album -- Section No. 3, Severn Division, Trent Canal	removed (fr.album)
350	8.55x14	March 23, 1905	Bottom right -- Hastings Ont.; Bottom left -- Workshop of Randolph Macdonald + Co; bottom right -- 1909	removed (fr.album)
351	13.7x8.5	August 22, 1910	Stamped top centre -- Hasting Work; bottom centre -- 8/22/10	removed (fr.album)
352	7.75x13.6		Stamped top centre -- Rosedale Work	removed (fr.album)
353	7.9x13.5			removed (fr.album)
354	12.8x17.75	June 1915	On album -- Canal Entrance. Washago, from Muskoka Road Bridge, June 1915; Stamped on album -- Section No. 3, Severn Division, Trent Canal	removed (fr.album)
355	12.8x17.8	June 1915	On album -- Canal Entrance, Washago, From Muskoka Road Bridge June 1915; Stamped on album -- Section No. 3, Severn Division, Trent Canal	removed (fr.album)
356	13.6x8.1		On album -- Office Verandah; stamped centre -- Rosedale Work; centre, above stamp -- The Office	removed (fr.album)
357	8.1x13.7	September 1908	Stamped, top centre -- Rosedale Work; on album -- Dredge #7 Sta 69. Sept/08	removed (fr.album)
358	13.9x7.95		Stamped on album -- Rosedale Work; Stamped top centre -- Rosedale Work; top centre -- No. 3	removed (fr.album)
359	8x13.8	July 19, 1908	On album -- Dredge #7 Rocking through Old Rosedale Rocks, July 29/08; stamped, top left -- Rosedale Work	removed (fr.album)
360	8x12.8	June 15, 1908	On album -- Dredge #7 Casting June 15-08, abt Sta 35; stamped on album -- Rosedale Work	removed (fr.album)
361	8.25x13.8	June 11, 1908	Stamped, top centre -- Rosedale Work; on album -- Dredge Casting June 11/08	removed (fr.album)
362	7.8x13.8	August 3, 1908	On album -- Baldwin Loco "Making Grade" Aug 3/08	removed (fr.album)
363	8.1x13.8	August 3, 1908	On album -- Vulcan Shovel Sta -- 63, Aug 3/08	removed (fr.album)
364	7.9x13.8	August 3, 1908	On album -- August 3-1908; stamped on album -- Rosedale Work	removed (fr.album)

365	8x13.6	September 1908	On album -- Vulcan Shovel Sept 1908; stamped on album -- Rosedale Work	removed (fr.album)
366	8.25x13.6	September 1908	On album -- Office Sept 1908; stamped on album -- Rosedale Work	removed (fr.album)
367	8.8x14.4	1913	Top centre -- Dredge #5 on Crib Foundation 1913; stamped bottom centre -- BELLEVILLE HARBOUR WORK	removed (fr.album)
368	8.8x14.3	November 1913	Top centre -- Dry Dock Nov 1913; stamped bottom centre -- BELLEVILLE HARBOUR WORK	removed (fr.album)
369	8.6x14.5	November 1913	Stamped top centre -- BELLEVILLE HARBOUR WORK; bottom centre -- Tug Wm G. Fox Nov 1913	removed (fr.album)
370	8.8x14.4	November 1913	Stamped bottom centre -- BELLEVILLE HARBOUR WORK; top -- Dredge no. 5 + Tug Fox Nov 1913	removed (fr.album)
371	11.7x9	April 25, 1909	On album -- Heeley Falls, APRIL 25/09	removed (fr.album)
372	11.7x9.1	April 25, 1909	On album -- Heeley Falls, APRIL 25/09	removed (fr.album)
373	9.1x11.8	December 6, 1909	Stamped bottom right -- DEC 6 1909; stamped top centre -- Hastings Work	removed (fr.album)
374	9.1x11.75	December 6, 1909	Stamped top left -- Hastings Work; stamped bottom left -- DEC 6 1909	removed (fr.album)
375	8.55x14.3	July 21, 1916	On album -- P+P Loco's + Cars Laid up. July 21/1916	removed (fr.album)
376	8.5x14.3	August 8, 1916	On album -- P+P Loco Crane Loaded ready to ship. Aug 8/1916	removed (fr.album)
377	8.5x14.3	August 4, 1916	On album -- Result of fire on Drag Line Aug 4th/1916	removed (fr.album)
378	14.4x8.5			removed (fr.album)
379	14.45x8.4			removed (fr.album)
380	11.8x17.15	March 4, 1898	On album -- Stone dressing yard -- Point Ann March 4th 1898	removed (fr.album)
381	11.8x16.6	March 4, 1898	On album -- Stone dressing yard -- Point Ann March 4th 1898	removed (fr.album)
382	10.3x7.55			removed (fr.album)
383	7.5x9.7			removed (fr.album)
384	7.8x9.9		On album -- Soulanges Canal	removed (fr.album)
385	7.5x10.1		On album -- Soulanges Canal	removed (fr.album)
386	7.3x10	December 11, 1903	On album -- Winter quarters R. St Mauree (sp?). Three Rivers, Que.; On album -- 453	removed (fr.album)
387	7.8x10.1	May 21, 1904	On album -- Booms (illegible) at stern of steamer Tugela to receive Southern Pine. Three Rivers, Que.	removed (fr.album)
388	7.6x9.9	May 31, 1904	On album -- Booms (illegible) to receive Southern Pine from Steamer Tugela, Three Rivers, Que.	removed (fr.album)
389	7.45x10	May 31, 1904	On album -- View from Ice Breaker of booms (illegible) to receive Southern Pine from Steamer Tugela, Three Rivers, Que.	removed (fr.album)
390	7.6x10.1	June 19, 1904	On album -- At the side of Shawinigan Falls, Que.	removed (fr.album)
391	7.4x10	June 19, 1904	On album -- Lower portion. Shawinigan Falls, Que.	removed (fr.album)
392	7.4x9.5	June 19, 1904	On album --Upper Portion, Shawinigan Falls, Que.	removed (fr.album)
393	8.75x13.9	1910	Stamped top left section -- Cobourg Work; below stamp -- 1910; bottom right corner -- Krieg hof (sp?) photo, Cobourg; on album -- Mould for Light House	removed (fr.album)
394	8.15x13.8		Stamped top centre -- Cobourg	removed (fr.album)
395	14x8.2			removed (fr.album)
396	7.75x13.8		Stamped top right -- Cobourg; top right -- G. T. R Ferry; Printed bottom left -- C. T. R. FERRY COBOURG ONT HUSTON PHOTO	removed (fr.album)
397	9.55x12	March 1916	On album -- P+P. Shovel Below Lock March 1916	removed (fr.album)
398	9.65x11.9	March 1916	On album -- Laying Rip. Rap. March 1916	removed (fr.album)
399	9.7x12	March 1916	On album -- Drilling from ice bottom piers Lake Couchiching, March 1916	removed (fr.album)
400	9.65x12	March 1916	On album -- Rock Excavation March 1916	removed (fr.album)
401	8.5x12	September 7, 1916	On album -- Lock Pit Sept 7/1916	removed (fr.album)
402	8.45x14.4	August 8, 1916	On album -- View from C. N. R. Looking West Aug 8/1916	removed (fr.album)
403	8.45x14.3		On album -- P+P. Office + Camps. Aug 8/1916; on photo to mark building -- (illegible) Camp Cook (illegible) Office	removed (fr.album)
404	14.35x8.5	July 21, 1916	On album -- P+P. Shovel Laid up about July 21/1916	removed (fr.album)
405	8.55x15	October 19, 1916	On album -- Rock excav Sta 1753 Oct 19/1916	removed (fr.album)
406	8.6x15	October 17, 1916	On album -- Drag Line, Sta 1661. Oct 17/1916	removed (fr.album)

407	8.4x14.1	September 7/ 1916	On album -- S. Side Lock Sept 7/1916	removed (fr.album)
408	8.3x14.3	September 7, 1916	On album -- N. Side Lock Pit sept 7/1916	removed (fr.album)
409	12x17.5	July 27, 1899	On album -- Looking East from 90 ft N. Station 718, Section 12 -- Soulanges Canal	removed (fr.album)
410	12.2x16.95	August 12, 1899	On album -- General view looking East from Station 565 N. Section 9 -- Soulanges Canal	removed (fr.album)
411	9.5x12	August 12, 1899	On album -- 3 rd Letting in of water -- view looking towards south wall from centre of canal, Section 13 -- Soulanges Canal	removed (fr.album)
412	12.4x16.75	August 12, 1899	On album -- Power House -- front view, Section 8, Soulanges Canal	removed (fr.album)
413	11.65x17.1	August 14, 1899	On album -- Dredge No 6 making channel through dam to supply water more rapidly for filling. Section 13 -- Soulanges Canal	removed (fr.album)
414	12x17.15	August 14, 1899	On album -- Water passing dam at station 572. Section 9 -- Soulanges canal	removed (fr.album)
415	11.6x16.8	August 29, 1899	On album -- Lock Gate Lifter in Canal Entrance. Section 13 -- Soulanges Canal	removed (fr.album)
416	11.85x16.7	October 25, 1899	On album -- Dyke at St Regis bar, view from East crib	removed (fr.album)
417	12.3x16.8	August 22, 1899	On album -- First Lockage of vessels, Soulanges Canal. Tug Mabel Macdonald & Dredge No. 4 in Guard Lock. Section 13 -- Soulanges Canal	removed (fr.album)
418	9.85x12.3	August 22, 1899	On album -- Dredge No. 4 & tug Mabel Macdonald passing out from Guard Lock. Section 13 -- Soulanges Canal	removed (fr.album)
419	7.6x10.35		On album -- Soulanges Canal	removed (fr.album)
420	7.65x10.4		On album -- Soulanges Canal	removed (fr.album)
421	7.5x10.45		On album -- Soulanges Canal	removed (fr.album)
422	7.6x10.4		On album -- Sinking Dredge No. 6	removed (fr.album)
423	11.9x17.5	July 27, 1899	On album -- Looking East from 90 ft N. Station 718. Section 12 -- Soulanges Canal	removed (fr.album)
424	12.5x16.95	July 27, 1899	On album -- Looking West from 70 ft S. station 713. Section 12 -- Soulanges Canal	removed (fr.album)
425	11.5x17.4	August 12, 1899	On album -- General view looking East from Station 565. Section 9 -- Soulanges Canal	removed (fr.album)
426	11.9x16.8	August 12, 1899	On album -- General view looking East from station 555 N. Section 9 -- Soulanges Canal	removed (fr.album)
427	9.5x11.9	August 12, 1899	On album -- 3rd Letting in of water -- view from south wall. Section 13 -- Soulanges Canal	removed (fr.album)
428	9.55x11.75	August 12, 1899	On album -- 3rd Letting in of water -- view Looking towards south wall, from centre of canal. Section 13 -- Soulanges Canal	removed (fr.album)
429	11.95x16.5	August 12, 1899	On album -- Power House -- front view. Section 8 -- Soulanges Canal	removed (fr.album)
430	11.9x16.5	August 12, 1899	On album -- One sct of Turbines at Power House. Section 8 -- Soulanges Canal	removed (fr.album)
431	11.8x16.7	August 14, 1899	On album -- Dredge No. 6 making channel through dam to supply water more rapidly for filling. Section 13 -- Soulanges Canal	removed (fr.album)
432	11.8x17.1	August 14, 1899	On album -- Water passing dam at station 572. Section 9 -- Soulanges Canal	removed (fr.album)
433	12.1x16.7	August 22, 1899	On album -- Dredge No. 6 making channel through dam for vessels (illegible). Section 13 -- Soulanges Canal	removed (fr.album)
434	12.25x16.65	August 22, 1899	On album -- First Lockage of vessels. Soulanges Canal, Tug Mabel Macdonald & Dredge No. 4 in Guard Lock, scores just entering. Section 13 -- Soulanges Canal	removed (fr.album)
435	9.8x12.15	August 22, 1899	On album -- Dredge No. 4 & tug Mabel Macdonald entering Guard Lock -- 1st Lockage, Section 13 -- Soulanges Canal	removed (fr.album)
436	9.8x12	August 22, 1899	On album -- Dredge No. 4 & tug Mabel Macdonald passing out from Guard Lock. Section 13 -- Soulanges Canal	removed (fr.album)
437	12x17.4	May 24, 1899	On album -- Slide North Bank -- Station 559. Section 9 -- Soulanges Canal	removed (fr.album)
438	11.7x16.8	May 24, 1899	On album -- Slide North Bank -- Station 559. Section 9 -- Soulanges Canal	removed (fr.album)
439	12.2x17	May 24, 1899	On album -- Slide North Bank -- Station 559. Section 9 -- Soulanges Canal	removed (fr.album)
440	12.2x16.9	May 24, 1899	On album -- Slide North Bank -- Station 559. Section 9 -- Soulanges Canal	removed (fr.album)
441	12.4x16.7	June 2, 1899	On album -- Letting in water above Guard Lock. Section 13 -- Soulanges Canal	removed (fr.album)
442	12.3x16.8	June 2, 1899	On album -- Letting in water above Guard Lock. Section 13 -- Soulanges Canal	removed (fr.album)
443	12.1x17.5	June 3, 1899	On album -- General View East of Lock. Section 13 -- Soulanges Canal	removed (fr.album)
444	11.9x16.9	June 10, 1899	On album -- Slide North Bank -- station 551. Section 9 -- Soulanges Canal	removed (fr.album)
445	12.35x16.8	June 10, 1899	On album -- Slide North Bank -- station 549-555. Section 9 -- Soulanges Canal	removed (fr.album)
446	12.2x17.1	June 10, 1899	On album -- Slide North Bank -- station 549-555. Section 9 -- Soulanges Canal	removed (fr.album)

447	12.2x16.85	June 10, 1899	On album -- Coteau Rapids from Old Fort	removed (fr.album)
448	12x17.1	July 13, 1899	On album -- Upper end of Waste Channel. Section 13 -- Soulanges Canal	removed (fr.album)
449	12.5x16.8	July 14, 1899	On album -- Arches of Road Bridge. Section 13 -- Soulanges Canal	removed (fr.album)
450	12.35x16.9	July 26, 1899	On album -- Lower end of Lock & Raceway. Section 13 -- Soulanges Canal	removed (fr.album)
451	8.6x13.8	August 1917	Label -- Sec. 3 - Severn Div. Aug. 1917. Class of Material below Lock; verso, right edge -- Class of material below Lock. Aug/17	removed (fr.album)
452	8.9x13.8	August 1917	Label -- Sec. 3 - Severn Div. Aug. 1917. Upper Breast Wall Forms and View of Lock; verso, right edge -- Upper breast wall forms & view of Lock Aug/17/	removed (fr.album)
453	9.1x14.6	July 28, 1915	Label -- Sec. 3 - Severn Div. July 28, 1915. Dragline operating just South of C. N. R. Bridge over canal; verso, right -- July 28/15. Drag Line operating just south of C. N. R Bridge over Canal	removed (fr.album)
454	8.75x13.7	August 1917	Label -- Sec. 3 - Severn Div. Aug. 1917. Upper Entrance to Lock and Temporary Bridge; verso right -- W. Upper Entrance to Lock & Temporary Bridge. Aug/17	removed (fr.album)
455	8.7x13.8	August 1917	Label -- Sec. 3 - Severn Div. Aug. 1917. Looking North from St. 1635; verso, right -- Looking north from Sta. 1635 Aug/17; verso centre -- 31	removed (fr.album)
456	8.8x13.8	August 1917	Label -- Sec. 3 - Severn Div. Aug. 1917. Lower end of Locks; verso, right -- Lower end Lock Aug/17; verso centre -- 31	removed (fr.album)
457	8.75x13.75	August 1917	Label -- Sec. 3 - Severn Div. Aug. 1917. Swift Power House; verso, right -- Swift Power House Aug. 17/17; verso centre -- 31	removed (fr.album)
458	12.3x16.8	November 6, 1917	Label -- Sec. 3 - Severn Div. -- Nov. 6/17. Entrance Piers Lake Couchiching; stamped verso top centre -- NOV 6-1917; stamped verso centre -- Section No. 3, Severn Division, Trent Canal; verso top left -- Entrance Piers Lake Couchiching	removed (fr.album)
459	12.35x16.8	November 6, 1917	Label -- Sec. 3 - Severn Div. -- Nov. 6/17. Rock Dam Station 1704; stamped verso top centre -- NOV 6-1917; stamped verso centre -- Section No 3, Severn Division, Trent Canal; verso top left -- Rock Dam Sta. 1704	removed (fr.album)
460	12.25x16.8	November 6, 1917	Label -- Sec. 3 -- Severn Div. -- Nov. 6/17. Muskoka Road Wharf; stamped verso top centre -- NOV 6-1917; stamped verso centre -- Section No. 3, Severn Division, Trent Canal; verso centre left -- Muskoka Road Wharf	removed (fr.album)
461	12.1x16.6	November 6, 1917	Label -- Sec. 3 -- Severn Div. -- Nov. 6/17. Dam "A" East Branch Severn River; stamped verso top centre -- NOV 6-1917; stamped verso centre -- Section No. 3, Severn Division, Trent Canal; verso centre -- Dam A. East Branch Severn River	removed (fr.album)
462	12.3x16.7	November 6, 1917	Label -- Sec. 3 -- Severn Div. -- Nov. 6/17. Dam "F" West Branch Severn River; stamped verso top centre -- NOV 6-1917; stamped verso centre -- Section No. 3, Severn Division, Trent Canal; verso top centre -- Dam F. West Branch. Severn River	removed (fr.album)
463	12.25x16.7	November 6, 1917	Label -- Sec. 3 -- Severn Div. -- Nov. 6/17. Upper Breast Wall; stamped verso top centre -- NOV 6-1917; stamped verso centre -- Section No. 8, Severn Division, Trent Canal; verso centre left -- Upper Breast Wall	removed (fr.album)
464	12.3x16.85	November 6, 1917	Label -- Sec. 3 -- Severn Div. -- Nov. 6/17. Lower Approach to Lock (in pencil: entrance from); stamped verso top centre -- NOV 6-1917; stamped centre -- Section No. 3, Severn Division, Trent Canal; verso top left -- Lower approach to Lock	removed (fr.album)
465	12.3x16.8	November 6, 1917	Label -- Sec. 3 -- Severn Div. -- Nov. 6/17. Sparrow Lake Chute; stamped verso top centre -- NOV 6-1917; stamped verso centre -- Section No. 3, Severn Division, Trent Canal; verso centre left -- Sparrow Lake Chute	removed (fr.album)
466	12.2x16.7	November 6, 1917	Label -- Sec. 3 -- Severn Div. -- Nov. 6/17. Main Channel Sparrow Lake Chute; stamped verso top centre -- NOV 6-1917; stamped verso centre -- Section No. 3, Severn Division, Trent Canal; verso centre left -- Main Channel. Sparrow Lake Chute	removed (fr.album)
467	12.2x16.65	November 6, 1917	Label -- Sec. 3 -- Severn Div. -- Nov. 6/17. Lower End Back Channel S. L. Chute; stamped verso top centre -- NOV 6-1917; stamped verso centre -- Section No. 3, Severn Division, Trent Canal; verso top centre -- Lower End Back Channel	removed (fr.album)
468	12.15x16.65	November 6, 1917	Label -- Sec. 3 -- Severn Div. -- Nov. 6/17. Centre Pier Hamlet Road Bridge; stamped verso top centre -- NOV 6-1917; stamped verso centre -- Section No. 3, Severn Division, Trent Canal; verso top centre -- Centre Pier Hamlet Road Bridge	removed (fr.album)
469	12.2x16.7	June 23, 1920	Label -- Sec. 3 -- Severn Div. -- Jun. 23/20. Stream of water thru C. N. R. bank just after explosion; verso top right -- 5; verso centre -- Trent Canal -- Severn Div. -- Sec. 3. June 23/20 -- Stream of water thru C. N. R. embankment just after explosion.	removed (fr.album)
470	12.3x16.7	June 23, 1920	Label -- Sec. 3 -- Severn Div. -- Jun. 23/20. Stream of water thru C. N. R. bank 15 minutes after explosion; verso top right -- 1; verso centre -- Trent Canal -- Severn Div. -- Sec. 3. June 23/20 -- Stream of water 15 min. after explosion at C. N. R. embankment	removed (fr.album)
471	12.25x16.6	June 23, 1920	Label -- Sec. 3 -- Severn Div. -- Jun. 23/20. Stream of water thru C. N. R. bank 58 minutes after explosion; verso top right -- 7; verso centre -- Trent Canal -- Severn Div. -- Sec. 3. June 23/20 -- Stream of water 58 min. after explosion, gates at head of stream almost submerged	removed (fr.album)

472	12.25x16.7	June 23, 1920	Label -- Sec. 3 -- Severn Div. -- Jun. 23/20. View of cut thru C. N. R. embankment upstream from East Bank; verso top right -- 8; verso centre -- Trent Canal -- Severn Div. -- Sec. 3. June 23/20 -- View of cut thru C. N. R. embankment looking upstream from east bank	removed (fr.album)
473	8.8x14.6	June 22, 1922	Label -- Sec. 3 -- Severn Div. -- Jun. /22. Camp Site at Hamlet Bridge; stamped verso top left -- C1; centre left -- Camp at Hamlet	removed (fr.album)
474	9.2x15.2	June 1922	Label -- Sec. 3 -- Severn Div. -- June 1922. Moving West Span of Hamlet Bridge; stamped verso bottom right -- 87	removed (fr.album)
475	9.2x15.2	June 1922	Label -- Sec. 3 -- Severn Div. -- June 1922. Moving West Span of Hamlet Bridge; stamped verso bottom right -- 87	removed (fr.album)
476	9.2x15	June 1922	Label -- Sec. 3 -- Severn Div. -- June 1922. Moving West Span of Hamlet Bridge; stamped verso bottom right -- 87; verso centre right -- June 1922	removed (fr.album)
477	9.25x15.2	June 1922	Label -- Sec. 3 -- Severn Div. -- June 1922. Moving West Span of Hamlet Bridge; stamped verso bottom right -- 87; verso top centre -- Jun 1922	removed (fr.album)
478	8.85x14.6	October 1922	Label -- Sec. 3 -- Severn Div. -- Oct. 1922. Completed Hamlet Bridge; stamped verso top left -- C1; verso bottom right -- Hamlet Bridge	removed (fr.album)
479	8.8x14.6	October 1922	Label -- Sec. 3 -- Severn Div. -- Oct. 1922. Completed Hamlet Bridge; stamped verso top left -- C1; verso bottom right -- Hamlet Bridge	removed (fr.album)
480	14.6x8.85	October 1922	Label -- Sec. 3 -- Severn Div. -- Oct. 1922. Completed Hamlet Bridge; stamped verso bottom right -- C1; verso bottom centre -- Hamlet Bridge	removed (fr.album)
481	14.6x8.8	October 1922	Label -- Sec. 3 -- Severn Div. -- Oct. 1922. Completed Hamlet Bridge; stamped verso top left -- C1; verso bottom centre -- Hamlet Bridge. Oct. 1922	removed (fr.album)
482	11.6x7	?	Top centre -- Tug Sloth 1921; verso top centre -- June 1922; verso centre -- 12; stamped verso -- Bobcaygeon Contrast	removed (fr.album)
483	11.45x6.9	1921	Bottom -- Engine Room, Dredge No. 7 1921; stamped verso -- Bobcaygeon Contrast	removed (fr.album)
484	6.95x11.4	?	Top left -- Dredge No. 7 1921; verso right -- June 1922; verso bottom left -- 3; verso centre -- 12; stamped verso -- Bobcaygeon Contrast	removed (fr.album)
485	12.7x17.75	March 8, 1920	Label -- Bobcaygeon-Trent -- March 18, /20. Foundation Excavation New Retaining Wall from Upper End looking East; verso centre -- Excavating to rock for foundation of new Concrete Retaining Wall, replacing old Timber -- structure at right. View from upper end looking East. march 18th 1920	removed (fr.album)
486	12.7x17.75	April 16, 1920	Label -- Bobcaygeon-Trent -- Apr. 16, /20. Prepare Cribs for Cofferdam. Concrete Dam to replace Wood Dam; verso top -- Preparing Cribs for Cofferdam, new Concrete dam to be built between cribs shown and old Timber dam at right; verso centre left -- Apl. 16, 1920	removed (fr.album)
487	12.7x17.7	February 14, 1921	Label -- Bobcaygeon-Trent -- Feb. 14, /21. Sump hole below site of New Lock. Note peculiar character of rock, water leak thru seams at right; verso top -- Sump hole below site of New Lock -- looking East. Note peculiar character of rock formation, water coming up through seams at right. In April when river rose, the leaks increased and flooded out the cut.; verso centre left -- Feb. 14th 1921	removed (fr.album)
488	12.7x17.7	October 6, 1920	Label -- Bobcaygeon-Trent -- Oct. 6, /20. Concrete Work for New Dam, Mixer at extreme right on shore. Work being carried from North to South Shore; verso top -- Concrete work for new dam. Remains of old Timber dam at left. In foreground, concrete apron. To right, forms for concrete piers. Mixer on shore at extreme right -- concrete carried by dump buckets on cars -- placed by derrick. Work being carried from North Shore to South. Oct, 6th 1920	removed (fr.album)
489	12.7x17.7	February 14, 1921	Label -- Bobcaygeon-Trent -- Feb. 14, /21. Sump hole at Lock, 2-8" pumps working had to put in 14" pump later, old lock extreme left; verso top -- Another view of Sump hole - 2 pumps -- 8" working hard -- Later put in a 14" pump. Old Lock can be seen at extreme left - new Lock to go to right of camera. Feb. 14th 1921	removed (fr.album)
490	9.85x14.5	April 9, 1929	Label -- Turner Dock Apr. 9/29. Crib No. 3 in position.	in album
491	9.8x15.4	April 9, 1929	Label -- Turner Dock Apr. 9/29. Crib No. 3 all cribs in place.	in album
492	12.7x17.75	March 5, 1921	Label -- Bobcaygeon-Trent -- Mar. 5, /21. Pump-house & Cofferdam at East end of Lock Pit. Verso top -- Pump house & cofferdam at east end of lock pit. Verso centre left -- Mar. 5th 1921	removed (fr.album)
493	12.7x17.8	February 14, 1921	Label -- Bobcaygeon-Trent -- Feb. 14, /21. Sump hole East End of Lock Pit, Excavating for lower mitre sills and Lock Walls.; verso top -- Sump hole at East end of Lock Pit, excavating for lower mitre sills Lock Walls; verso centre left -- Feb. 14th 1921	removed (fr.album)
494	12.7x17.7	March 16, 1921	Label -- Close up of Beds of Rock lower end of Lock Pit, Note thickness of beds and seams between.; verso top -- Close-up of beds of rock of lower end of Lock Pit. Note thickness of beds, and seams between; verso centre left -- March 16th - 1921	removed (fr.album)
495	12.75x17.75	March 16, 1921	Label -- Bobcaygeon-Trent -- Mar. 16, /21. Limestone formation encountered in Lock Pit. Note seams between beds, boulder -- clay formation over rock; verso top -- Limestone formation encountered in Lock Pit. Note seams between beds and boulder -- clay formation over rock; verso bottom left -- March 16th 1921	removed (fr.album)
496	12.7x17.7	April 20, 1921	Label -- Bobcaygeon-Trent -- Apr. 20, /21. Looking West from upper end of Lock. Excavating for Emergency Gate; verso top -- Looking West from upper end of Lock. Excavating for emergency Gate; verso centre left -- Apr. 20th 1921	removed (fr.album)

497	12.75x17.75	May 7, 1921	Label -- Bobcaygeon-Trent -- May 7, /21. Pouring section of South Lock Wall; verso top -- Pouring section of South Lock Wall; verso centre left -- May 7th 1921	removed (fr.album)
498	12.75x17.8	May 7, 1921	Label -- Bobcaygeon-Trent -- May 7, /21. Excavating Upper Mitre Sill Lock; verso top -- Excavating at Upper Mitre Sill of Lock; verso centre left -- May 7th 1921	removed (fr.album)
499	12.8x17.75	July 18, 1921	Label -- Bobcaygeon-Trent -- July 18, /21. Looking W along South upper entrance Wall, leveling bottom to grade; verso top -- view towards West, along South upper entrance wall Leveling bottom to grade. At right shows end of North entrance Wall curving off to meet core wall from dam; verso centre left -- July 18th 1921	removed (fr.album)
500	12.6x17.8	July 20, 1921	Label -- Bobcaygeon-Trent -- July 20, /21. Looking East from Upper Entrance at first opening of new Canal; verso top -- View towards East from upper entrance at first opening of new Canal; verso centre left -- July 20th 1921	removed (fr.album)
501	12.7x17.8	June 1921	Label -- Bobcaygeon-Trent -- 1921. Looking East shows Rock Bolts in rock lock bottom ready for concrete floor; verso top -- June 1921-- looking east, showing rock bolts in rock at bottom of Lock ready to receive concrete floor. No 7 Dredge working towards lock with derrick at site of old lock	removed (fr.album)
502	8.9x14.7	1921	Label -- Bobcaygeon-Trent -- 1921. View from North Bank across lower side of New Dam; verso top -- Bobcaygeon Dam. View from North bank across lower side of New dam	removed (fr.album)
503	6.95x11.5	June 1922	Label -- Bobcaygeon Sec. -- June 1922. Breaking Rock on Dredge Dipper; verso right -- June 1922; verso bottom left -- 6; stamped verso centre -- Bobcaygeon Contrast; verso centre -- 12	removed (fr.album)
504	7x11.65	June 1922	Label -- Bobcaygeon Sec. -- June 1922. Breaking Rock on Dredge Dipper; verso right -- June 1922; verso bottom left -- 3; verso centre -- 12; stamped verso centre -- Bobcaygeon Contrast	removed (fr.album)
505	8.4x14.1	June 1922	Label -- Bobcaygeon-Trent -- June 1922. Crib after Launching; verso top left -- after launching	removed (fr.album)
506	8.35x14	June 1922	Label -- Bobcaygeon-Trent -- June 1922. Launching Crib; verso top -- Launching Crib for E. End section June 1922	removed (fr.album)
507	8.35x14.1	June 1922	Label -- Bobcaygeon-Trent -- June 1922. Crib ready to Launch; verso top left -- ready to launch	removed (fr.album)
508	12.3x16.7	August 10, 1922	Label -- Bobcaygeon-Trent -- Aug. 10, /22. Looking West from Highway Bridge; verso centre -- Bobn Sec. Looking E from Highway Bridge Aug 10/22	removed (fr.album)
509	12.2x16.7	August 10, 1922	Label -- Bobcaygeon-Trent -- Aug. 10, /22. Looking West from Highway Bridge; verso centre -- Bobcaygeon Section Looking W from Highway Bridge Aug 10/22	removed (fr.album)
510	12.2x16.7	August 10, 1922	Label -- Bobcaygeon-Trent -- Aug. 10, /22. Looking East from Highway Bridge; verso centre -- Bobn Sect. Looking E. from N. side Highway Bridge Aug 10/22	removed (fr.album)
511	12.25x16.8	August 10, 1922	Label -- Bobcaygeon-Trent -- Aug. 10, /22. Looking East from Highway Bridge; verso centre -- Bobn Sec. Looking West from S. Side Highway Bridge Aug 10/22	removed (fr.album)
512	12.1x16.8	August 10, 1922	Label -- Bobcaygeon-Trent -- Aug. 10, /22. Highway Bridge & South Approach; verso centre -- Bobn Sect. Highway Bridge + S. Approach Aug 10/22	removed (fr.album)
513	12.1x16.8	August 10, 1922	Label -- Bobcaygeon-Trent -- Aug. 10, /22. Highway Bridge; verso centre -- Bobn Sect. Highway Bridge Aug, 10/22	removed (fr.album)
514	12.2x16.8	July 23, 1923	Label -- Bobcaygeon-Trent -- July 23, /23. Lock & Upper Entrance; verso -- 6 1/2 x4, #133. Trent Canal -- Bobcaygeon Section. July 23/23 -- View of lock and upper entrance from bridge. Property of Randolph Macdonald Co. Cuts to be made by us & charged to advertiser. Picture of Macdonald Dredge to come -- cut to be made of it & charged to advet; verso bottom right -- crap (?)	removed (fr.album)
515	12.15x16.8	July 23, 1923	Label -- Bobcaygeon-Trent -- July 23, /23. Lock & Bridge from Upper Entrance; verso centre -- Trent Canal -- Bobcaygeon Section July 23/23 -- View of lock & bridge from upper entrance	removed (fr.album)
516	12.35x16.75	July 23, 1923	Label -- Bobcaygeon-Trent -- July 23, /23. Lower Entrance N. E. from Hotel Roof; verso centre -- Trent Canal -- Bobcaygeon Section. July 23/23 -- View of lower entrance looking north east from hotel roof	removed (fr.album)
517	12.2x16.7	July 23, 1923	Label -- Bobcaygeon-Trent -- July 23, /23. Lower Entrance; top left -- L. E.; verso centre -- Trent canal -- Bobcaygeon Section. July 23/23 -- View of lower entrance	removed (fr.album)
518	12.25x16.85	July 23, 1923	Label -- Bobcaygeon-Trent -- July 23, /23. Lock & Upper Entrance from Roof of Bank Montreal; verso centre -- Trent Canal -- Bobcaygeon Section. July 23/23 -- Lock & upper entrance from roof of Bank of Montreal	removed (fr.album)
519	12.2x16.7	July 23, 1923	Label -- Bobcaygeon-Trent -- July 23, /23. Upper Entrance to Lock; verso centre -- Trent Canal -- Bobcaygeon Section. July 23/23 -- Upper entrance to lock and bridge looking N. E.	removed (fr.album)
520	12.25x16.8	July 23, 1923	Label -- Bobcaygeon-Trent -- July 23, /23. Upper Entrance & End of Dam; top left -- UP; verso centre -- Trent Canal -- Bobcaygeon Section. July 23/23 -- Upper entrance and end of dam	removed (fr.album)
521	12.2x16.7	July 23, 1923	Label -- Bobcaygeon-Trent -- July 23, /23. Upper Entrance to Lock looking N. E. showing Bridge; verso centre -- Trent Canal -- Bobcaygeon Section. July 23/23 -- View of upper entrance to lock	removed (fr.album)
522	12.2x16.8	July 23, 1923	Label -- Bobcaygeon-Trent -- July 23, /23. Lower Side of Dam looking South; verso centre -- Trent Canal -- Bobcaygeon Section. July 23/23 -- View of lower side of dam looking south	removed (fr.album)
523	12.2x16.75	July 23, 1923	Label -- Bobcaygeon-Trent -- July 23, /23. Dam and Dry Dock; verso centre -- Trent Canal -- Bobcaygeon Section. July 23/23 -- View of dam & dry dock	removed (fr.album)
524	12.2x16.8	July 23, 1923	Label -- Bobcaygeon-Trent -- July 23, /23. Upstream Side of Dam looking N. E.; verso centre -- Trent Canal -- Bobcaygeon Section. July 23/23 -- Upstream side of dam looking N. E.	removed (fr.album)

525	12.2x16.8	July 23, 1923	Label -- Bobcaygeon-Trent -- July 23, /23. Lower Side of Dam & Culverts at D. D.; verso centre -- Trent Canal -- Bobcaygeon Section. July 23/23 -- View of lower side of dam & culverts at dry dock	removed (fr.album)
526	12.15x16.7	July 23, 1923	Label -- Bobcaygeon-Trent -- July 23, /23. Upper Entrance to Dry Dock; verso centre -- Trent Canal -- Bobcaygeon Section. July 23/23 Upper Entrance to Dry Dock	removed (fr.album)
527	12.25x16.7	July 23, 1923	Label -- Bobcaygeon-Trent -- July 23, /23. North of D. D. & Culvert looking W.; verso centre -- Trent Canal -- Bobcaygeon Section. July 23/23 -- Looking west at dry dock & culvert north of same	removed (fr.album)
528	12.2x16.8	July 23, 1923	Label -- Bobcaygeon-Trent -- July 23, /23. Concrete Wall above D. D. on North Shore of River; verso centre -- Trent Canal -- Bobcaygeon Section. July 23/23. Concrete wall above Dry dock on North Shore of river	removed (fr.album)
529	12.2x16.8	July 23, 1923	Label -- Bobcaygeon-Trent -- July 23, /23. Looking N. W. at Dry Dock and Wall above Same; verso centre -- Trent Canal -- Bobcaygeon Section. July 23/23 -- Looking N. W. at Dry dock and wall above same	removed (fr.album)
530	8.3x10.8			removed (fr.album)
531	10.4x8.3			removed (fr.album)
532	10.8x8.2		Verso top centre -- Lift Bridge, Looking South; verso top centre -- THE RANDOLPH MACDONALD CO'Y., LIMITED; stamped verso -- Bobcaygeon Contrast	removed (fr.album)
533	9.2x11.55	August 1923	Label -- Georgetown Highway 810 -- Aug. 1923. Showing stony character of material. Two teams on rooter plow, one team with stone boat; verso top -- Georgetown -- Acton Highway Contiacs (sp?) 810. Showing stony character of material -- two teams on rooter plow with stone boat -- August 1923-; stamped verso bottom right -- 28	removed (fr.album)
534	9.2x11.55	August 1923	Label -- Georgetown Highway 810 -- Aug. 1923. Making Fill with wheel Scrapers; verso top -- Making fill with wheelers; stamped verso bottom right -- 28	removed (fr.album)
535	9.2x11.55	August 1923	Label -- Georgetown Highway 810 -- Aug. 1923. Grading Street in Georgetown cutting down sidewalk to conform to new grade of road; verso top centre -- Grading street in Georgetown, cutting down sidewalk to conform to new grade of road; stamped verso bottom right -- 28	removed (fr.album)
536	9.2x11.5	August 1923	Label -- Georgetown Highway 810 -- Aug. 1923. Making fill with wheel Scrapers. One team collecting loose rock with stone boat; verso top centre -- Making fill with wheelers - one team collecting loose rock with stone boat	removed (fr.album)
537	9.2x11.55	August 1923	Label -- Georgetown Highway 810 -- Aug. 1923. Bad material for Wheel Scrapers! Collecting largest stone with stone boat; verso top centre -- Bad material for Wheel Scrapers! Collecting largest of stone with stone boat; stamped verso bottom right -- 28	removed (fr.album)
538	9.2x11.55	August 1923	Label -- Georgetown Highway 810 -- Aug. 1923. Looking East towards Georgetown Camp on turn of road, showing loose rock being buried in fill; verso top centre -- Looking East towards Georgetown -- camp on turn of road -- showing loose rock being buried in a fill; stamped verso bottom right -- 28	removed (fr.album)
539	9.2x11.55	August 1923	Label -- Georgetown Highway 810 -- Aug. 1923. Showing clay and loose rock in wheeler cut; verso top centre -- Showing clay and loose rock in wheeler cut; stamped verso bottom right -- 28	removed (fr.album)
540	9.2x11.6	August 1923	Label -- Georgetown Highway 810 -- Aug. 1923. Making a fill with wheelers, Note amount of loose rock; verso top centre -- Making a fill with wheelers - note amount of loose rock; stamped verso bottom right -- 28	removed (fr.album)
541	9.2x11.5	August 1923	Label -- Georgetown Highway 810 -- Aug. 1923. Grading & Widening Highway. Note amount of loose rock. Telephone poles were on side of original road; verso top centre -- Grading and widening highway. Note amount of loose rock. Telephone poles were on side of original road; stamped verso bottom right -- 28	removed (fr.album)
542	9.2x11.5	August 1923	Label -- Georgetown Highway 810 -- Aug. 1923. Burying loose rock on side of fill; verso top centre -- Burying loose rock on side of fill; stamped verso bottom right -- 28	removed (fr.album)
543	17.85x12.9			in album
544	17.85x12.8			in album
545	17.7x12.85			in album
546	8.9x14.6	August 26, 1926	Top -- EAST ABUTMENT WINDEMERE AUG -- 26/26; bottom centre -- COFFERDAM	in album
547	8.9x14.7	August 25, 1926	Top -- EAST ABUTMENT WINDEMERE AUG -- 25/26; bottom centre -- COFFERDAM	in album
548	8.8x14.65	August 25, 1926	Top -- EAST ABUTMENT WINDEMERE AUG -- 25/26; bottom centre -- COFFERDAM	in album
549	9.1x14.5	August 26, 1926	Top -- EAST ABUTMENT -- WINDEMERE AUG -- 26/26	in album
550	9.2x15	August 25, 1926	Top -- WINDEMERE GRADE AUG 25/26; bottom left -- SUB - CONTRACT	in album
551	14.9x9	August 25, 1926	Top -- GRADING WINDEMERE; bottom -- NELSON & JOHNSON SUB. AUG -- 25/26	in album
552	9.1x15			in album
553	8.25x13.95	November 12, 1928	Label -- Little Current Dredging Nov. 12/28. Derr. #2 cleaning loose material from channel	in album
554	8.25x13.9	November 23, 1928	Label -- Little Current Ontario Nov. 23/28. General View	in album
555	8.25x13.95	November 23, 1928	Label -- Little Current Dredging Nov. 23/28. Drilling in channel Derr. #2 cleaning 2nd cut.	in album

556	8.3x14	December 11, 1928	Label -- Little Current Dredging Dec. 11/28. Capsized Dump Scow	in album
557	8.3x14	December 11, 1928	Label -- Little Current Dredging Dec. 11/28. Capsized Dump Scow	in album
558	8.3x14	December 12, 1928	Label -- Little Current Dredging Dec. 12/28. Righting Capsized Dump Scow	removed (fr.album)
559	8.4x14.35	February 7, 1921	Label -- 2/7/21 Q & R. Quarry East Face From loading track N of Crusher; verso -- 2/7/21 Q&R Quarry East Face from loading track north of Crusher; stamped verso bottom right -- H11	removed (fr.album)
560	8.6x13.25	February 7, 1921	Label -- 2/7/21 Blue's Quarry East Face Looking South; verso -- 2/7/21 Blue's Quarry East or Upper face. Looking south; stamped verso top left -- H 11	removed (fr.album)
561	8.45x14.35	February 7, 1921	Label -- 2/7/21 Q & R Quarry North Face From loading track near Crusher; verso -- 2/7/21 Q & R Quarry North Face From loading track near Crusher; stamped verso top centre -- H 11	removed (fr.album)
562	20.55x24	1926-27	Bottom centre -- WINDEMERE 1926-27; verso top right -- Windemere Cut off for dept. Public Hwy 1926-7; verso top left corner -- Windemere Cut off; verso centre -- #2. 4 Cols. Cut 4" Deep Herald: stamp of Superior Engravers, Ltd.	removed (fr.album)
563	20.8x24.15	1926-27	Bottom centre -- WINDEMERE 1926-27; verso top -- Windemere cut off for dept. Public Highways 1926-7; verso centre left -- Windemere cut off; verso centre right -- stamp of Superior Engravers, Ltd.	removed (fr.album)
564	8.85x14.9	May 23, 1935	Label -- DRILL BOAT #3, TWO MILE NARROWS. May 23rd, 1935. Rock piled in water & on far bank at right of picture excavated by Derrick to test spacing, drill holes 4' 8" x 7' 6" ranges.	removed (fr.album)
565	8.85x14.8	1935	Label -- SEVEN - MILE NARROWS: looking S. W., Before widening. 1935	removed (fr.album)
566	9.05x14.6	1935	Label -- TWO MILE NARROWS: 1935; verso along right edge -- 2 Mile Narrows 1935 --; stamped verso bottom right -- 11	removed (fr.album)
567	20.6x24.25	1926-27	Bottom left -- WINDEMERE 1926-27; verso top centre -- Windemere Cut off for dept. Public Highway; verso bottom left -- Windemere cut off; verso centre left -- #1; stamp of Superior Engravers, Ltd.	removed (fr.album)
568	8.25x13.95	November 23, 1928	Label -- Turner Dock Nov. 23/28. Crib No. 1	in album
569	8.25x13.95	November 28, 1928	Label -- Turner Dock Nov. 28/28. Crib No. 2	in album
570	8.25x13.95	November 28, 1928	Label -- Turner Dock Nov. 28/28. Crib No. 2 & Derr. #2	in album
571	8.25x13.95	November 29, 1928	Label -- Turner Dock Nov. 29/28. Crib No. 2	in album
572	8.25x13.95	December 11, 1928	Label -- Turner Dock Dec. 11/28. Crib No. 2 Sinking	in album
573	8.25x13.95	December 18, 1928	Label -- Turner Dock Dec. 18/28. Crib No. 2 ready for filling. Crib 4 left for Winter	in album
574	8.25x13.95	December 18, 1928	Label -- Turner Dock Dec. 18/28. Crib No. 2 ready for filling	in album
575	8.25x13.95	December 18, 1928	Label -- Turner Dock Dec. 18/28. Crib No. 4 left for Winter	in album
576	8.3x14	November 12, 1928	Label -- Turner Dock Nov. 12/28. Drilling for Crib Seats	in album
577	8.35x14	23-Nov-28	Label -- Turner Dock Nov. 23/28. Dredging at Commercial Dock	in album
578	8.3x14	November 12, 1928	Label -- Turner Dock Nov. 12/28. Dredging at Commercial Dock	in album
579	8.3x14	November 23, 1928	Label -- Turner Dock Nov. 12/28. General View	in album
580	8.35x14	December 18, 1928	Label -- Turner Dock Dec. 18/28. Crib No. 4 left for Winter	in album
581	9.9x15.4	April 9, 1929	Label -- Turner Dock April 9/29. Crib No. 3	in album
582	8.5x14	April 9, 1929	Label -- Turner Dock Apr. 9/29 Print 1. Crib 3 ready for launching	in album
583	8x13.7	April 9, 1929	Label -- Turner Dock Apr. 9/29 Print 2. Crib No. 3 launching	in album
584	8.3x13.9	April 9, 1929	Label -- Turner Dock Apr. 9/29 Print 3. Crib No. 3 after launching the above 3 prints were taken within one minute from 1 to 3	in album
585	8.85x14.8	June 5, 1935	Label -- Looking towards PARRY SOUND, C. N. Ry. BRIDGE -- to Depot Harbour. June 5th, 1935; verso -- June 5/35. Looking towards Parry Sound -- C. N. Ry. Bridge -- to Depot Harbour. Boats have to use the left-hand passage thru' bridge because of rock shoal which extends from right of picture to red buoy shown in left foreground. (illegible) given to A. Anderson June 21/35; stamped verso top right -- 86	removed (fr.album)
586	8.85x14.45	August 22, 1927	Label -- Caledonia Bridge. Temporary trestle Water level 608.2 8/22/27; verso top -- Temp. Trestle. 8/22/27. Water level 608.2; stamped verso bottom right -- F33; stamped left -- 12 1972; verso centre -- #5547 -- Wed -- 11AM; verso top left -- illegible; verso centre left section -- illegible stamp	removed (fr.album)
587	8.95x14.3	September 15, 1927	Label -- Caledonia Bridge for Dept. of Public Highways. Sept. 15, 1927; stamped verso bottom right -- D99; verso top right -- Sept. 15/27; verso bottom centre -- Caledonia Bridge for Dept. Public Highways 1927	removed (fr.album)
588	9.1x14.4	September 15, 1927	Label -- Caledonia Bridge. Sept. 15, 1927; stamped verso bottom right -- D99; verso top right -- Sept. 15/27	removed (fr.album)



589	9x14.5	July 25, 1927	Label -- Caledonia Bridge. West side Temporary Trestle looking North, 10 A.M. 7/25/27. Water level 613.0; stamped verso top left -- 69; verso right edge -- west side Temp. Trestle looking north. 7/25/27. 10A.M. water level 613.0 Caledonia Bridge	removed (fr.album)
590	9x14.6	August 24, 1927	Label -- Caledonia Bridge. Aug. 24/27; stamped verso bottom right -- D69; stamped verso left edge -- AUG 24 1927; verso centre -- Caledonia 1927	removed (fr.album)
591	8.9x14.9	June 5, 1935	Label -- TWO MILE NARROWS: June 5th, 1935. Looking from Parry Sound end Showing rock pile excavated by Derrick; stamped verso top left -- 98; verso right -- June 5/35. 2-mile Narrows, looking from P. Sound end showing rock pile excavated by derrick	removed (fr.album)
592	8.95x14.9	May 23, 1935	Label -- TWO MILE NARROWS, May 23rd, 1935. Looking N. from deck of derrick. Rock piled on shore drilled 4'8" between holes -- 7'6" between ranges. Owen Clam; stamped verso bottom right -- 44; verso top -- Two-Mile Narrows -- May 23/35. Looking N. from deck of derrick -- Rock piled on shore was drilled 4"-8" between holes -- 7'-6" between ranges excavated by Owen Clam shown	removed (fr.album)
593	8.85x14.9	May 21, 1935	Label -- TWO-MILE NARROWS: May 21st, 1935. Rock in foreground placed there years ago by previous contractor; stamped verso bottom right -- 87; verso top -- Two-Mile Narrows -- May 21/35. Looking North. Points of rock shown in foreground was placed there years ago by previous contractor	removed (fr.album)
594	8.9x14.9	May 21, 1935	Label -- TWO-MILE Narrows: May 21st, 1935. Looking North. Points of rock shown in foreground placed there years ago by previous contractor; stamped verso bottom right - 87; verso top -- Two-Mile Narrows -- May 21/35. Looking North. From left -- Black smith shop -- Drill Boat to dump scow. Rock piled at right was placed there years ago by previous contractor.	removed (fr.album)
595	8.85x14.8	June 5, 1935	Label -- SEVEN - MILE NARROWS Looking towards Parry Sound (North) June 5th, 1935; stamped verso bottom right -- 13; verso top -- June 5/35. Seven Mile Narrows looking towards Parry Sd. -- (North)	removed (fr.album)
596	8.8x14.8	June 5, 1935	Label -- SEVEN - MILE NARROWS: looking towards Georgian Bay. June 5th, 1935; stamped verso top left -- 98; verso right -- June 5/35. Seven-Mile Narrows -- looking towards Georgian Bay. Copy given to A. Anderson -- June23/35 also copy of photo showing Area 8. (other "illegible" print on hand today)	removed (fr.album)
597	8.8x14.8	June 5, 1935	Label -- SEVEN MILE NARROWS looking towards Parry Sound. June 5th, 1935; stamped verso bottom right --13; verso left -- June 5/35. 7-Mile Narrows. Looking towards Parry Sound	removed (fr.album)
598	8.85x14.8	June 5, 1935	Label -- SEVEN MILE NARROWS: from Georgian Bay end. Two units on left to be removed to permit widening of channel. June 5th, 1935; stamped verso bottom right -- 86; verso right -- June 5/35. Seven-Mile Narrows from Georgian Bay end. The two units on left to be removed to permit widening of channel	removed (fr.album)
599	8.95x14.6	May 23, 1935	Label -- DRILL BOAT NO. 3 & DERRICK "WHITBY" at Two-Mile Narrows. May 23rd, 1935; stamped verso bottom right -- 11; verso top -- Drill Boat No. 3 & Derrick "Whitby" at 2-Mile Narrows -- May 23/35	removed (fr.album)
600	8.9x14.85	May 21, 1935	Label -- DRILL BOAT #3 Derrick "WHITBY" working at TWO-MILE NARROWS. May 21st, 1935; stamped verso bottom right -- 87; verso top -- Drill Boat No 3 & Derrick "Whitby" working at TWO-MILE Narrows -- May 21/35	removed (fr.album)
601	8.8x14.8	June 5, 1935	Label -- Looking South at Two-Mile Narrows. DERRICK casting blasted rock on Island shore. June 5th, 1935; stamped verso top left -- 98; verso right -- June 5/35. Looking South at Two-Mile Narrows -- Derrick casting blasted rock on Island shore	removed (fr.album)
602	10.25x15.35	May 6, 1929	Label -- 5/6/29. Turner from channel showing S. S. Sweden unloading coal and moored 1/2 way along dock we are building; stamped verso top left -- 31; verso right -- 5/6/29. Turner from channel showing S. S. Sweden unloading coal and moored half way along dock we are building. We were ordered to move derrick out of the way and last two days digging trench	removed (fr.album)
603	10.1x15.3	May 6, 1929	Label -- 5/6/29. Turner Dock. Mixing plant for shear Leg Wall; stamped verso top left -- 31; verso right -- 5/6/29. Mixing Plant for shear Leg wall. Turner Dock	removed (fr.album)
604	10.25x15.4	May 6, 1929	Label -- 5/6/29. Shear Leg Wall and Mixing Plant; stamped verso top left -- 31; verso right -- 5/6/29 Shear Leg Wall and Mixing Plant	removed (fr.album)
605	10.3x15.4	May 6, 1929	Label -- 5/6/29. Shear Leg wall, Coal Bridge. Two boats at Coal Dock, S. S. Sweden at West end; stamped verso top left -- 31; verso right -- 5/6/29. Shear Leg wall, Coal Bridge. Two boats at Coal Dock, S. S. Sweden at West end	removed (fr.album)
606	10.25x15.35	May 6, 1929	Label -- 5/6/29. Turner dock showing high water. S. S. Sweden moored at dock and stopping us from working at trench in Back Portes Leg wall; stamped verso top left -- 31; verso right -- 5/6/29. Turner dock showing high water. S. S. Sweden moored at dock we are building and stopping us from working at trench for Back Portes Leg wall	removed (fr.album)
607	8.3x14.1	October 1926	Label -- Placing three lengths (75') of 18" spiral, rivetted steel pipe in 20' of water. Grimsby, Ont., Oct., 1926; verso right -- lacing three lengths (75ft) of 18" spiral rivetted steel pipe in 20' of water. Grimsby, Ont. Oct 1926	removed (fr.album)
608	8.2x14	October 1926	Verso right -- lacing three lengths (75ft) of 18" spiral rivetted Steel pipe in 20' of water. Grimsby, Ont. Oct 1926	removed (fr.album)
609	8.9x14.9	June 30, 1937	Stamped verso top left -- 17; verso right -- June 30/37. Reginald on Collingwood Dock Starb Side	removed (fr.album)
610	8.9x14.9	June 30, 1937	Label -- Reginald on Collingwood Dock, Starboard side aft. June 30, 1937; stamped verso top left -- 17; verso right -- Reginald on Collingwood Dock Starboard Side aft. June 30/37	removed (fr.album)

611	8.95x14.9	June 30, 1937	Stamped verso top left -- 17; verso right -- June 30/37. Reginald on Collingwood Dock wheel stern bearing and Rudder starb side	removed (fr.album)
612	8.9x14.9	June 30, 1937	Stamped verso top left -- 17; verso right -- June 30/37. Reginald on Collingwood Dock Starb Bow	removed (fr.album)
613	8.8x14.8	May 21, 1935	Stamped verso bottom right --87; verso top -- TWO-MILE NARROWS -- May 21/35. Looking South. Showing rock deposited years ago by previous contractor	removed (fr.album)
614	8.9x14.9	May 21, 1935	Stamped verso bottom right -- 88; verso top -- Two- Mile Narrows -- May 21/35. Derrick Clamming rock into scow	removed (fr.album)
615	8.9x14.95	May 21, 1935	Stamped verso top left -- 87; verso top -- Two-Mile Narrows -- May 21/35. Rock in foreground placed there years ago by previous contractor	removed (fr.album)
616	8.1x14.5	?	Stamped verso bottom right -- E33; verso right -- span #4, 8/22/27. Pound 8/25/27	removed (fr.album)
617	9.15x14.5	September 15, 1927	Stamped verso bottom right -- D99; stamped verso top centre -- NOTE: NEW ADDRESS 1130 BAY ST. Phone Kingsdale 2806 THE RANDOLPH MACDONALD CO'Y., LIMITED; verso right -- Sept. 15/27	removed (fr.album)
618	9.15x14.6	September 15, 1927	Stamped verso bottom right -- D99; verso top right -- sept. 15/27	removed (fr.album)
619	8.25x13.9	November 1926	Verso right -- Pump house with addition. Grimsby, Ont. Nov. 1926	removed (fr.album)
620	10.2x15.2	June 7, 1921	Bottom left -- T. I. B/W 1921; verso top left -- 555; verso bottom centre -- Toronto Breakwater. JUN 7-1921	removed (fr.album)
621	8.3x14.1	1926	Verso right -- Pipes assembled on pier and moved to dredge on rafts. Grimsby, Ont., 1926	removed (fr.album)
622	10.8x15.4	May 6, 1929	Stamped verso top left -- 31; verso right -- 5/6/29. Turner dock from Little Current dock S. S. Sweden unloading coal at west end of coal dock. Our derrick was ordered ahead lost two days work	removed (fr.album)
623	11.75x7.05	1935	Stamped verso bottom left -- 2; verso top -- 1935 Devels (sp?) Ell	removed (fr.album)
624	6.35x9	1935	Stamped verso bottom right -- 110; verso right -- 1935 Devels (sp?) Ell	removed (fr.album)
625	8.8x11.7	1920	Top centre -- 15; verso top -- 15, Early September 1920 -- Excavating for foundation of dam. Old Structure to left	removed (fr.album)
626	8.8x11.6	September 1920	Top centre -- 20; verso top -- 20. Sept -- 1920 -- pumps for unwatering dam	removed (fr.album)
627	8.7x10.9	February 7, 1921	Stamped verso bottom right -- H11; verso -- 2/7/21. Blues Quarry, Centre Part, looking East over loading track	removed (fr.album)
628	14x8.2			removed (fr.album)
629	14x8.25			removed (fr.album)
630	9.2x12	March 3, 1916	Bottom right -- 3/3/16	removed (fr.album)
631	14x28			removed (fr.album)
632	9.9x12	March 3, 1916	Bottom right -- 3/3/16	removed (fr.album)
633	8.2 X 10.7	February 1920	Label -- Bobcaygeon, Ont. Feby. 1920. Erecting Cookery and Dining Camp using Gypsum Board for walls and roof.	in album
634	8.5 X 11.5	February 1920	Label -- Bobcaygeon, Ont. Feby. 1920. View of Dining Camp with kitchen attached on far side.	in album
635	8.5 X 11.5	February 1920	Label -- Bobcaygeon, Ont. Feby. 1920. At work on Store and Office Building. Cookery in background	removed (fr.album)
636	8.5 X 11.5	February 1920	Label -- Bobcaygeon, Ont. Feby. 1920. View from entrance to camp ground	removed (fr.album)
637	8.2 X 10.7	March 1920	Label -- Bobcaygeon, Ont. March 1920. Kitchen and Dining Camp, Roof papered walls painted over Gypsum Board.	removed (fr.album)
638	8.2 X 10.7	March 1920	Label -- Bobcaygeon, Ont. March 1920. Interior of Dining Camp Kitchen to left.	in album
639	8.2 X 10.7	April 1920	Label -- Bobcaygeon, Ont. April 1920. Erecting House, Gypsum Board covered with Neponset paper.	in album
640	8.2 X 10.7	February 1920	Label -- Bobcaygeon, Ont. Feby. 1920. Looking North across upstream side of old dam. Drydock at far end.	removed (fr.album)
641	7 X 11.8	February 1920	Label -- Bobcaygeon, Ont. Feby. 1920. Looking South across lower side of old dam.	removed (fr.album)
642	8.2 X 10.7	February 1920	Label -- Bobcaygeon, Ont. Feby. 1920. Looking South along lower side of old dam.	removed (fr.album)
643	8.8 X 11.2	February 1920	Label -- Bobcaygeon, Ont. Feby. 1920. Looking downstream from old dam on North end, water at low level.	removed (fr.album)
644	8.2 X 10.7	February 1920	Label -- Bobcaygeon, Ont. Feby. 1920. Upper Entrance old Canal looking E.	removed (fr.album)
645	7 X 11.5	February 1920	Label -- Bobcaygeon, Ont. Feby. 1920. Looking East from Highway Bridge across old Lock. Site of New Lock about 300' behind camera.	removed (fr.album)
646	9 X 11.9	June 1920	Label -- Bobcaygeon, Ont. June 1920. Looking East down old Canal, most of these beautiful trees had to be destroyed in building new Canal.	removed (fr.album)
647	8 X 10.5	April 1920	Label -- Bobcaygeon, Ont. April 1920. Looking upstream showing old timber retaining wall to be replaced with concrete wall.	removed (fr.album)
648	8.2 X 10.7	April 1920	Label -- Bobcaygeon, Ont. April 1920. Looking W. along line of Ditch to go behind new concrete retaining wall	removed (fr.album)
649	8.2 X 10.7	April 1920	Label -- Bobcaygeon, Ont. April 1920. Looking E. along line of ditch to go behind new concrete wall.	removed (fr.album)

650	8.2 X 10.7	April 1920	Label -- Bobcaygeon, Ont. April 1920. Excavating for new Wall looking West.	removed (fr.album)
651	8.2 X 10.7	April 1920	Label -- Bobcaygeon, Ont. April 1920. Looking W. along old retaining wall. Messrs Eason & Spence going over work.	removed (fr.album)
652	8.2 X 10.7	April 1920	Label -- Bobcaygeon, Ont. April 1920. Looking East along site of new wall, ditch behind to Left. Drilling for wall footings.	removed (fr.album)
653	8.2 X 10.7	April 1920	Label -- Bobcaygeon, Ont. April 1920. Looking West along line of new retaining wall.	removed (fr.album)
654	8.2 X 10.7	May 1920	Label -- Bobcaygeon, Ont. May 1920. Placing footings for new wall mixing by hand, looking East.	removed (fr.album)
655	9 X 11.5	June 1920	Label -- Bobcaygeon, Ont. June 1920. Placing concrete in retaining wall, looking East.	removed (fr.album)
656	9 X 11.5	June 1920	Label -- Bobcaygeon, Ont. June 1920. Placing concrete with London Mixer.	removed (fr.album)
657	9.4 X 11.9	June 1920	Label -- Bobcaygeon, Ont. June 1920. Looking E. along back of forms for retaining wall.	removed (fr.album)
658	9 X 11.5	October 1921	Label -- Bobcaygeon, Ont. Oct. 1921. Completed retaining wall and drain looking West.	removed (fr.album)
659	9 X 11.5	October 1921	Label -- Bobcaygeon, Ont. Oct. 1921. Looking W. from N. side of Dry dock at gate.	in album
660	9 X 11.5	October 1921	Label -- Bobcaygeon, Ont. Oct. 1921. Looking E. from N. upper end of drydock.	in album
661	8.2 X 10.7	April 1920	Label -- Bobcaygeon, Ont. April 1920. Old drydock, vessels still in dock. Gov't tug "Harwood"	removed (fr.album)
662	8 X 10.5	April 1920	Label -- Bobcaygeon, Ont. April 1920. After removing tug and houseboat. Looking W. prepare cofferdam.	in album
663	9.2 X 11.9	July 1920	Label -- Bobcaygeon, Ont. July 1920. Looking N.E. into old drydock which is being demolished. Erecting Derrick no. 4.	removed (fr.album)
664	8.7 X 11.3	July 1920	Label -- Bobcaygeon, Ont. July 1920. Derrick No. 4 starting to dismantle old Drydock.	removed (fr.album)
665	8.5 X 11	July 1920	Label -- Bobcaygeon, Ont. July 1920. Cleaning out old Drydock.	removed (fr.album)
666	8.7 X 11.3	July 1920	Label -- Bobcaygeon, Ont. July 1920. Excavating for mitre sills of Drydock.	removed (fr.album)
667	12 X 9	July 1920	Label -- Bobcaygeon, Ont. July 1920. Placing footing for section of W. Wall.	removed (fr.album)
668	9.3 X 11.8	August 1920	Label -- Bobcaygeon, Ont. Aug. 1920. Sill in place.	removed (fr.album)
669	8.8 X 11.3	August 1920	Label -- Bobcaygeon, Ont. Aug. 1920. Excavating for N. Wall of Drydock.	removed (fr.album)
670	12 X 9	August 1920	Label -- Bobcaygeon, Ont. Aug. 1920. Excavating for N. Wall Drydock.	removed (fr.album)
671	8.7 X 11.3	August 1920	Label -- Bobcaygeon, Ont. Aug. 1920. Excavating for N. Wall Drydock.	in album
672	9 X 11.4	August 1920	Label -- Bobcaygeon, Ont. Aug. 1920. Placing concrete in S. Wall.	in album
673	9 X 11.7	September 1920	Label -- Bobcaygeon, Ont. Sept. 1920. Excavating Junction D.D. & Dam.	in album
674	9 X 11.7	September 1920	Label -- Bobcaygeon, Ont. Sept. 1920. Move from S. Wall Drydock.	removed (fr.album)
675	9 X 11.7	September 1920	Label -- Bobcaygeon, Ont. Sept. 1920. Derrick No. 4 place concrete at N. end of Dam.	removed (fr.album)
676	9 X 11.7	September 1920	Label -- Bobcaygeon, Ont. Sept. 1920. D.D. Entrance walls completed. N. Wall & floor unfinished.	removed (fr.album)
677	8.9 X 11.3	August 1921	Label -- Bobcaygeon, Ont. Aug. 1921. Unwatering Drydock to complete having finished new lock.	removed (fr.album)
678	9 X 12	August 1921	Label -- Bobcaygeon, Ont. Aug. 1921. Preparing for floors and E. Wall of Drydock.	removed (fr.album)
679	8.5 X 11.5	August 1921	Label -- Bobcaygeon, Ont. Aug. 1921. Small box dam for unwatering drydock to complete.	removed (fr.album)
680	8.5 X 11.5	August 1921	Label -- Bobcaygeon, Ont. Aug. 1921. Concreting E. Wall of Drydock.	removed (fr.album)
681	8.5 X 11.5	August 1921	Label -- Bobcaygeon, Ont. Aug. 1921. Concreting N. Wall of Drydock.	removed (fr.album)
682	8.3 X 10.5	March 1920	Label -- Bobcaygeon, Ont. March 1920. Preparing cribs for lower cofferdam looking South. Old dam South.	removed (fr.album)
683	8.3 X 10.5	March 1920	Label -- Bobcaygeon, Ont. March 1920. Cribs for lower cofferdam.	removed (fr.album)
684	8.3 X 10.5	March 1920	Label -- Bobcaygeon, Ont. March 1920. Cribs for lower cofferdam.	removed (fr.album)
685	8.3 X 10.5	April 1920	Label -- Bobcaygeon, Ont. April 1920. Work on upper cofferdam taking soundings for crib, looking W.	removed (fr.album)
686	8.3 X 10.5	April 1920	Label -- Bobcaygeon, Ont. April 1920. Cribs in place upper cofferdam.	removed (fr.album)
687	9 X 11.7	June 1920	Label -- Bobcaygeon, Ont. June 1920. Along backs of cribs upper cofferdam, joins old dam midstream.	removed (fr.album)
688	8.5 X 11.5	September 1920	Label -- Bobcaygeon, Ont. Sept. 1920. West from top of old dam shows upper cofferdam, cribs braced.	removed (fr.album)
689	9 X 11.7	August 1920	Label -- Bobcaygeon, Ont. Aug. 1920. Excavating for new dam.	removed (fr.album)
690	9 X 11.7	August 1920	Label -- Bobcaygeon, Ont. Aug. 1920. Excavate for dam, old structure on right.	removed (fr.album)
691	9 X 11.7	August 1920	Label -- Bobcaygeon, Ont. Aug. 1920. Excavate site for new dam.	in album
692	9 X 11.7	August 1920	Label -- Bobcaygeon, Ont. Aug. 1920. Excavate for new dam water not yet under control.	removed (fr.album)

693	9 X 11.7	September 1920	Label -- Bobcaygeon, Ont. Sept. 1920. Main pumps now control water box dams not needed.	removed (fr.album)
694	9 X 11.7	September 1920	Label -- Bobcaygeon, Ont. Sept. 1920. N. across bed of river along new dam.	in album
695	9 X 11.7	September 1920	Label -- Bobcaygeon, Ont. Sept. 1920. Excavate site of new dam follow up with concrete.	in album
696	9 X 11.7	September 1920	Label -- Bobcaygeon, Ont. Sept. 1920. Excavate foundation for new dam.	removed (fr.album)
697	9 X 11.7	September 1920	Label -- Bobcaygeon, Ont. Sept. 1920. Excavate dam foundation shows upper cofferdam & small box dam.	removed (fr.album)
698	9 X 11.7	September 1920	Label -- Bobcaygeon, Ont. Sept. 1920. Dam excavation dump on S. Bank.	removed (fr.album)
699	9 X 11.7	September 1920	Label -- Bobcaygeon, Ont. Sept. 1920. Dam Excavation drill with Jackhammers.	removed (fr.album)
700	9 X 11.7	September 1920	Label -- Bobcaygeon, Ont. Sept. 1920. Concrete gang follow excavating.	removed (fr.album)
701	9 X 11.7	September 1920	Label -- Bobcaygeon, Ont. Sept. 1920. Setting stoplog sill & erecting stoplog gains pier N. side dam.	removed (fr.album)
702	9 X 11.7	September 1920	Label -- Bobcaygeon, Ont. Sept. 1920. Placing stoplog gain with derrick. Pier forms in background.	removed (fr.album)
703	11.7 X 9	October 1920	Label -- Bobcaygeon, Ont. Oct. 1920. Midstream concrete aprons placed.	removed (fr.album)
704	8.5 X 11	October 1920	Label -- Bobcaygeon, Ont. Oct. 1920. Concrete work about midstream.	removed (fr.album)
705	11.7 X 9	October 1920	Label -- Bobcaygeon, Ont. Oct. 1920. Pumphouse boiler on old dam pier. North along site of new dam.	removed (fr.album)
706	8.5 X 11	October 1920	Label -- Bobcaygeon, Ont. Oct. 1920. Concrete past midstream - North pumps to left.	removed (fr.album)
707	9 X 11.7	October 1920	Label -- Bobcaygeon, Ont. Oct. 1920. Concrete past midstream , North. South along site of new dam.	removed (fr.album)
708	8.2 X 11.2	October 1920	Label -- Bobcaygeon, Ont. Oct. 1920. Look N. along site of new dam from S. end.	removed (fr.album)
709	8.4 X 10.8	August 1921	Label -- Bobcaygeon, Ont. Aug. 1921. South below dam box, dam to right for unwatering drydock.	removed (fr.album)
710	8.2 X 11.2	March 1921	Label -- Bobcaygeon, Ont. March 1921. Look South from middle of dam along upstream face of piers.	removed (fr.album)
711	11.5 X 9	1921	Label -- Bobcaygeon, Ont. Autumn 1921. Look North along completed dam. Piers of old dam to left to be removed.	removed (fr.album)
712	8.9 X 11.2	1920	Label -- Bobcaygeon, Ont. 1920. Operating Clam at Gravel Pit.	removed (fr.album)
713	9 X 11.7	1920	Label -- Bobcaygeon, Ont. 1920. Loading with Clam at Gravel Pit.	removed (fr.album)
714	11.7 X 9	1920	Label -- Bobcaygeon, Ont. 1920. Operating Clam at Gravel Pit.	removed (fr.album)
715	9 X 11.7	1920	Label -- Bobcaygeon, Ont. 1920. Looking West from upstream Entr. Dredge cleaned out reach below G.	removed (fr.album)
716	8.2 X 10.8	1920	Label -- Bobcaygeon, Ont. 1920. Looking West from Swing Bridge. New lock site opposite House L.	removed (fr.album)
717	8 X 11	October 1920	Label -- Bobcaygeon, Ont. Oct. 1920. Same view shows No. 7 taking cut thru canal ripping out old timber.	removed (fr.album)
718	8 X 11	1920	Label -- Bobcaygeon, Ont. 1920. View from behind No. 7 look east.	removed (fr.album)
719	8 X 11	January 1920	Label -- Bobcaygeon, Ont. Jany. 1920. Looking East down cut left by 7 preparing cofferdam above bridge.	removed (fr.album)
720	8.5 X 11	January 1920	Label -- Bobcaygeon, Ont. Jany. 1920. Looking West from Bank Bldg. Derrick 4 ready to excavate.	removed (fr.album)
721	8.5 X 11	1920/1921	Label -- Bobcaygeon, Ont. 1920/1. From behind derrick pumps to left.	removed (fr.album)
722	8.5 X 11	February 1921	Label -- Bobcaygeon, Ont. Feby. 1921. East down cut when excavation for lock is in progress.	removed (fr.album)
723	8.5 X 11	February 1921	Label -- Bobcaygeon, Ont. Feby. 1921. Excavate for lock, derricks start at lower end working West.	removed (fr.album)
724	8.5 X 11	February 1921	Label -- Bobcaygeon, Ont. Feby. 1921. Excavate lower end of lock.	removed (fr.album)
725	8.5 X 11	February 1921	Label -- Bobcaygeon, Ont. Feby. 1921. Excavate for lower end of lock. View from top of bank bldg.	removed (fr.album)
726	8.5 X 11	March 1921	Label -- Bobcaygeon, Ont. March 1921. Pumps in operation. Beatty 14" pump to right, Beatty & Morris pumps to left.	removed (fr.album)
727	8.5 X 11	March 1921	Label -- Bobcaygeon, Ont. March 1921. Build forms for small piers on which to set lower mitre sill. Leaks from seams to right.	removed (fr.album)
728	8.5 X 11	March 1921	Label -- Bobcaygeon, Ont. March 1921. Lock Pit flooded, Cut off wall run into bank.	removed (fr.album)
729	8.5 X 11	March 1921	Label -- Bobcaygeon, Ont. March 1921. Cut off wall on North side, Pumps flooded out in old position.	removed (fr.album)
730	8.5 X 11	April 1921	Label -- Bobcaygeon, Ont. April 1921. Getting control of water again clean trench for lower mitre sill.	removed (fr.album)
731	8.5 X 11	April 1921	Label -- Bobcaygeon, Ont. April 1921. Gould pump set up to help unwater trench for lower mitre sill.	removed (fr.album)
732	8.5 X 11	April 1921	Label -- Bobcaygeon, Ont. April 1921. After flooding it was necessary to clean out silt from trench for lower mitre sill.	removed (fr.album)
733	8.5 X 11	April 1921	Label -- Bobcaygeon, Ont. April 1921. Clean out pit after flooding forms Lower entrance to lock. Concrete cut off wall into bank.	removed (fr.album)
734	8.5 X 11	April 1921	Label -- Bobcaygeon, Ont. April 1921. Placing timbers of lower Mitre sill.	removed (fr.album)
735	8.5 X 11	April 1921	Label -- Bobcaygeon, Ont. April 1921. Setting lower mitre sill and anchorage. Mr. Spence at left.	removed (fr.album)

736	8.5 X 11	March 1921	Label -- Bobcaygeon, Ont. March 1921. Forms for lower entrance walls cut off walls to bank each side.	removed (fr.album)
737	8.5 X 11	March 1921	Label -- Bobcaygeon, Ont. March 1921. Excavate in lock pit shows faulty character of rock.	removed (fr.album)
738	8.5 X 11	April 1921	Label -- Bobcaygeon, Ont. April 1921. Forms for tunnels and valves in lower left recess of lock.	removed (fr.album)
739	8.5 X 11	May 1921	Label -- Bobcaygeon, Ont. May 1921. Looking east in lock pit, forms following excavation.	removed (fr.album)
740	8.7 X 11.3	May 1921	Label -- Bobcaygeon, Ont. May 1921. Forms for lock chamber, walls being built first, floor to be placed later.	removed (fr.album)
741	11.4 X 8.2	May 1921	Label -- Bobcaygeon, Ont. May 1921. Forms for mud pockets also shows pumps, Smith mixer set on North Bank.	removed (fr.album)
742	8.5 X 11.5	June 1921	Label -- Bobcaygeon, Ont. June 1921. Smith Mixer on N. Bank spouting concrete for mud pocket, upper lock gate.	removed (fr.album)
743	8.5 x 11.5	June 1921	Label -- Bobcaygeon, Ont. June 1921. Excavate in lock pit around upper gate.	removed (fr.album)
744	8.5 X 11.5	July 1921	Label -- Bobcaygeon, Ont. July 1921. Form work at South upper gate.	removed (fr.album)
745	8 X 11.5	June 1921	Label -- Bobcaygeon, Ont. June 1921. Looking East shows Dredge and Derrick tearing out old lock.	removed (fr.album)
746	8.5 X 11.5	June 1921	Label -- Bobcaygeon, Ont. June 1921. Forms for wall of guard gate.	removed (fr.album)
747	9.3 X 8.5	June 1921	Label -- Bobcaygeon, Ont. June 1921. Excavate for core wall Ft. Sherwood.	removed (fr.album)
748	8.5 X 11	July 1921	Label -- Bobcaygeon, Ont. July 1921. Looking N.E. showing .....?.....Island.	removed (fr.album)
749	8.5 X 7	April 1921	Label -- Bobcaygeon, Ont. April 1921. Looking West along south bank of Lock pit.	removed (fr.album)
750	11.5 X 8.5	June 1921	Label -- Bobcaygeon, Ont. June 1921. Drill for rock bolts to hold down concrete floor of lock.	removed (fr.album)
751	8.5 X 11	July 1921	Label -- Bobcaygeon, Ont. July 1921. Concrete North Entrance Wall.	removed (fr.album)
752	11.5 X 8.5	July 1921	Label -- Bobcaygeon, Ont. July 1921. Hang lower gate with Dredge.	removed (fr.album)
753	11.5 X 8.5	July 1921	Label -- Bobcaygeon, Ont. July 1921. Dredge hanging upper gate.	removed (fr.album)
754	8.5 X 11.5	July 1921	Label -- Bobcaygeon, Ont. July 1921. ....?...7 first vessel in lock...?...bridge open wide.	removed (fr.album)
755	11 X 8.5	July 1921	Label -- Bobcaygeon, Ont. July 1921. Concrete work about upper gate.	removed (fr.album)
756	9 X 12	July 1921	Label -- Bobcaygeon, Ont. July 1921. ....?...upper reach after com-...?...of entrance walls.	removed (fr.album)
757	11.5 X 8.5	July 1921	Label -- Bobcaygeon, Ont. July 1921. Looking East at Bulkhead across lower end. No. 7 working outside.	removed (fr.album)
758	11.5 X 8.5	July 1921	Label -- Bobcaygeon, Ont. July 1921. Looking West toward upper gate.	removed (fr.album)
759	8.5 X 10.5	July 1921	Label -- Bobcaygeon, Ont. July 1921. Looking East down lock chamber.	removed (fr.album)
760	11.5 X 8.5	June 1921	Label -- Bobcaygeon, Ont. June 1921. Looking down into lock chamber toward upper gate, pour floor.	removed (fr.album)
761	11.5 X 8.5	June 1921	Label -- Bobcaygeon, Ont. June 1921. Looking West up lock chamber on left recess for lower gates.	removed (fr.album)
762	11.5 X 8.5	June 1921	Label -- Bobcaygeon, Ont. June 1921. Looking east at bulkhead enclosing lower entrance to lock.	removed (fr.album)
763	8.5 X 11.5	June 1921	Label -- Bobcaygeon, Ont. June 1921. Excavate south upper entrance wall looking West.	removed (fr.album)
764	11.5 X 8.5	June 1921	Label -- Bobcaygeon, Ont. June 1921. Lock chambers, pumps running in sump. Some rock bolts in floor.	removed (fr.album)
765	11.5 X 8.5	June 1921	Label -- Bobcaygeon, Ont. June 1921. Tough digging in old lock # 7.	removed (fr.album)
766	11.5 X 8.5	July 1921	Label -- Bobcaygeon, Ont. July 1921. Temporary bridge from S. Side. Traffic crossed this bridge.	removed (fr.album)
767	12 X 9	1921	Label -- Bobcaygeon, Ont. 1921. New lock filled for first time.	removed (fr.album)
768	11.5 X 8.5	1921	Label -- Bobcaygeon, Ont. Fall 1921. Temporary bridge looking North.	removed (fr.album)
769	8.5 X 11	August 1921	Label -- Bobcaygeon, Ont. Aug. 1921. Looking East from lower lock gate. Derrick working at pivot pier.	removed (fr.album)
770	9 X 12	August 1921	Label -- Bobcaygeon, Ont. Aug. 1921. Dredge working East in Lower entrance.	removed (fr.album)
771	12 X 9	August 1921	Label -- Bobcaygeon, Ont. Aug. 1921. Forms for pivot pier being built.	removed (fr.album)
772	8.5 X 11	August 1921	Label -- Bobcaygeon, Ont. Aug. 1921. Pivot pier forms in place pouring.	removed (fr.album)
773	11.5 X 8.5	August 1921	Label -- Bobcaygeon, Ont. Aug. 1921. Placing concrete in pivot pier with bottom dump buckets.	removed (fr.album)
774	8 X 11.5	August 1921	Label -- Bobcaygeon, Ont. Aug. 1921. Look West up lower entrance No. 7 taking cut off island shore.	removed (fr.album)
775	9 X 11.5	October 1921	Label -- Bobcaygeon, Ont. Oct. 1921. Hoist 5 on top of completed pivot pier, excavate south abutment.	removed (fr.album)
776	9 X 11.5	November 1921	Label -- Bobcaygeon, Ont. Nov. 1921. Sinking panel forms for walls constructed in wet.	removed (fr.album)
777	11.5 X 9	November 1921	Label -- Bobcaygeon, Ont. Nov. 1921. Place forms for South abutment highway bridge.	removed (fr.album)